

1. Approving National Aviation  
Authority/Country:

2.

3. Form Tracking Number:

FAA/UNITED STATES

# AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

013098

4. Organization Name and Address:

SOUTHERN AEROPARTS, INC.  
10837 E. MARSHALL STREET, STE 101  
TULSA, OK 74116

Repair Station : QAKR523K

5. Work Order/Contract/Invoice  
Number:

013098 / 69539

6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	CONTROL BOX	790274	N/A	1.00 EA	04111444	REPAIRED

13. Remarks \*\* In accordance with manual No. 25-50-01 Revision: 8 Revision Date: JUL/08/2005

No outstanding Service Bulletins or AD's noted on this unit.

SOUTHERN AEROPARTS, INC. certifies that the work specified in Block 12 and 13 was performed in accordance with EASA Implementation Rule part 145 approval, and with respect to that work, the aircraft component is considered ready for release to service under EASA approval number 145-539

14. Certifies the items identified above were manufactured in conformity to:

19. ☒ 14 CFR 43.9 Return to Service

☒ Other regulations specified in Block 13

☐ Approved design data and are in a condition for safe operation.  
☐ Non-approved design data specified in Block 13.

20. Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

15. Authorized Signature:	16. Approval/Authorization No.:	20. Authorized Signature:	21. Approval/Certificate No.:
17. Name (Type or printed):	18. Date (dd/MM/yyyy):	22. Name (Typed or printed):	23. Date (MM/dd/yyyy):
		DEREK K. HAYNES	MAR/21/2007

## User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

**SOUTHERN AEROPARTS, INC.**

10837 E. MARSHALL STREET, STE 101

TULSA, OK 74116

TEL: 918-437-7676 FAX: 918-437-1418

WWW.SOUTHERNAEROPARTS.COM

FAA REPAIR STATION QAKR523K / DISTRIBUTOR

**TEAR DOWN REPORT**

Page : 1 Of 1

A/C #		<b>W/O No.</b> 013098 
WARRANTY		
LAST SHIP		
WORKSCOPE	REPAIR	
QUOTE APPROVAL		
QR #	75510-A1116	
DEPARTMENT	ELE	<b>P/N</b> 790274 
MUST SHIP BY		<b>S/N</b> 04111444 
For Customer	AJ WALTER AVIATION LTD	
S.O. No.	008099	

Cust P.O.	: 69539	P/N	: 790274	TAG INFO	: AJ WALTER AVIATION		
WO NUMBER	: 013098	Desc	: CONTROL BOX	TAG DATE	: MARCH 05, 2007		
WORKSCOPE	: REPAIR	S/N	: 04111444	SPEC	:		
DEPARTMENT	: ELE	MFG	:	Manual	: 25-50-01		
LINE #	:	Qty	: 1.00	Cond As: RP	Revision	: 8 / Jul-08-2005	
Completed As	: 790274	S/N As	: 04111444	Into Bin Loc	: SHIPPING		
Company	: 1	Division	: ELE	Department	: 01		
Order Date	: Mar-14-2007	Received Date	: Mar-05-2007	Due Date	: Mar-26-2007	Print Date	: Mar-14-2007

**Overhaul WORK ORDER No. 013098**

Manuals	Description	Manual Date	Revision No.	Revision Date	Current	Until
25-50-01	SLIDING CARPET ASSY	Jul-08-2005	8	Jul-08-2005	<input type="checkbox"/>	Mar-31-2007

**REPORTED BY CUSTOMER**

PLEASE QUOTE TO REPAIR AND RELEASE WITH DUAL REQUIREMENTS

**PRELIMINARY BENCH**

RUN SWITCH DOES NOT OPERATE PROPERLY, CASE SCREWS MISSING.

**TEARDOWN FINDINGS**

WHITE STICKY TAPE FOUND ON TOP, SIDES, AND BOTTOM SURFACES OF UNIT. RUN SWITCH INOP., AND 2 SCREWS MISSING. UNIT TO BE RETURNED AS "REPAIRED."

**CORRECTIVE ACTION**

REPLACED RUN SWITCH AND 2 SCREWS. CLEANED AND TESTED UNIT. THIS UNIT HAS BEEN REPAIRED IN ACCORDANCE WITH CMM 25-50-01 REV, 8 DATED 07/08/2005.

Authorized Signature:

Name:

Derek K. Haynes

Date:

MAR 21 2007