Approving Civil Aviation Authority/Country Transport Canada	AUTHORIZED RELEASE	ECERTIFICATE	3. Form Tracking Number. WO136524
4. Organization Name and Address.			
AJW Technique Inc 7055, rue Alexander Fleming			5. Work Order, Contract or Invoice Number:
7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada		technique	T40408-1
6. Item. 7. Description:	8. Part Number	1	
1 MOTOR OPERATED ACTUATOR ASSEMB		a. Quantity: 10. Sellambatch Number:	REPAIRED
12. REMARKS			
Unit repaired in accordance with CMM ATA 28-20-21, REV 03, dated Feb. 14/2012	-20-21, REV 03, dated Feb. 14/2012		
For further information please refer to Tear Down/Inspection Report.	wn/Inspection Report.		
13a. Certifies the items identified shows use		Maintenance pe	EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17
Approved design data and are in a condition for safe coordinate.	ctured in conformity to:	t, except where ribed in Black 1:	ified in Block 12, the work identified in Block d in accordance with Canadian Aviation
- Non-account of the second of	n saie operation.	Regulations.	
L		X CAR 571.10 Maintenance Release	
		Other regulation specified in Block 12	
13c. Ac	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
			14e. Date (dd/mmm/www)
	Installer Responsibilities		13-Feb-2023
This certificate does not constitute authority to install the pact		Haikal Dib	13-Feb-2023
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the Statements in blocks 13a or 14a do not constitute installation certification. In all constitute in the statements in blocks 13a or 14a do not constitute installation certification.	ations of a country other than specified in Bi	Haikal Dib	13-Feb-2023
applicable national regulations before the aircraft may be flown.		Ponsibilities Haikal Dib lock 1, must ensure that their regulations recognize or	13-Feb-2023
	llation certification. In all cases,the technical se flown.	This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the aircraft must contain an installation certification issued in accordance with the	13-Feb-2023 ertifications from the
	llation certification. In all cases,the technical se flown.	Haikal Dib Ponsibilities lock 1, must ensure that their regulations recognize or lock 1 record for the aircraft must contain an installation ce	13-Feb-2023 ertifications from the

AMMECHNIQUE

100-7055 Alexander-Fleming, Saint-Eaurent, QC, H4S 2B7, Canada www.aiw-group.com

Tear Down/Inspection Report

Work Order: WO136524 Date Printed: 2023-02-13 Customer RO: T40408-1

Page: 2

REASON LEGEND

(AD) AD: Part replaced due to Air worthiness Directive that needs to be incorporated. This code will include the last digits of the "AD".

(BR)* BROKEN: Part found Broken, cracked, crushed, ruptured, split, frayed, deformed. "NOT Customer Induced".

(BU)* BURNT/MELTED: Part found burnt, overheated, scorched, seared, blistered, short circuited etc...

(CID) CUSTOMER INDUCED DAMAGED: Part which is found damaged due to lack of maintenance, incident, mishandling, FOD etc....

(CO)* CORRODED: Part found corroded, pitted, rusted, decayed, oxidized, powdery and is beyond repair.

(CMM) 100% CMM: Part which is a mandatory replacement as per CMM.

(CR) CUSTOMER REQUEST

(CT)* CONTAMINATED: Part found contaminated by foreign object, debris, water, oil etc..." NOT Customer Induced".

(DE)* DEFECTIVE: Part defective, intermittent or loose

(DL)* DELAMINATED: Part found delaminated

(LE)* LEAKING: Part Leaking, seeping, porous beyond acceptable level as per CMM

(MI) MISSING: Part missing to complete a unit as per CMM. "Customer responsibility"

(MOD) MODIFICATION: Part requires modification as per CMM or other technical documentation. Part may be modified or replaced with a modified part

(NR)* NOT REUSABLE: Part that cannot be reused EX: O-ring, rings, gaskets, packing's, retainers, stripped screws, lock nuts, seals, lock washer.

(OOS) OUT OF SCOPE: Unit discrepancy not directly caused by customer and is above and beyond normal wear and tear or excluded from applicable commercial contracts.

(OOT)* OUT OF TOLERANCE: Part did not meet the tolerance or calibration as per CMM.

(RP)* RUPTURED: Part Punctured, ripped, torn, cut, deteriorated. (For Diaphragm, bellows...)

(RW)* REWORKED: Part reworked, refurbished, balanced, machined as per CMM.

(SB) SB: Part replaced due to Service Bulletin that needs to be incorporated. This code will include the last digits of the "SB"

(SE)* SEIZED: Part seized.

(SIL) SIL: Part replaced due to Service Information Letter that needs to be incorporated. This code will include the last digits of the SIL.

(TX) TIME CONTROLED: Part reached the end of its life, it is time expired and may either be overhauled if applicable or replaced due to times or cycles.

(WO)* WORN: Part scratched, grinded, rubbed, grooved, scrapped, gouged, chipped, abrasion etc....

(WT) WARRANTY: Part replaced under warranty

(CS) CUSTOMER SUPPLIED PARTS

(NDT) NON DESTRUCTIVE TEST

(IP) INCORRECT PART:

(SS) SUPERSEDED;

(AR) AS REQUIRED;

* NORMAL WEAR AND TEAR

AJW/TECHNIQUE

100-7055 Ale cander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO136524
 Date Printed: 2023-02-13
 Customer RO: T40408-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WES F SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: MOTOR OPERATED ACTUATOR ASSEMBLY

Phone: Email: P/N: MA30A1001 S/N: AA100695 Qty: 1

Mfg: ITT AEROSPACE

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: MA3)A1001

Serial Out: AA100695

Symptoms:

CODE:

REASON FOR REMOVAL

DETAILS:

test and recert - as removed - removed in serviceable condition.

Faults:

CODE:

NORMAL ON TEST

DETAILS:

Elect ical and functional tests performed. Tests OK

See attached Test Report

CODE:

REP/IR

DETAILS:

- Unit to be cleaned from dirt

- Grounding Screw Washers worn to be replaced

Unit to be repaired per CMM ATA 28-20-21 Rev 003

Corrective Actions:

CODE:

REPAIRED

DETAILS:

- Unit cleaned

- Grounding Screw Washers replaced

Unit repaired per CMM ATA 28-20-21 Rev 003

PN Description Reason Qty Needed Disposition

NAS1149D0316H WASHER, 203X.438X.016H,AL WO 2 Consumable

Form created with Quantum Control(tm) technology. Product Licensed to: AJW Technique Inc.