



1. Approving Civil Aviation Authority/Country FAA/United States		AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 115071	
4. ORGANIZATION: Name and Address <div style="text-align: center;">  Med-Craft, Inc. </div>		2450 N.W. 110th Avenue Miami, Florida 33172 Tel.: (305) 594-7444 Fax: (305) 594-9080 F.A.A. Repair Station N° LZ4R354M			5. Work Order / Contract / Invoice Number: TM-R230856	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1.	Drain Valve	141885-1	1	R230856	OVERHAULED	
12. Remarks: Work Order 115071 prescribing the actual work performed is attached. Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.4663. The work stated in Block 11 was accomplished IAW CMM 38-30-04 Rev Date: 08/15/85 Rev No.: 1						
13a. Certifies the items mentioned above were manufactured in conformity to: *** <input checked="" type="checkbox"/> Approved design and manufacture in accordance with the type certificate *** *** <input checked="" type="checkbox"/> Work approved design and manufacture in accordance with the type certificate *** *****			14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulations specified in Block 12 Certified that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature: *****			14b. Authorized Signature:  OSCAR UZ		14c. Approval/Certificate Number: LZ4R354M	
13d. Name (Typed or Printed): *****			14d. Name (Typed or Printed): OSCAR UZ		14e. Date (dd/mm/yy): 09 JUN 2014	
User/Installer Responsibilities						
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.</p> <p>Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.</p> <p>Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>						

WORK ORDER

Work Order : 115071
Part Number : 141885-1
Serial Number : R230856
ATA Number : 38-30-04
Service Req. : Repair

Repair Order : TM-R230856
Description : Drain Valve
Manufacturer : Weber
Revision Date : 08/15/85
Date : 03/26/14

FAA REPAIR STATION LZ4R354M

CONDITION REPORTED - CONFIRMED

Leaking & please re-serialise with R230856
as the S/N.

CONDITION AS RECEIVED

Missing ID plate.
W/O is opened with P/N and S/N stated on R/O.

HIDDEN DAMAGE INSPECTION

NONE FOUND

REMARKS

QUOTE and HOLD.

Receiving Clerk: Giovanni Acosta

DATE: 03/26/2014

AD NOTES, Customer Specs

THERE ARE NO A.D. NOTES FOR THIS UNIT

Signature: _____



DATE: _____

03/26/2014

WORK ORDER

Work Order : 115071
Part Number : 141885-1
Serial Number : R230856
ATA Number : 38-30-04
Service Req. : Repair

Repair Order : TM-R230856
Description : Drain Valve
Manufacturer : Weber
Revision Date : 08/15/85
Date : 03/26/14

FAA REPAIR STATION LZ4R354M

TEARDOWN REPORT

*Pretest

Upon pretest found:

1. Unit was received in conditions for overhaul.
2. Deteriorated parts.

*Disassembly

Upon disassembly and inspection, the following discrepancies were found:

1. Worn seal.
2. Damaged boot.
3. Unit requires reconditioning.
4. Due to damaged and worn parts, unit will be overhauled.

TECHNICIAN: Manuel Ignacio Collada SUPERVISOR: _____



WORK ORDER

Work Order : 115071
Part Number : 141885-1
Serial Number : R230856
ATA Number : 38-30-04
Service Req. : Repair

Repair Order : TM-R230856
Description : Drain Valve
Manufacturer : Weber
Revision Date : 08/15/85
Date : 03/26/14

FAA REPAIR STATION LZ4R354M

CORRECTIVE ACTION

1. Replaced all worn and damaged parts.
2. Reassembled and tested in accordance with the manufacturer's specifications.
3. Unit passed all functional tests.

Unit overhauled and certified for return to service.

Tech : Manuel Ignacio Collada Spvsr :



Date : 06/09/14

SERVICE PERFORMED

Overhauled

MAINTENANCE RELEASE

Issued with respect to job performed as checked above.
The component identified above was inspected in accordance with current regulations of the F.A.A. and is approved for return to service. Pertinent details of the repair are on file at this agency under

W.O.# 115071 Date JUN 09 2014 Signed _____

