

EASA Form 1 MF/CAO/145 / Formulaire 1 de l'EASA MF/CAO/145 – Issue 3 / Édition 3

AIRFRANCE

45 rue de PARIS F-95747 ROISSY CHARLES DE GAULLE CEDEX

FAX : 33 (0) 141 560 165

TLX : RSYLOAF

MFC24

WORK SHOP REPORT

No: B962099

Customer...: AJ WALTER AVIATION LTD
Work Order.: R374570Dossier.....: 2075450
Requisition No.: 00669937Designation : BRAKE TEMPERATURE MONITORING UNIT
Part Number...: 4305790410
Serial Number.: 0178

TSN.: UNKNOWN

CSN.: UNKNOWN

Removal from A/C.: AJ100
Aircraft Model...: UNKNOWN

Pos.: UNKNOWN

Time...: UNKNOWN
Cycles.: UNKNOWN

Removal Date.....: 16MAR20

Location.: VLR

Removal Type.....: UNSCHEDULED

Removal Reason...: MEL32-07-01B - PLEASE MOD TO - 4305790411
A/C 4K-AZ86 TYPE A340
RELEASE REQUESTED EASA/FAA/TCCA

Condition as received.....: ID PLATE AND SAFETY PLATE MISSING. UNIT DIRTY.

Work requested.....: REPAIR

Warranty requested.:

Warranty Accepted.:

Shop Finding.....: NO FAULT FOUND.

Confirmation of Removal.: NO FAULT FOUND

Repair Text.....: ID PLATE, SAFETY PLATE AND FILM PROTECTIVE ADDED.
UNIT CLEANED AND TESTED.

Documentation Reference.: MESSIER BUGATTI

CMM 32-47-12 REV05 SEP10

Modif/Remarks.....:

New Part Number....:

New Serial Number.:

Parts replaced : SEE PART LIST

Issue Date.....: 16NOV20

Name :

Repair Shop

Revision date.: 16NOV20

Signed :

VLR EL54

Page 1/2

K. KADDOUR

WORK SHOP REPORT**No: B962099****-- Parts replaced --**

Part Number / Alt	Description	QTY	UI
D92505-3	PLATE	1	EA
4305714050	PLATE,SAFETY	1	EA
4305714160	FILM,PROTECTIVE	1	EA

Issue Date.....: 16NOV20**Repair Shop****Revision date.: 16NOV20****VLR EL54****Page 2/2**