

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE			3. Form Tracking Number. WO150541	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada						5. Work Order, Contract or Invoice Number: T42500
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:	
1	HF Antenna Coupler	792-6140-001	1.00	1136	REPAIRED	
12. REMARKS Unit repaired and tested serviceable in accordance with CMM 23-11-04 1st Revision dated Nov 13 2015. See tear down report for additional information.						
PRINTED FROM ELECTRONIC FILE						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17				
13b. Signature:		13c. Approved Organization Number	14a. Certifies that, except where otherwise specified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12			
13d. Name (Typed or Printed):		13e. Date	14b. Signature 	14c. Approval Organization Number 33-12		
			14d. Name (Typed or Printed) Hon Tak Chan	14e. Date (dd/mm/yyyy) 16/Nov/2023		
Installer Responsibilities						
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.						

Work Order: WO150541

Date Printed: 11/16/2023

Customer RO: T42500

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: HF Antenna Coupler

Phone:

P/N: 792-6140-001

Qty: 1

Email:

S/N: 1136

Mfg: ROCKWELL COLLINS

TSN: 0

TSO: N/A

TSR: 0

CSN: 0

CSO: N/A

CSR: 0

P/N Out: 792-6140-001

S/N Out: 1136

Symptoms:

CODE: REPAIR

DETAILS: PLEASE QUOTE TO TEST AND RECERTIFY. PLEASE TO REPAIR IF IT FAILS TEST.
REMOVED IN SERVICEABLE CONDITION FROM A/C REG: G-MDBD.

Faults:

CODE: INITIAL TEST FAILURE

DETAILS: Unit failed to tune above 12MHz frequency.

CODE: PCBR

DETAILS: Troubleshooting confirmed tuning module off calibrate need re-calibration.

CODE: REPAIR

DETAILS: The following repair(s) will be performed:
RF tuning assembly module to be calibrated.
unit to be tested and re-certified.

Corrective Actions:

CODE: REPAIRED

DETAILS: Calibrated RF tuning assembly module.
Unit repaired and tested serviceable in accordance with CMM 23-11-04 1st Revision dated Nov 13 2015.

AJW[®]TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

WO Packing Slip

WO #: WO150541

Date: 11/16/2023 Time: 8:31:21 AM

Cust Ref #:T42500

SM #: SH170563



SH170563

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Ship To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX RH13 0AS
UNITED KINGDOM

Order Date: 11/1/2023

Ship Via:

Ship Via Acc:

Prepared By: SYSDBA

Customer #: AJW01

Buyer:

Part Number/Description	Qty	
792-6140-001 HF Antenna Coupler Loc/Whse: Serial #: 1136	1	



DOCKED