



| | | | | | | | | | | | | | |
|--|--|---|--|--|--|--|--|--------------------------|--|------------------|--|--|--|
| 1. Approving Civil Aviation Authority/Country Transport Canada | | 2. AUTHORIZED RELEASE CERTIFICATE FORM ONE | | | | 3. Form Tracking Number. WO139401 | | | | | | | |
| 4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada | | | | | | 5. Work Order, Contract or Invoice Number: R408361 R19265022_1 | | | | | | | |
| 6. Item: | | 7. Description: | | 8. Part Number: | | 9. Quantity: | | 10. Serial/Batch Number: | | 11. Status/Work: | | | |
| 1 | | Cabin Handset | | 89-01-07062 | | 1.00 | | 524523 | | INSPECTED/TESTED | | | |
| 12. REMARKS TESTED SERVICEABLE IN ACCORDANCE WITH CMM 23-73-01 REV.20 DATED SEP 20/2018 FOR MORE INFORMATION REFER TO THE TEARDOWN/INSPECTION REPORT. | | | | | | | | | | | | | |
| 13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12 <div><div><div>PRINTED FROM ELECTRONIC FILE</div><div>EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17</div></div><div><div><input checked="" type="checkbox"/> CAR 571.10 Maintenance Release <input checked="" type="checkbox"/> Other regulation specified in Block 12</div></div></div> | | | | | | | | | | | | 14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. | |
| 13b. Signature: | | 13c. Approved Organization Number | | 14b. Signature   | | 14c. Approval Organization Number 33-12 | | | | | | | |
| 13d. Name (Typed or Printed): | | 13e. Date | | 14d. Name (Typed or Printed) Mehran Mohammady | | 14e. Date (dd/mm/yyyy) 06/Apr/2023 | | | | | | | |
| Installer Responsibilities This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown. | | | | | | | | | | | | | |

Work Order: WO139401

Date Printed: 4/6/2023

Customer RO: R408361

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: Cabin Handset

Phone:

P/N: 89-01-07062

Qty: 1

Email:

S/N: 524523

Mfg: HOLMBERG GMBH

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 89-01-07062

Serial Out: 524523

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: Handset intermittent.

Faults:

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal is not confirmed.

CODE: CLEANING

DETAILS: Cleaning is required due to routing shop procedure.

CODE: TEST AND RECERTIFY

DETAILS: Unit will be retested and re-certified in accordance with CMM 23-73-01

Corrective Actions:

CODE: INSPECTED/ TESTED

DETAILS: TESTED SERVICEABLE IN ACCORDANCE WITH CMM 23-73-01 REV.20 DATED SEP 20/2018