

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO150543	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: T42502	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	HF Antenna Coupler	792-6140-001	1.00	1705	REPAIRED
12. REMARKS Unit repaired and tested serviceable in accordance with CMM 23-11-04 1st Revision dated Nov 13 2015. See tear down report for additional information.					
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Signature:		13c. Approved Organization Number		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12	
13d. Name (Typed or Printed):		13e. Date		14b. Signature <i>Charles Lee</i>	
14c. Approval Organization Number 33-12		14d. Name (Typed or Printed) Hon Tak Chan		14e. Date (dd/mm/yyyy) 15/Nov/2023	
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO150543

Date Printed: 11/15/2023

Customer RO: T42502

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: HF Antenna Coupler

Phone:

P/N: 792-6140-001

Qty: 1

Email:

S/N: 1705

Mfg: ROCKWELL COLLINS

TSN: 0

TSO: N/A

TSR: 0

CSN: 0

CSO: N/A

CSR: 0

P/N Out: 792-6140-001

S/N Out: 1705

Symptoms:

CODE: REPAIR

DETAILS: PLEASE QUOTE TO TEST AND RECERTIFY. PLEASE TO REPAIR IF IT FAILS TEST.
REMOVED IN SERVICEABLE CONDITION FROM A/C REG: G-OMYT.

Faults:

CODE: INITIAL TEST FAILURE

DETAILS: Unit passed arrival test with NFF.

CODE: PAINTING

DETAILS: Painting is required due to unit housing paint worn. (2 pictures attached)

CODE: REPAIR

DETAILS: The following repair(s) will be performed:
Unit housing to be painted.
Unit to be tested and re-certified.

Corrective Actions:

CODE: REPAIRED

DETAILS: Paint unit housing.
Unit cleaned, repaired and tested serviceable in accordance with CMM 23-11-04 1st Revision dated Nov 13 2015.

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

WO Packing Slip

WO #: WO150543

Date: 11/15/2023 Time: 12:46:17 PM

Cust Ref #: T42502

SM #: SH170520



SH170520

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Ship To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX RH13 0AS
UNITED KINGDOM

Order Date: 11/1/2023

Ship Via:

Ship Via Acc:

Prepared By: SYSDBA

Customer #: AJW01

Buyer:

Part Number/Description

Qty

792-6140-001 HF Antenna Coupler

Loc/Whse:

Serial #: 1705

1



DOCKED