

1. Approving Civil Aviation
Authority/ Country:

2.

AUTHORIZED RELEASE CERTIFICATE

3. Form Tracking Number:

182243

FAA/United States

FAA Form 8130-3, Airworthiness Approval Tag

4. Organization Name and Address:

AVIATION INSTRUMENTS REPAIR SPECIALISTS, INC. (DBA A.I.R.S.) VTBR433V

A.I.R.S./14316 Commerce Way Miami Lakes, FL 33016 U.S.A.

Phone: 305-887-5600, Fax: 305-820-0931

5. Work Order/Contract/ Invoice Number:

T42035

6. Item:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1 SMOKE DETECTOR

475571-1

1

TMA3032

REPAIRED

12. Remarks:

REPAIRED in accordance with CMM 26-10-88, Revision 11, Date Aug 05, 2020

Full details of work carried out per work order no. 182243

Modification Level: N/A

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part - 145 and in respect to that work SMOKE DETECTOR is considered ready for release to service under

EASA Part - 145 approval no. EASA.145.5033

FAA Ad's: NONE EASA Ad's: NONE

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12.

14a ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval/Authorization No.:

Not Applicable

Not Applicable

14b. Authorized Signature:



14c. Approval/Certificate No.:

VTBR433V

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy)

Not Applicable

Not Applicable

14d. Name (Typed or Printed):

Elio Kocijancic

14e. Date (dd/mm/yyyy):

27/Sep/2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

TearDown/Inspection Form

AVIATION INSTRUMENTS REPAIR SPECIALISTS, INC. (DBA A.I.R.S.)

Work Order: 182243

Date: September/27/2023

A.I.R.S./14316 Commerce Way

Miami Lakes, FL 33016

U.S.A.

Phone: 305-887-5600

Fax: 305-820-0931

C.R.S. No.: VTBRA433V

Sold to:

A J WALTER AVIATION The Headquarters, Maydwell Ave.

Ship to:
A J WALTER AVIATION LIMITED
THE HEADQUARTERS
MAYDWELL AVENUE, TBA TBA
United States

Serial: TMA3032 Manufacturer: KIDDE AEROSPACE

Part Number: 475571-1 Description: SMOKE DETECTOR
Purchase Order: T42035
Service Performed: REPAIRED
Manual Number: 642 Revision: 11 Date: 08/05/2020

TearDown/Inspection Data

1. Removal: NONE

Inst.: REPAIRED

2. Initial Inspection Findings

Appearance: Normal on Visual Inspection
Loose or Missing Parts: Missing Screws
Mod. Level: N/A

3. Teardown

Disassembly: Normal
Painting: Normal Painting

4. Test

Operation: Operation I/AW Mfg. Specs

Was Complaint Verified: Yes

Mods. Completed: None

5. Final

Warranty Accepted: N/A

Final Test and Inspection: Final Inspection Normal
A.T.A.: 26-10-88
A.D. S.B.: NO A.D. / S.B REQUIRED

6. Work Done

UNIT WAS INSPECTED, DISASSEMBLED, CLEANED, INSTALLED SCREWS, ASSEMBLED, REPAIRED I/AW MFG. SPECS. TESTED OPERATION AND FOUND READY TO RETURN TO SERVICE. NO APPLICABLE SB OR A/D'S ON FILE. ATA 26-10-88. WORK PERFORMED BY Brandon Ravelo.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect of the work performed is approved to service. Pertinent details of the work performed are on file at this Agency under Work Order: 182243

Technician: Brandon Ravelo

Inspector: Elio Kocijancic

Certificate No. 2569075



Signature:

Date: September/27/202

Form: CRS-3



Aviation Instruments Repair Specialists, Inc. (dba A.I.R.S.)
/ EASA.145.5033
14316 COMMERCE WAY
MIAMI LAKES, FL 33016
Phone: 305-887-5600
Fax: 305-820-0931
E-Mail: info@airs-inc.com

SHIPPER DATE: 09/27/2023

Shipping Ticket

SHIPPER #:
129749

Bill To:

A J WALTER AVIATION THE HEADQUARTERS,
MAYDWELL AVE.
WEST SUSSEX
SLINFOLD, RH13 0SH
UNITED KINGDOM

Shipped To:

A J WALTER AVIATION LIMITED
THE HEADQUARTERS
MAYDWELL AVENUE, TBA TBA
UNITED STATES

Order Date: 09/13/2023

Work Order #: 182243

Terms: 45 days

Customer RO #: T42035

Customer #: 1866

F.O.B: Miami Lakes

Ship Via: FedEx

Shipping Notes: 124277507

<u>P/N</u>	<u>Description</u>	<u>Qty</u>	<u>S/N</u>	<u>Condition</u>
475571-1	SMOKE DETECTOR	1	TMA3032	REPAIRED

From:

Aviation Instruments Repair Specialists,
Inc. (dba A.I.R.S.)
14316 COMMERCE WAY
MIAMI LAKES, FL 33016

Print Name: _____

Signature: _____

Date: _____

Packing CheckList:

	Yes	No	NA
Part Number	[]	[]	[]
Serial Number	[]	[]	[]
Form 8130-3	[]	[]	[]
Cert. Trace	[]	[]	[]
Forms Audit	[]	[]	[]
Bubble Wrap	[]	[]	[]

To:

PO\RO#:T42035

Rob Harris-Dibben

A J WALTER AVIATION LIMITED
THE HEADQUARTERS
MAYDWELL AVENUE, TBA TBA
UNITED STATES

Phone: 011441403711777