

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: W17366A	
4. Organization Name and Address:  / Aero-mark MRO, LLC FAA Repair Station 8MAR982B 14560 Greeno Road, Fairhope, AL 36532				5. Workorder/Contract/Invoice No: R409794	
6.	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	MANIFOLD	1555B9900-01	1	1555B99LI007948	REPAIRED
12. REMARKS: REPAIRED IN ACCORDANCE WITH LIEBHERR CMM 29-10-22, REVISION # 5 DATED 27/Nov/2019. FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER W17366. THE WORK WAS PERFORMED BY CODY ROOTE (CROOTE) EMPLOYEE # CAR18345. THIS FAA FORM 8130-3 CORRECTS THE ERROR IN BLOCK 10 OF THE FAA FORM 8130-3, WORK ORDER W17366, DATED 14/Mar/2022 AND DOES NOT COVER CONFORMITY/CONDITION/RELEASE TO SERVICE. THIS IS A REISSUED FAA FORM 8130-3 TO CORRECT SERIAL NUMBER FROM 1555B99LI007948 TO 1555B99LI007948. "CAS CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NUMBER EASA.145.6405."					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data are in a condition for safe operation ☒ Not approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12; the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service		14c. Approval/Certificate No: 8MAR982B	
13b. Authorized Signature: 		13c. Approval/Authorization No: 8MAR982B		14d. Date (dd/mm/yyyy): 16/Mar/2022	
13d. Name (Typed or Printed): TRAVIS BRANCH		14e. Date (dd/mm/yyyy): 16/Mar/2022			
User/Installer Responsibilities					
It is important to understand the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

Workorder Report**W17366**

Customer:	AVTRADE	Part Number:	1555B9900-01
Customer PO:	R409794	Serial Number:	1555B99LI007948
Manufacturer:	LIEBHERR	Nomenclature:	HP PTU MANIFOLD

Customer Instructions: INSPECT**Receiving Inspection** HEAVY CLEANING REQUIRED.**Preliminary Functional** PASSED FUNCTIONAL TESTING.**Preliminary Inspection** ORINGS REMOVED FOR REMOVAL OF UNIONS FOR TESTING. SHIPPING CAPS MISSING AT RECEIVING. ITEMS ORDERED DO NOT AFFECT FINAL FUNCTION.**Corrective Action** DISASSEMBLED, CLEANED, AND INSPECTED. REPLACED ALL NECESSARY PARTS, REASSEMBLED, FUNCTIONALLY TESTED, AND REPAIRED IN ACCORDANCE WITH THE MANUFACTURER'S SPECIFICATIONS.**Specifications Met:** 29-10-22**Unit was:** REPAIRED

Work Performed By:	CODY ROOTE	Cert No.:	CAR18345	Date:	14/Mar/2022
--------------------	------------	-----------	----------	-------	-------------

Work Inspected By:	TRAVIS BRANCH	Cert No.:	TDB22129	Date:	14/Mar/2022
--------------------	---------------	-----------	----------	-------	-------------

A list of Parts Used is attached, if applicable.

Parts used on this workorder:

<u>Part Number</u>	<u>Nomenclature</u>	<u>QTY</u>
NAS1612-8A	PACKING	1.00
NAS1612-6A	PACKING	1.00
NAS1612-12A	PACKING	2.00
NAS1612-10A	PACKING	2.00
MS21914-12W	CAP	2.00
MS21914-8W	CAP	1.00
MS21914-6W	CAP	1.00
MS21914-10W	CAP	1.00

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: W 17366	
4. Organization Name and Address: GKS / Aero-mark MRO, LLC FAA Repair Station 8MAR982B 14560 Greeno Road, Fairhope, AL 36532		5. Workorder/Contract/Invoice No: R409794			
6. Item: 1	7. Description: MANIFOLD	8. Part Number: 1555B9900-01	9. Quantity: 1	10. Serial Number: 1555B99L1007948	11. Status/Work: REPAIRED
12. REMARKS: REPAIRED IN ACCORDANCE WITH LIEBHERR CMM 29-10-22, REVISION # 5 DATED 27/Nov/2019. FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER W17366. THE WORK WAS PERFORMED BY CODY ROOTE (CROOTE) EMPLOYEE # CAR18345 "CASE CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NUMBER EASA.145.6405."					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data are in a condition for safe operation ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service			
13b. Authorized Signature:	13c. Approval/Authorization No:	14b. Authorized Signature: <i>Travis Branch</i>		14c. Approval/Certificate No: 8MAR982B	
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or printed): TRAVIS BRANCH		14e. Date (dd/mm/yyyy): 14/Mar/2022	
User/Installer Responsibilities					
It is important to understand the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

Workorder Report**W17366**

Customer:	AVTRADE	Part Number:	1555B9900-01
Customer PO:	R409794	Serial Number:	1555B99L1007948
Manufacturer:	LIEBHERR	Nomenclature:	HP PTU MANIFOLD

Customer Instructions: INSPECT**Receiving Inspection** HEAVY CLEANING REQUIRED.**Preliminary Functional** PASSED FUNCTIONAL TESTING.**Preliminary Inspection** ORINGS REMOVED FOR REMOVAL OF UNIONS FOR TESTING. SHIPPING CAPS MISSING AT RECEIVING. ITEMS ORDERED DO NOT AFFECT FINAL FUNCTION.**Corrective Action** DISASSEMBLED, CLEANED, AND INSPECTED. REPLACED ALL NECESSARY PARTS, REASSEMBLED, FUNCTIONALLY TESTED, AND REPAIRED IN ACCORDANCE WITH THE MANUFACTURER'S SPECIFICATIONS.**Specifications Met:** 29-10-22**Unit was:** REPAIRED

Work Performed By:	CODY ROOTE	Cert No.:	CAR18345	Date:	14/Mar/2022
--------------------	------------	-----------	----------	-------	-------------

Work Inspected By:	TRAVIS BRANCH	Cert No.:	TDB22129	Date:	14/Mar/2022
--------------------	---------------	-----------	----------	-------	-------------

A list of Parts Used is attached, if applicable.

Parts used on this workorder:

<u>Part Number</u>	<u>Nomenclature</u>	<u>QTY</u>
NAS1612-8A	PACKING	1.00
NAS1612-6A	PACKING	1.00
NAS1612-12A	PACKING	2.00
NAS1612-10A	PACKING	2.00
MS21914-12W	CAP	2.00
MS21914-8W	CAP	1.00
MS21914-6W	CAP	1.00
MS21914-10W	CAP	1.00