


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 318860	
4. Organization Name and Address:  AIRCO SERVICES AirCo Services, LLC 2995 Lone Oak Circle Suite# 10 Eagan, MN 55121 Ph: 316-945-9820, Fax: 651-393-3310 FAA Approval Holder: T12R188L		5. Work Order/Contract/Invoice Number: R1644		11. Status/Work: REPAIRED	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	
1	POWER MANAGEMENT CONTROL	69-73614-57	1.00	D01311	
12. Remarks: REFERENCE WORK ORDER REPORT FOR WORK PERFORMED. ALL WORK PERFORMED I/AW, Manual ID: 33-10-15, Revision #: 8, Revision Date: 9/1/2014 MODS INSTALLED: NONE					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number. EASA.145.4100.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval Authorization No.:		14b. Authorized Signature: 	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14c. Approval/Certificate No.: T12R188L	
				14d. Name (Typed or Printed): Adam Holstine	
				14e. Date (dd/mm/yyyy): 14-Dec-2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

**AirCo Services, LLC**

2995 Lone Oak Circle

Suite# 10

Eagan, MN 55121

FAA REPAIR STATION #TI2R188L

Tear Down/Inspection

Work Order #: R1644

PN: 69-73614-57

Desc: POWER MANAGEMENT CONTROL

SN: D01311

To:

ATTN: REBECCA WILDERS
A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WE RH13 OSH
UNITED KINGDOM

Ship To:

A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD, RH13 0AS
UNITED KINGDOM

Date Printed	Cust No.	Terms	Customer Contact			Cust PO
12/14/2023	01489	N30	REBECCA WILDERS			R418741
F.O.B.	Ship Via		Manual:	Revision:	Rev Date:	Location:
	FEDEX INT'L PRIORITY	124277507	33-10-15	8	9/1/2014	1J207-1
ASSIGNED TECHNICIANS			ASSIGNED INSPECTOR			
Timothy Wood			Adam Holstine			

Action Requested

REPAIR

Squawk: IN-OP. Please advise cost to Repair IAW mfg specs.

Faults:

REPAIR

Unit dirty and lens cover is worn. L5 switch INOP. Lamp intermittent and switch does not consistently engage/disengage. Unit requires replacement of switch assembly, cleaning, and testing IAW mfg specs.

Action Taken:

REPAIR

Replaced L5 switch and cleaned unit. Functionally tested unit in accordance with CMM 33-10-15, Rev 8, 9/1/2014. Tagged, Repaired, and certified airworthy in accordance with mfg specs.

PN	Description	Qty Needed	CD	Disposition
433-673-1004-4016	SWITCH	1	NE	Consumable

By:

Date:

12/14/2023