


1. Approving Competent Authority / Country: United Kingdom Civil Aviation Authority		2		AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number: L 2592295	
4. Organization Name and Address: Panasonic		Panasonic Avionics Corporation Quadrant House, Heron Drive, Palfant Road, Langley Berks, SL3 8XP, UK				5. Work Order/Contract/Invoice R285978	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No	11. Status / Work		
1	MAIN MULTIPLEXER	RD-AX1302-11	1	100043	REPAIRED		
12. Remarks PLEASE REFER TO SR NUMBER 4277110.							
Certifies that unless otherwise specified in Block 12 the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZYY163X. Panasonic Avionics Corporation internal reference SR4277110							
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in a condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 12.		14a. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		14b. Authorized Signature: 			
13b. Authorised Signature:		13c. Approval/Authorization Number		14c. Certificate/Approval Ref No: UK. 145.00297			
13d. Name		13e. Date (dd mm yy)		14d. Name Mick White		14e. Date (dd mm yy) 08-MAR-2016	
USER/INSTALLER RESPONSIBILITIES							
This certificate does not automatically constitute authority to install the item(s).							
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.							
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

Panasonic Avionics Corporation

Quadrant House, Heron Drive, Parlaunt Road,
Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

REPAIR REPORT / DELIVERY ORDER

SOLD TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

SHIP TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

PAGE 1 of 1

SHIP TRANSACTION:



CUSTOMER P.O. NUMBER R285978		CUSTOMER 1001	TAIL NO. 4K-AZ12	CUST PROD REF 13224798	SERVICE REQUEST 4277110
PART NUMBER RD-AX1302-11	NOMENCLATURE MAIN MULTIPLEXER			DATE REMOVED	DATE RECEIVED 24-FEB-2016
SERIAL NUMBER 100043	DATE OF MFG 31-MAR-1999	WTY START DATE 31-MAR-1999	WTY END DATE 29-JUN-2002	DATE REPAIRED 04-MAR-2016	SHIP DATE

MOD IN
0

REASON FOR CUSTOMER REJECTION	IN PES MODE ALL PCUS CHANNEL #1 NOT OPERATE
--	---

INTERNAL INSPECTION	No Physical Damage
---------------------	--------------------

EXTERNAL INSPECTION	No Physical Damage - DIRTY.
---------------------	-----------------------------

INSPECTION	
ACTUAL FAILURE / CORRECTIVE ACTION	UNIT FAILED ON MULTIPLE STEPS. CSS LAYOUT & SETTING DATA CORRUPT. DATA RESET. UNIT CLEANED, RE-TESTED AND PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-34-58 REV 15 DTD JAN 2009.

MOD OUT: 0

INSPECTED BY: Mick White

REPAIRED BY: **Blackwell, Gary**

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR	OUT OF WARRANTY CHARGE	278				

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Cost of Labor	
Cost of Material	
Total Cost	

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged