


1. Approving Civil Aviation Authority/Country		2.		3. Form Tracking Number.	
Transport Canada				WO150978	
4. Organization Name and Address.				5. Work Order, Contract or Invoice Number:	
AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				T42582	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	SPOILER CONTROL MODULE ASSY	285T0012-201	1.00	D10277	REPAIRED
12. REMARKS					
REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 27-61-02 REV 17 DATED APR 08, 2020. FOR ADDITIONAL INFORMATION SEE TEAR DOWN/INSPECTION REPORT.					
PRINTED FROM ELECTRONIC FILE					
13a. Certifies the items identified above were manufactured in conformity to:			14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.		
☐ Approved design data and are in a condition for safe operation.			☒ CAR 571.10 Maintenance Release		
☐ Non-approved design data specified in Block 12			☒ Other regulation specified in Block 12		
13b. Signature:		13c. Approved Organization Number		14b. Signature	
					
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed)	
				Elloi Dion	
				14e. Date (dd/mm/yyyy) 01/Dec/2023	
				14c. Approval Organization Number 33-12	
Installer Responsibilities					
This certificate does not constitute authority to install the part.					
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO150978

Date Printed: 12/1/2023

Customer RO: T42582

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: SPOILER CONTROL MODULE ASSY

P/N: 285T0012-201

Qty: 1

Phone:

S/N: D10277

Mfg: BAE SYSTEMS CONTROLS

Email:

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 285T0012-201

Serial Out: D10277

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: REMOVED IN SERVICEABLE CONDITION FOR TEST CERTIFICATION AND REPAIR AS
REQUIRE FROM ACFT G-ZAPX

Faults:

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal is confirmed.

CODE: INITIAL TEST FAILURE

DETAILS: - Unit passed the test.
- Will inspect internally as per CMM.

CODE: DISASSEMBLY / INSPECTION FINDINGS

DETAILS: - Unit dirty.
- Found a cracked solder joint on motherboard (A1).

CODE: REPAIR

DETAILS: - Unit will be cleaned.
- Cracked solder joint will be repaired.
- Final test required.

Corrective Actions:

CODE: REPAIRED

DETAILS: - Cleaned unit.
- Cracked solder joint have been repaired.
- Repaired and tested serviceable in accordance with CMM 27-61-02 REV 17 DATED APR 08, 2020.