

60800136

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

Lufthansa Technik

1. Approving Competent Authority / Country LBA / Germany		2.		3. Form Tracking Number 619724																					
4. Approved Organisation Name and Address: Lufthansa Technik AG Weg beim Jäger 193 P.O. Box 63 03 00 D-22313 Hamburg Federal Republic of Germany																									
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	5. Work Order/Contract/Invoice 810135																				
01	OUTLET GUIDE VANE FAN (5A)		4		11. Status / Work OVERHAULED																				
12. Remarks FSCM F0301 ATA 7223 TPO MK-No. 13 Pack Code 00 Resp. Workshop 48255 Workshop Station HAMBS08 A.J. Walter Aviation Ltd. 163693 Visual Inspected. See Original Certificate Form Tracking Number: 482666 Fan Outlet Guide Vane repaired in accordance with EM CFMI-TP-SM.7 Chapter 72-23-03 Rep.005/006 Rev.56 dated from 20110215. EX ESN: 731203 <table><thead><tr><th></th><th>Opr. Hours</th><th>Cycle</th><th>Opr. Day</th></tr></thead><tbody><tr><td>TT</td><td>N/A</td><td>N/A</td><td>N/A</td></tr><tr><td>TSO</td><td>0</td><td>0</td><td>0</td></tr><tr><td>TSC</td><td>0</td><td>0</td><td>0</td></tr><tr><td>TSF</td><td>0</td><td>0</td><td>0</td></tr></tbody></table> TASK PERFORMED IN ACCORDANCE WITH EM 72-23-03 REV 56 Return to Service in Accordance with U.S. Federal Aviation Regulations This civil aeronautical product has been maintained altered, or modified (as appropriate) in accordance with U.S. Federal Aviation Regulations For Lufthansa Technik AG, Hamburg, Germany FAA Certificate No. DLAY225D Note: Acceptance No. TCCA 897-08							Opr. Hours	Cycle	Opr. Day	TT	N/A	N/A	N/A	TSO	0	0	0	TSC	0	0	0	TSF	0	0	0
	Opr. Hours	Cycle	Opr. Day																						
TT	N/A	N/A	N/A																						
TSO	0	0	0																						
TSC	0	0	0																						
TSF	0	0	0																						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☒ Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.																									
13b. Authorised Signature		13c. Approval / Authorisation Number		14a. Authorised Signature																					
13d. Name		13e. Date (dd mm yyyy)		14b. Name																					
				025513, Rainer Kock																					
EASA FORM 1 - Issue 2 USER/INSTALLER RESPONSIBILITIES				14c. Certificate / Approval Ref. Number DE.145.0001																					
				14e. Date (dd mm yyyy) 30 Nov 2011																					

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



60800136

1. 国家 Country P. R. China	2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness	3. 证书编号 Certificate Ref. No. LHT / CAAC / A / 619724
------------------------------	--	---

批准放行证书 / 适航批准标签
Authorized Release Certificate / Airworthiness Approval Tag

4. 单位 Organisation 	Lufthansa Technik AG Weg beim Jäger 193 P.O. Box 63 03 00 D-22313 Hamburg Federal Republic of Germany		5. 工作单/合同单/发票 Work Order/Contract/Invoice 810135			
6. 序号 Item 01	7. 内容 Description OUTLET GUIDE VANE FAN (5A)	8. 件号 Part No. 336-065-008-0	9. 适用性 Eligibility * CFM56-5A	10. 数量 Qty. 4	11. 系列号/批号 Serial / Batch No. N/A	12. 产品状态 Status / Work OVERHAULED

13. 备注 Remarks A.J. Walter Aviation Ltd. 163693 FSCM F0301 ATA 7223 TP O MK-No. 13 Pack Code 00 Visual Inspected. See Original Certificate Form Tracking Number: 482666 Fan Outlet Guide Vane repaired in accordance with EM CFMI-TP-SM.7 Chapter 72-23-03 Rep.005/006 Rev.56 dated from 20110215. EX ESN:731203	Workshop Station HAMBS08 Resp. Workshop 48255
--	--

For storage conditions see CMM or Operator's maintenance program.
Limited life parts will normally be accompanied by maintenance history including life used.

14. 新产品 New Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该产品 (出口产品) 符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured in accordance with the airworthiness regulations of the stated country and/or in case of parts to be exported with the approved design data and with the notified special requirements of the importing country. (over)	15. 使用过的产品 Used Parts: 兹声明上述产品除第 13 项的其它规定外, 已按照上述国家适航条例和进口国通知的特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as otherwise specified in block 13 was (were) carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work the parts(s) is (are) in condition for safe operation and considered ready for release to service. (over)
--	---

16. 批准人签名 Signature 	18. 批准日期 Date (d/m/y) 30/Nov/2011
17. 批准人姓名 (打印的) Name (Printed) 025513, Rainer Kock	

批准放行证书/适航批准标签
AUTHORIZED RELEASE CERTIFICATE / AIRWORTHINESS APPROVAL TAG
使用者/安装者职责
USER / INSTALLER RESPONSIBILITIES

- (1) 必须明确: 本文件并不批准零件/组件/附件可以装到相关产品上。
- (2) 当使用者/安装者使用的是在适航当局条例中, 而不是本表第 1 项中所指国家适航当局的条例时, 使用者/安装者必须保证所在国的适航当局能接受所指国家适航当局批准出口的零件/组件/附件。
- (3) 表中的第 14 项、第 15 项的陈述, 并不说明本表是安装批准。在所有情况下, 航空器使用前, 航空器使用者/安装者应把本国适航条例颁发的安装批准放入维修记录中。

Workshop Report

Customer Order No. 163693		 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 P.O. Box 63 03 00 D-22313 Hamburg Federal Republic of Germany		60800136		 Certificate Ref. No. 619724	
Customer A.J. Walter Aviation Ltd.				Work order/Contract/Invoice 810135			
Part No. as received 336-065-008-0		Serial No. as received		Description OUTLET GUIDE VANE FAN (5A)			
Part No. as dispatched 336-065-008-0		Serial No. as dispatched		Responsible Workshop 48255			
Reason for removal Inspect and repair				Modification Status as dispatched according to Mod-Label			
Findings Protective Coating eroded. Steel Strip damaged.				N/A			
Action Outlet Guide Vane repaired per EM Chapter 72-23-03 Rep.005/006/ Rev. 56 dated from 20110215.							
						Name 25513, Rainer Kock	
						Date (d/m/y) 30/Nov/2011	


The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

1. Approving National Aviation Authority/Country: FAA/United States		2.		3. Form Tracking Number: 482666		
4. Organization Name and Address: THERMAL STRUCTURES, INC. 2362 RAILROAD STREET, CORONA, CALIFORNIA 92880-5410, USA BUSINESS PHONE: 951-736-9911 FAX: 951-736-1064 FAA APPROVED REPAIR STATION NUMBER: TEUR016K EASA APPROVAL CERTIFICATE NUMBER: EASA.145.4932				5. Work Order/Contract/Invoice Number: 97827-250800613		
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
1	OUTLET GUIDE VANE	336-065-008-0	N/A	1	RT35524	REPAIRED
13. Remarks: TSI WORK ORDER NUMBER: 97827 PURCHASE ORDER NUMBER: 250800613 PER ATA 72-23-03, CFM56-5A ENGINE MANUAL (ESM) 72-23-03 REV 56 INSPECTION 001 - CONFIGURATION 02/COMPOSITE PER ESM 72-23-03 REPAIR 005 - REPLACEMENT OF A METALLIC LEADING EDGE REPAIR 006 - FULL REPLACEMENT OF THE PAINT OR FILM COATING REPAIR 012 - REPAIR OF VANE ROOT FACES THE PRESCRIBED WORK WAS PERFORMED IN ACCORDANCE WITH FAA APPROVED DATA. TSI CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CONDUCTED IN ACCORDANCE WITH EASA.145.4932 WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RETURN TO SERVICE UNDER EASA.145.4932 APPROVAL CERTIFICATE NUMBER: EASA.145.4932						
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 13.						
15. Authorized Signature: NOT APPLICABLE		16. Approval/Authorization No.: NOT APPLICABLE		19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		21. Approval/Certificate No.: TEUR916K
17. Name (Typed or Printed): NOT APPLICABLE		18. Date (m/d/y): NOT APPLICABLE		20. Authorized Signature: 		23. Date (m/d/y): NOV/18/2011
22. Name (Typed or Printed): MICHAEL NAIM YWAKIEM						
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

1. Approving National Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 482666	
4. Organization Name and Address: THERMAL STRUCTURES, INC. 2362 RAILROAD STREET, CORONA, CALIFORNIA 92880-5410, USA BUSINESS PHONE: 951-736-9911 FAX: 951-736-1064 FAA APPROVED REPAIR STATION NUMBER: TEUR016K EASA APPROVAL CERTIFICATE NUMBER: EASA.145.4932						5. Work Order/Contract/Invoice Number: 97827-250800613	
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	OUTLET GUIDE VANE	336-065-008-0	N/A	1	RT35524	REPAIRED	
13. Remarks: TSI WORK ORDER NUMBER: 97827 PURCHASE ORDER NUMBER: 250800613 PER ATA 72-23-03, CFM56-5A ENGINE MANUAL (ESM) 72-23-03 REV 56 INSPECTION 001 - CONFIGURATION 02/COMPOSITE PER ESM 72-23-03 REPAIR 005 - REPLACEMENT OF A METALLIC LEADING EDGE REPAIR 006 - FULL REPLACEMENT OF THE PAINT OR FILM COATING REPAIR 012 - REPAIR OF VANE ROOT FACES THE PRESCRIBED WORK WAS PERFORMED IN ACCORDANCE WITH FAA APPROVED DATA. TSI CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CONDUCTED IN ACCORDANCE WITH EASA.145.4932 WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RETURN TO SERVICE UNDER EASA.145.4932 APPROVAL CERTIFICATE NUMBER: EASA.145.4932							
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☒ Non-approved design data specified in Block 13.							
15. Authorized Signature: NOT APPLICABLE		16. Approval/Authorization No.: NOT APPLICABLE		19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		21. Approval/Certificate No.: TEUR916K	
17. Name (Typed or Printed): NOT APPLICABLE		18. Date (m/d/y): NOT APPLICABLE		20. Authorized Signature: 		23. Date (m/d/y): NOV/18/2011	
22. Name (Typed or Printed): MICHAEL NAIM YWAKIEM							
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							


1. Approving National Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 482650	
4. Organization Name and Address: THERMAL STRUCTURES, INC. 2362 RAILROAD STREET, CORONA, CALIFORNIA 92880-5410, USA BUSINESS PHONE: 951-736-9911 FAX: 951-736-1064 FAA APPROVED REPAIR STATION NUMBER: TEUR916K EASA APPROVAL CERTIFICATE NUMBER: EASA.145.4932						5. Work Order/Contract/Invoice Number: 97636-250799954	
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	OUTLET GUIDE VANE	336-065-008-0	N/A	1	RT47991	REPAIRED	
13. Remarks: TSI WORK ORDER NUMBER: 97636 PURCHASE ORDER NUMBER: 250799954 PER ATA 72-23-03, CFM56-5A ENGINE MANUAL (ESM) 72-23-03 REV 56 INSPECTION 001 - CONFIGURATION 02/COMPOSITE PER ESM 72-23-03 REPAIR 005 - REPLACEMENT OF A METALLIC LEADING EDGE REPAIR 006 - FULL REPLACEMENT OF THE PAINT OR FILM COATING REPAIR 012 - REPAIR OF VANE ROOT FACES THE PRESCRIBED WORK WAS PERFORMED IN ACCORDANCE WITH FAA APPROVED DATA. TSI CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CONDUCTED IN ACCORDANCE WITH EASA.145.4932 WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RETURN TO SERVICE UNDER EASA.145.4932 APPROVAL CERTIFICATE NUMBER: EASA.145.4932							
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☒ Non-approved design data specified in Block 13.							
15. Authorized Signature: HAM LSC09 22.11.11 21:57  306 266207 Certific. Sticker		16. Approval/Authorization No.: NOT APPLICABLE		19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		21. Approval/Certificate No.: TEUR916K	
17. Name (Typed or Printed): MICHAEL NAIM YWAKIEM		22. Date (m/d/y): NOT APPLICABLE		23. Date (m/d/y): NOV/18/2011			
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

1. Approving National Aviation Authority/Country: FAA/United States		2.				3. Form Tracking Number: 482650			
4. Organization Name and Address: THERMAL STRUCTURES, INC. 2362 RAILROAD STREET, CORONA, CALIFORNIA 92880-5410, USA BUSINESS PHONE: 951-736-9911 FAX: 951-736-1064 FAA APPROVED REPAIR STATION NUMBER: TEUR016K EASA APPROVAL CERTIFICATE NUMBER: EASA.145.4932						5. Work Order/Contract/Invoice Number: 97636-250799954			
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:			
1	OUTLET GUIDE VANE	336-065-008-0	N/A	1	RT47991	REPAIRED			
13. Remarks: TSI WORK ORDER NUMBER: 97636 PURCHASE ORDER NUMBER: 250799954 PER ATA 72-23-03, CFM56-5A ENGINE MANUAL (ESM) 72-23-03 REV 56 INSPECTION 001 - CONFIGURATION 02/COMPOSITE PER ESM 72-23-03 REPAIR 005 - REPLACEMENT OF A METALLIC LEADING EDGE REPAIR 006 - FULL REPLACEMENT OF THE PAINT OR FILM COATING REPAIR 012 - REPAIR OF VANE ROOT FACES THE PRESCRIBED WORK WAS PERFORMED IN ACCORDANCE WITH FAA APPROVED DATA. TSI CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CONDUCTED IN ACCORDANCE WITH EASA.145.4932 WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RETURN TO SERVICE UNDER EASA.145.4932 APPROVAL CERTIFICATE NUMBER: EASA.145.4932									
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☒ Non-approved design data specified in Block 13.						19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature: NOT APPLICABLE		16. Approval/Authorization No.: NOT APPLICABLE		20. Authorized Signature: 		21. Approval/Certificate No.: TEUR916K			
17. Name (Typed or Printed): NOT APPLICABLE		18. Date (m/d/y): NOT APPLICABLE		22. Name (Typed or Printed): MICHAEL NAIM YWAKIEM		23. Date (m/d/y): NOV/18/2011			
User/Installer Responsibilities									
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.									

1. Approving National Aviation Authority/Country: FAA/United States		2.		3. Form Tracking Number: 482666			
4. Organization Name and Address: THERMAL STRUCTURES, INC. 2362 RAILROAD STREET, CORONA, CALIFORNIA 92880-5410, USA BUSINESS PHONE: 951-736-9911 FAX: 951-736-1064 FAA APPROVED REPAIR STATION NUMBER: TEUR016K EASA APPROVAL CERTIFICATE NUMBER: EASA.145.4932				5. Work Order/Contract/Invoice Number: 97827-250800613			
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	OUTLET GUIDE VANE	336-065-008-0	N/A	1	RT31585	REPAIRED	
13. Remarks:							
TSI WORK ORDER NUMBER: 97827 PURCHASE ORDER NUMBER: 250800613 PER ATA 72-23-03, CFM56-5A ENGINE MANUAL (ESM) 72-23-03 REV 56 INSPECTION 001 - CONFIGURATION 02/COMPOSITE PER ESM 72-23-03 REPAIR 005 - REPLACEMENT OF A METALLIC LEADING EDGE REPAIR 006 - FULL REPLACEMENT OF THE PAINT OR FILM COATING REPAIR 012 - REPAIR OF VANE ROOT FACES THE PRESCRIBED WORK WAS PERFORMED IN ACCORDANCE WITH FAA APPROVED DATA. TSI CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CONDUCTED IN ACCORDANCE WITH EASA.145.4932 WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RETURN TO SERVICE UNDER EASA.145.4932 APPROVAL CERTIFICATE NUMBER: EASA.145.4932							
14. Certifies the items identified above were manufactured in conformity to:			19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.				
15. Authorized Signature: NOT APPLICABLE		16. Approval/Authorization No.: NOT APPLICABLE		20. Authorized Signature: 		21. Approval/Certificate No.: TEUR916K	
17. Name (Typed or Printed): NOT APPLICABLE		18. Date (m/d/y): NOT APPLICABLE		22. Name (Typed or Printed): MICHAEL NAIM YWAKIEM		23. Date (m/d/y): NOV/18/2011	
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

1. Approving National Aviation Authority/Country: FAA/United States		2.				3. Form Tracking Number: 482666			
4. Organization Name and Address: THERMAL STRUCTURES, INC. 2362 RAILROAD STREET, CORONA, CALIFORNIA 92880-5410, USA BUSINESS PHONE: 951-736-9911 FAX: 951-736-1064 FAA APPROVED REPAIR STATION NUMBER: TEUR916K EASA APPROVAL CERTIFICATE NUMBER: EASA.145.4932						5. Work Order/Contract/Invoice Number: 97827-2508000613			
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:			
1	OUTLET GUIDE VANE	336-065-008-0	N/A	1	RT31585	REPAIRED			
13. Remarks: TSI WORK ORDER NUMBER: 97827 PURCHASE ORDER NUMBER: 250800613 PER ATA 72-23-03, CFM56-5A ENGINE MANUAL (ESM) 72-23-03 REV 56 INSPECTION 001 - CONFIGURATION 02/COMPOSITE PER ESM 72-23-03 REPAIR 005 - REPLACEMENT OF A METALLIC LEADING EDGE REPAIR 006 - FULL REPLACEMENT OF THE PAINT OR FILM COATING REPAIR 012 - REPAIR OF VANE ROOT FACES THE PRESCRIBED WORK WAS PERFORMED IN ACCORDANCE WITH FAA APPROVED DATA. TSI CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CONDUCTED IN ACCORDANCE WITH EASA.145.4932 WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RETURN TO SERVICE UNDER EASA.145.4932 APPROVAL CERTIFICATE NUMBER: EASA.145.4932									
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☒ Non-approved design data specified in Block 13.									
15. Authorized Signature: NOT APPLICABLE		16. Approval/Authorization No.: NOT APPLICABLE		19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		21. Approval/Certificate No.: TEUR916K			
17. Name (Typed or Printed): NOT APPLICABLE		18. Date (m/d/y): NOT APPLICABLE		20. Authorized Signature: 		23. Date (m/d/y): NOV/18/2011			
				22. Name (Typed or Printed): MICHAEL NAIM YWAKIEM					
User/Installer Responsibilities									
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.									

1. Approving National Aviation Authority/Country: FAA/United States		2.		AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 482650				
4. Organization Name and Address: THERMAL STRUCTURES, INC. 2362 RAILROAD STREET, CORONA, CALIFORNIA 92880-5410, USA BUSINESS PHONE: 951-736-9911 FAX: 951-736-1064 FAA APPROVED REPAIR STATION NUMBER: TEUR016K EASA APPROVAL CERTIFICATE NUMBER: EASA.145.4932				5. Work Order/Contract/Invoice Number: 97636-250799954								
6. Item:	7.	Description:	8.	Part Number:	9.	Eligibility: *	10.	Quantity:	11.	Serial/Batch Number:	12.	Status/Work:
1		OUTLET GUIDE VANE		336-065-008-0		N/A		1		RT48239		REPAIRED
13. Remarks: TSI WORK ORDER NUMBER: 97636 PURCHASE ORDER NUMBER: 250799954 PER ATA 72-23-03, CFM56-5A ENGINE MANUAL (ESM) 72-23-03 REV 56 INSPECTION 001 - CONFIGURATION 02/COMPOSITE PER ESM 72-23-03 REPAIR 005 - REPLACEMENT OF A METALLIC LEADING EDGE REPAIR 006 - FULL REPLACEMENT OF THE PAINT OR FILM COATING REPAIR 012 - REPAIR OF VANE ROOT FACES THE PRESCRIBED WORK WAS PERFORMED IN ACCORDANCE WITH FAA APPROVED DATA. TSI CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CONDUCTED IN ACCORDANCE WITH EASA.145.4932 WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RETURN TO SERVICE UNDER EASA.145.4932 APPROVAL CERTIFICATE NUMBER: EASA.145.4932												
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 13.												
15. Authorized Signature: NOT APPLICABLE		16. Approval/Authorization No.: NOT APPLICABLE		19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		20. Authorized Signature: 		21. Approval/Certificate No.: TEUR916K				
17. Name (Typed or Printed): NOT APPLICABLE		18. Date (m/d/y): NOT APPLICABLE		22. Name (Typed or Printed): MICHAEL NAIM YWAKIEM		23. Date (m/d/y): NOV/18/2011						
User/Installer Responsibilities												
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.												

1. Approving National Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 482650	
4. Organization Name and Address: THERMAL STRUCTURES, INC. 2362 RAILROAD STREET, CORONA, CALIFORNIA 92880-5410, USA BUSINESS PHONE: 951-736-9911 FAX: 951-736-1064 FAA APPROVED REPAIR STATION NUMBER: TEUR916K EASA APPROVAL CERTIFICATE NUMBER: EASA.145.4932						5. Work Order/Contract/Invoice Number: 97636-250799954	
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	OUTLET GUIDE VANE	336-065-008-0	N/A	1	RT48239	REPAIRED	
13. Remarks: TSI WORK ORDER NUMBER: 97636 PURCHASE ORDER NUMBER: 250799954 PER ATA 72-23-03, CFM56-5A ENGINE MANUAL (ESM) 72-23-03 REV 56 INSPECTION 001 - CONFIGURATION 02/COMPOSITE PER ESM 72-23-03 REPAIR 005 - REPLACEMENT OF A METALLIC LEADING EDGE REPAIR 006 - FULL REPLACEMENT OF THE PAINT OR FILM COATING REPAIR 012 - REPAIR OF VANE ROOT FACES THE PRESCRIBED WORK WAS PERFORMED IN ACCORDANCE WITH FAA APPROVED DATA. TSI CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CONDUCTED IN ACCORDANCE WITH EASA.145.4932 WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RETURN TO SERVICE UNDER EASA.145.4932 APPROVAL CERTIFICATE NUMBER: EASA.145.4932							
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☒ Non-approved design data specified in Block 13.				19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature: NOT APPLICABLE		16. Approval/Authorization No.: NOT APPLICABLE		20. Authorized Signature: 		21. Approval/Certificate No.: TEUR916K	
17. Name (Typed or Printed): NOT APPLICABLE		18. Date (m/d/y): NOT APPLICABLE		22. Name (Typed or Printed): MICHAEL NAIM YWAKIEM		23. Date (m/d/y): NOV/18/2011	
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							