



1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 107782-1	
4. Organization Name and Address: SOUTHERN AEROPARTS 4157 SOUTHWEST BLVD TULSA, OK. 74107 US				5. Work Order, Contract or Invoice Number: Work Order No.: SPN102431 Customer RO.: RW1412	
Repair Station No.: QAKR523K					
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	FEEDBACK ACTUATOR ASSEMBLY	LJ70534	1.00	1277	TESTED
12. REMARKS IN ACCORDANCE WITH CMM: 78-32-34 REV: 7 DATE: 15-JUN-1994					
NO APPLICABLE AND/OR ADDITIONAL A/D'S OR S/B'S NOTED ON THIS UNIT AT THIS TIME. Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number 145.5539					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval Authorization No:		14b. Authorized Signature 	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyy):		14c. Approval/Certificate No: QAKR523K	
				14d. Name (Typed or Printed): MARK GILL	
				14e. Date (dd/mm/yyy): 20/Dec/2019	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Southern Aeroparts
4157 Southwest Blvd
Tulsa, OK. 74107
US

Tear Down/Inspection

Work Order #: SPN102431

Date Printed: 20-Dec-19

Page: 1 of 1

To:
MID-AMERICAN AEROSPACE
2727 16TH AVE SW
CEDAR RAPIDS, IA 52404
UNITED STATES

Ship To:
MID-AMERICAN AEROSPACE
2727 16TH AVE SW
CEDAR RAPIDS, IA 52404 UNITED STATES

Cust.PO Ref.: RW1412

Cust.Phone:

Cust.Email:

Cust.Code: 310398

Cust.Fax:

Station: SAI

IN. PN: LJ70534

Descr: FEEDBACK ACTUATOR ASSEMBL' Qty: 1

OUT PN: LJ70534

Serial Numbers: 1277

Symptoms:

See PO

Faults:

Unit was tested and passes all tests and checks per CMM. Unit has free play in the gimbal. CMM has no play tolerances or friction tests for the gimbal.
KC - 12/10/2019

Corrective Actions:

Unit was tested IAW CMM

CMM: 78-32-34 Rev: 7 Date: 15-Jun-1994