

1. Approving Competent Authority/Country CAA / United Kingdom		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number ARC110302	
4. Organisation Name and Address  OAKENHURST AIRCRAFT SERVICES LTD Oakenhurst Aircraft Services Ltd Claydons Lane Rayleigh, Essex SS6 7UP United Kingdom Tel: +44 (0)1268741622 Email: sales@oakenhurst.com Web: www.oakenhurst.com				5. Work Order/Contract/Invoice WP92548 / R417260	
6. Item 1	7. Description Handset With Support	8. Part No. N40-1B20223-102	9. Qty. 1	10. Serial No. 331581	11. Status/Work Repaired
12. Remarks The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under FAA certificate no. 05KY452Y. Work as stated in box 11 has been carried out in accordance with manufacturers manual No: ATA 44-10-03 Revision: 14 Dated: 26 NOV 2021. Unit support Bracket: PNR: N40-1A20000-002 with SER: 689168 and Handset PNR: N40-1B20223-000 with SER: 704721.					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation ☐ Non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		14c. Certificate/Approval Ref. No. UK 145.00524	
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature  AVW 47	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name Stephen Brett	
				14e. Date (dd mmm yyyy) 26 Oct 2023	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. Approving Competent Authority/Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number ARC110301	
4. Organisation Name and Address  OAKENHURST AIRCRAFT SERVICES LTD		Oakenhurst Aircraft Services Ltd Claydons Lane Rayleigh, Essex SS6 7UP United Kingdom Tel: +44 (0)1268741622 Email: sales@oakenhurst.com Web: www.oakenhurst.com		5. Work Order/Contract/Invoice WP92548 / R417260	
6. Item 1	7. Description Handset With Support	8. Part No. N40-1B20223-102	9. Qty. 1	10. Serial No. 331581	11. Status/Work Repaired
12. Remarks Work as stated in box 11 has been carried out in accordance with manufacturers manual No: ATA 44-10-03 Revision: 14 Dated: 26 NOV 2021. Unit support Bracket: PNR: N40-1A20000-002 with SER: 689168 and Handset PNR: N40-1B20223-000 with SER: 704721.					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation ☐ Non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		Other regulation specified in block 12	
13b. Authorised Signature		13c. Approval/Authorisation Number		14c. Certificate/Approval Ref. No. EASA.UK.145.00524	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name Stephen Brett	
				14e. Date (dd mmm yyyy) 26 Oct 2023	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622

CAA Part 145: UK.145.00524

EASA Part 145: EASA.UK.145.00524

Completion Report

No: **WP92548**

Issue: **04**

Date: **26-Oct-23**

AJW Aviation
The Headquarters
Maydwell Avenue
Slinfold
West Sussex
RH13 0AS
United Kingdom

Attn: Summer Smythe

Tel: 0044 (0) 1403 798000 Fax:

E-Mail: summer.smythe@ajw-group.com

Your Ref: R417260	Our Ref: WP92548	Test Required: I.A.W. Manufacturers CMM	
Part No: N40-1B20223-102	Description: Handset With Support	TSN: N/A	CSN: N/A
Serial No: 331581	Workscope: Audio Repair	TSO: N/A	CSO: N/A
DoM: 01-Oct-13	Overhauled:	Inspected:	
Removed From:	Serial No:	Reg No: AP-BMM	Position:

Technical Reference: LIB02574 - Issue No: N/A - Rev No: 14


Inspection Findings:

Unit received for inspect/test with a reported defect of 'cradle assy top back collar and handset side damaged'. Unit tested. Testing Failed due to intermittent FPC layer. Unit disassembled for inspection. Inspection found support bracket attaching set missing, support assy damaged, handset ID label missing (requires new holmco serial number to be issued), keypad worn, front shell damaged, rear shell cracked, cable support cracked and SMD connector cracked. Reported defect confirmed. Unit re-assembled. Upon approval unit requires replacement of U/S parts, cleaning, re-assembly, testing and final checks to be carried out.

Workscope has been changed to repair.

Completion Summary:

Replacement parts fitted, reassembled, cleaned and tested IAW CMM.

Signed:  

Name: **S.BRETT**

Date: **26/OCT/2023**

For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP

Oakenhurst Aircraft Services Ltd. Claydons Lane, Rayleigh, Essex, SS6 7UP, UK.

Certificate Ref: ARC110301 - SERVICEABLE

Customer: AJW Aviation

Part No: N40-1B20223-102

Qty: 1

Description: Handset With Support

Serial No: 331581

Status/Work: Repaired

Order No: WP92548 / R417260

Release: EASA Form 1(Part 145)

Released: 26-Oct-23

Inspectors

Acceptance Stamp:



QAL0030

SERVICEABLE ITEM