

1. Approving Competent Authority / Country
CAA/UNITED KINGDOM

2.

AUTHORISED RELEASE CERTIFICATE EASA FORM 1

3. Form Tracking Number

104195603

4. Organisation Name and Address :
Tel: +44(0)118 926 1111
Fax: +44(0)118 966 8543



ROCKWELL COLLINS UK LIMITED
SUTTONS PARK AVENUE
READING, BERKSHIRE, RG6 1LA, UNITED KINGDOM

5. Work Order / Contract / Invoice
PO No: T10259

6. Item	7. Description	8. Part No	9. Qty	10. Serial No	11. Status / Work
	CABIN INTERPHONE CONTROLLER	1167005-142	1	9803040241	INSPECTED/TESTED

12. Remarks

Service Notification 104195603 refers
Inspected & tested IAW CMM 523-0781446 Ed-1, Rev 6, May 22/2002
using test software 1168245-303-6A.
Certifies that the work described in block 11/12 was carried out in accordance with EASA Part 145
and is eligible for TCCA release under Rockwell Collins UK
Certificate Number 807-24

<input type="checkbox"/> approved design data and are in condition for safe operation		<input checked="" type="checkbox"/> Part-145.A.50 Release to Service		<input checked="" type="checkbox"/> Other regulation specified in block 12	
<input type="checkbox"/> non-approved design data as defined in block 1		Certifies that unless otherwise specified in block 12, the work identified in block 1 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature	13c. Approval/Authorisation No		14b. Authorised Signature	14c. Certificate/Approval No	14e. Date (dd mm yy)
				UK.145.00237	04/APR/2012
13d. Name	13e. Date (dd mm yy)		14d. Name		
			Andrew Robinson		

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving National Aviation
Authority/Country:
FAA/United States

2.

AUTHORIZED RELEASE CERTIFICATE

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number

104195603

4. Organization Name and Address:

ROCKWELL COLLINS UK LIMITED
SUTTONS PARK AVENUE
READING, BK RG6 1LA UNITED KINGDOM BZ5Y 771M

5. Work Order/Contract/Invoice Number:
PO No: T10259

6. Item:

7. Description:

000010

CABIN INTERPHONE CONTROLLER

8. Part Number:

1167005-142

9. Eligibility:*

N/A

10. Quantity:

1

11. Serial/Batch Number:

9803040241

12. Status/

TESTED

13. Remarks:

1. Service notification number 104195603 refers.
2. Inspected & tested IAW CMM 523-0781446 Ed-1, Rev 6, May 22/2002 using test software 1168245-303-6A.

Item Numbers refer to numbers on Delivery Document

14. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation

☐ Non-approved design data specified in block 1.

15. Authorized Signature:

N/A

16. Approval/Authorization No.:

17. Name (Typed or Printed):

18. Date (m/d/y):

19. ☒ 14 CFR 43.9 Return to Service

☐ Other regulation specified in Block 1

Certifies that unless otherwise specified in Block 13, the work identified in Block 14, Code Federal Regulations, part 43 and in respect to that work, the items are approved return to service.

20. Authorized Signature:

AR

21. Approval/Certificate No

BZ5Y 771M

22. Name (Typed or printed)
Andrew Robinson

AR
R.C.U.K

23. Date (m/d/y):

APR/04/2012

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1.

Statements in block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Service Notification: 104195603

Service Memorandum

Customer: AJ WALTER AVIATION LTD

Contract Number :

Page 1 of 2

Customer P.O. Number: T10259

Customer Reject Paper Number :

Repair Station Certificate #:
BZ5Y771M UK.145.00237

Government Incoming Document Number:
Date Equipment Received : 22.03.2012

Equipment Type/Model :

Outgoing Equipment

Incoming Equipment

Aircraft Information

Part Number :

: 1167005-142

: 1167005-142

Type :

Serial Number/MCN :

: 9803040241

: 9803040241

Serial Number:

Tail No :

Description :

: CABIN INTERPHONE C

: CABIN INTERPHONE C

Position :

Customer Part Number :

Customer Serial Number:

Removed at Gateway:
Date Unit Removed :

For Questions Regarding This
Service Work, Please Contact
Customer Service at:
Phone : +44 (0) 118 935 9246
Fax : +44 (0) 118 966 8544

Customer Complaint/Instructions

Please test and recert.

Preliminary Inspection Results:

ESD caps fitted. QA seal intact.

Hidden Damage Inspection Results

N/A

Was the Complaint Verified? N/A

Description of What Was Wrong with the Equipment:
No faults found.

Were There Any Defects Found? YES

Airworthiness Directives

N/A

Description of Service Work Performed:

Uncased unit. Visually inspected. Cleaned edge connectors as a precaution. Ran self tests. Downloaded software 1167071-331-B6L & ran audio tests. No faults found. Reassembled & tested IAW CMM 523-0781446, Ed-1, Rev 6, May 22/2002 using test software 1168245-303-6A..

Service Bulletins/Mods Installed This Return:

None

Outgoing Service Bulletin Configuration:
A,B,C,D

Service Notification: 104195603

Service Memorandum
Page 2 of 2

This Article Has Been Certified Airworthy
On 04.04.2012 By A. Robinson

Preliminary Inspection	: 28.03.2012	By Paul A Staker
Final Test	: 28.03.2012	By Paul A Staker
Tested Per 1 :	CMM 523-0781446	ED. 1 REV. 06 TEMP REV. 32
Final Inspection	: 04.04.2012	By Andrew G Robinson

Defective / Failed Parts Replaced

Part Number

Description

Circuit Symbol

The supplier agrees that it will correct, without charge, any defect which is related to the original repair work performed, provided the customer gives the supplier prompt written notice of such defect and the equipment involved is returned to the supplier where repair work was performed. The period of the guarantee in the servicing of the product shall be one year from the date of despatch. Failures which are caused by aircraft/system deficiencies, customer damage/misuse, shipping or handling damage or exposure to environmental conditions in excess of those published in the equipment specifications are not covered by this guarantee. Warranty will be void if Rockwell Collins inspection seals are broken.

Rockwell Collins obligation shall be limited to that specified herein, and in no event will Rockwell Collins be responsible for consequential damages.

(For Airworthiness Release)

The work recorded above has been carried out in accordance with the requirements of the Air Navigation Order for the time being in force and in that respect the aircraft/equipment is considered fit for release to service.

ROCKWELL COLLINS UK LIMITED

E.A.S.A. APPROVAL UK.145.00237

F.A.A. APPROVAL BZ5Y 771M