

24426

1. Approving National Aviation
Authority/Country:

2.

AUTHORIZED RELEASE CERTIFICATE

3. Form Tracking Number:

381198

FAA/United States

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

5. Work Order/Contract/Invoice Number:

381198

4. Organization Name and Address:

Meggitt Safety Systems, Inc., 1915 Voyager Avenue, Simi Valley, CA 93063-3349 Certificate #WL3R949L

6. Item:

7. Description:

8. Part Number:

9. Eligibility:

10. Quantity:

11. Serial/Batch Number:

12. Status/Work:

1 DUAL DETECTOR ASSEMBLY,
APU

902013-01

N/A

1

3467

TESTED

13. Remarks:

UNIT WAS TESTED AND INSPECTED PER CMM 26-10-85, REV 6, DATED OCT 15 2006, BY S.KHATRA, ON JUL 28 2011.
UNIT APPROVED FOR RETURN TO SERVICE BY S.KHATRA, CERT # 3341685, ON JUL 28 2011

REF: TRAVELLER P/N 902013-01 S/N 3467

"USED PART, SHIPPED PER COUNTRY ACCEPTANCE LETTER OF USED PART"

"Certifies that the work specified in block 12/13 was carried out in accordance with EASA 145 and with respect to that work the aircraft component is considered ready for release to service under EASA Acceptance Certificate Number: EASA.145.5016"

19. ☒ 14 CFR 43.9 Return to Service☒ Other Regulation specified in Block 13

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to the work, the items are approved for return to service.

20. Authorized Signature:

21. Approval/Certificate No.:

22. Name(Typed or Printed):

23. Date (m/d/y):

KHATRA, SUKHINDER

Jul/28/2011

WL 3R949L

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the country specified in Block 1, it is essential that he user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

MEGGITT

Meggitt Safety Systems

1915 Voyager Avenue, Simi Valley CA 93063-3349

Tel: +1 805 584 4100 Fax: +1 805 577 8990

www.meggittsafety.com

REPAIR STATION WL3R949L

CUSTOMER: ALFA AVIATION SERVICES INC.

TEAR DOWN REPORT

RMR NO: 381198

PART NO: 902013-01

S/N: 3467

PURCHASE ORDER NO: R8046

SALES ORDER NO: 381198

1. Customer Reason for Removal:

TEST AND REPAIR

2. Meggitt findings:

TUBE, OKAY; DET S/N 17732 NO FAULT FOUND.


3. Discription of Work Accomplished:

TUBE, OKAY; DET S/N 17732 WAS TESTED AND INSPECTED.
UNIT RE-ASSEMBLED, TESTED AND INSPECTED PER CMM 26-10-85, REV 6, DATED OCT 15 2006.

4. Parts Replaced:

N/A

5. Authorized Signature


KHATRA, SUKHJINDER

Date: Jul/28/2011