

1. Approving Civil Aviation Authority/Country:
FAA/UNITED STATES

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
365539-22

4. Organization Name and Address:
Triumph Accessory Services - Grand Prairie
1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300


5. Work Order/Contract/Invoice Number:
365539 / R400260

6.Item:	7. Description:	8. Part Number:	9. Quantity:	10.Serial Number:	11.Status/Work:
1	N2 SPEED SENSOR	3218KGB01	1	EM168483-A	OVERHAULED

12.Remarks:
OVERHAULED IAW CMM ATA 77-11-15 REV: 13 DATE: 10/31/2007; TSN: 40764.10 CSN: 17537 TSO: 0 CSO: 0

Certifies that the work specified in block 11/12 was carried out in accordance with EASA part 145 and, with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number: EASA 145.5893

14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

14b.. Authorized Signature:


14c. Approval/Certificate No.:
GPYR474X

14d. Name: (Typed or Printed)
Leonardo Saldivar

14e. Date (dd/mm/yyyy):
11 NOV 2022

User/Installer Responsibilities
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.
Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.

FAA Form 8130-3 (02-14)
NSN: 0052-00-012-9005
FAA authorized authority per Op Specs A025 for electronic signatures IAW AC 120-78.

1. 国家 Country: CHINA		2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness 授权发布证书/航空认证标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG		3. 证书编号 Certificate Ref. No. 365539-22	
4. 单位 Organization: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		5. 工作单/合同单/货单 Work Order/Contract/Invoice Number: 365539 / R400260			
6. 序号 Item:	7. 内容 Description:	8. 件号 Part Number:	9. 适用性 Eligibility:*	10. 数量 Quantity:	11. 系列号/批号 Serial/Batch Number:
1	N2 SPEED SENSOR	3218KGB01	NOT KNOWN	1	12. 产品状态 Status/Work: OVERHAULED
13. 备注 OVERHAULED IAW CMM ATA 77-11-15 REV: 13 DATE: 10/31/2007; TSN: 40764.10 CSN: 17537 TSO: 0 CSO: 0					
Remarks:					
15. 使用过的产品 Used Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例和特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in Block 13, the work was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the parts(s) is (are) in condition of safe operation and considered ready for release to service. (over)					
16. 批准人 Signature:		18. 批准日期 Date		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100391	
17. 批准人姓名 (打印的) Name (Printed)		Leonardo Saldivar			

AAC-038(12/94)

*参阅产品目录详细查找是

*Cross-check eligibility for more details with parts catalogue

WORK ORDER FORM 100

Page No. 1



Work Order: 365539-22

Triumph Accessory Services -Grand Prairie

1038 Santerre Drive

Grand Prairie, TX 75050-1937

972/623-9300 FAX (972) 660-1580

FAA CRS No: GPYR474X

CAAC CRS No: F00100391

Customer: 012424 / AJ WALTER AVIATION LTD

Dept#: EL2

Cust RO#: R400260

Step: SHOP COMPLETE

Warranty Code: NW Qty: 1

Work Req: OH

P/N: 3218KGB01 / N2 SPEED SENSOR

S/N: EM168483-A

Mfg: CFMI

Manual#: 77-11-15 RevDate: 10/31/2007 Rev#: 13 ATA: 77-11-15

OH. RFR VIBRATION INDICATION INTERMITTENT

REMOVAL A/C REG: VH-VUZ. TSN 40764.10 CSN 17537

***** COMPLY WITH CUSTOMER P.O. REQUIREMENTS *****

Date Recvd: 09/21/2022 Date Reqr: / / Date Estmtd: 11/15/2022

PRELIMINARY INSPECTION: DATE: 09/21/2022 TECH: Leonardo Saldivar (esign)
NO VISIBLE SHIPPING DAMAGE NOTED
NO A.D.'S

TEARDOWN FINDINGS:

UNIT FAILED CONTINUITY TEST FOR THE "A/C" CHANNEL
INTERNAL INSPECTION REVEALED PINS 1 AND 2 WIRES BROKEN FROM
THE CONNECTOR WITH "A/C" CONTACTS MISSING, REQUIRES
INSTALLATION OF CONTACTS AND SLEEVING (QTY 2)
CUSTOMER REQUESTS OVERHAUL
100% KIT REQUIRED FOR O/H
DISASSEMBLED, CLEANED AND INSPECTED FOR OVERHAUL
IAW ATA 77-11-15 REV 13 DTD 10/31/2007
TECHNICIAN: PAULITO VIRAY (esign) DATE: 10/03/2022

CORRECTIVE ACTION:

REPLACED "A/C" CONNECTOR CONTACTS.
INSTALLED 100% KIT FOR O/H.
OVERHAULED IAW ATA: 77-11-15 REV. 13, DATED: 10/31/2007.
*
*OVERHAULED IAW CMM ATA 77-11-15 REV: 13 DATE: 10/31/2007; TSN: 4076
4.10 CSN: 17537 TSO: 0 CSO: 0
TECHNICIAN: Vernon C. Manka (esign) DATE: 11/07/2022

Test Technician: Fyllip B. Johnson (esign) DATE: 11/11/2022
Supervisor: Dwane Slusher (esign) DATE: 11/11/2022
Final Inspection: Leonardo Saldivar (esign) DATE: 11/11/2022

