




62015868

1. Approving Competent Authority / Country CAA UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number 22140259 00000001																
4. Organisation Name and Address Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany		5. Work Order / Contract / Invoice 62015868		11. Status / Work REPAIRED																
6. Item 01	7. Description SYSTEM DATA ACQUISITION CONC.	8. Part No. LA2E50700C90000	9. Qty. 1	10. Serial No. 2E5002013																
12. Remarks A.J. Walter (Aviation) Ltd. T42524 <table><tr><td>Opr. Hours</td><td>Cycle</td><td>Opr. Day</td></tr><tr><td>UNKNOWN</td><td>UNKNOWN</td><td>UNKNOWN</td></tr><tr><td>UNKNOWN</td><td>UNKNOWN</td><td>UNKNOWN</td></tr><tr><td>UNKNOWN</td><td>UNKNOWN</td><td>UNKNOWN</td></tr><tr><td>0</td><td>0</td><td>0</td></tr></table> TASK PERFORMED IN ACCORDANCE WITH CMM 31-55-37 REV. 18 / CMDS 31-55-37 ISSUE 042		Opr. Hours	Cycle	Opr. Day	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	0	0	0	ATA 3154		TP R	MK-No. 10
Opr. Hours	Cycle	Opr. Day																		
UNKNOWN	UNKNOWN	UNKNOWN																		
UNKNOWN	UNKNOWN	UNKNOWN																		
UNKNOWN	UNKNOWN	UNKNOWN																		
0	0	0																		
		Pack Code 00	Resp. Workshop 33431060																	
		Workshop Station HAM305																		
13a. Certifies that the items identified above were manufactured in conformity to: ☒ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12																				
13b. Authorised Signature		13c. Approval / Authorisation Number		14a. ☒ Part -145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.																
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature 025941 Wolfgang Rühmann																
				14c. Certificate / Approval Ref. Number UK.145.01408																
				14e. Date (dd mmm yyyy) 12 Dec 2023																

USER / INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



62015868

1. Approving Competent Authority / Country LBA / Germany		2.		3. Form Tracking Number 22140259 000000001	
4. Organisation Name and Address: Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany				5. Work Order/Contract/Invoice 62015868	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
01	SYSTEM DATA ACQUISITION CONC.	LA2E50700C90000	1	2E5002013	REPAIRED
12. Remarks A.J. Walter (Aviation) Ltd. T42524 TP R MK-No. 10 Pack Code 00 Resp. Workshop 33431060 Workshop Station HAM305					
Opr. Hours Cycle Opr. Day UNKNOWN UNKNOWN UNKNOWN TSO UNKNOWN UNKNOWN UNKNOWN TSC UNKNOWN UNKNOWN UNKNOWN TSF 0 0 0 TASK PERFORMED IN ACCORDANCE WITH CMM 31-55-37 REV. 18 / CMDS 31-55-37 ISSUE 042					
Return to Service in Accordance with 14 CFR part 43 The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under FAA Certificate No.: DLAY225D TCCA Approval No.: 897-08					
☒ Further details of work performed are attached either in a Workshop Report reference number see blocks 3 and 5 or in other applicable documents					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☒ non-approved design data specified in block 12					
14a. ☒ Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature		13c. Approval / Authorisation Number		14c. Certificate / Approval Ref. Number DE.145.0001	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name Wolfgang Rühmann	
				14e. Date (dd mmm yyyy) 12 Dec 2023	

EASA FORM 1 - Issue 3
USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Workshop Report

62015868

Customer Order No. T42524	 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany	Certificate Ref. No. 22140259 00000001
Part No. as received LA2E50700C90000	Serial No. as received 2E5002013	Work Order/Contract/Invoice 62015868
Part No. as dispatched LA2E50700C90000	Serial No. as dispatched 2E5002013	Description SYSTEM DATA ACQUISITION CONC.
Reason for removal AS REMOVED. FOR TEST AND REPAIR IF REQUIRED.		Responsible Workshop 33431060
Findings Incoming test failed in Analog card test, analog card defective and needs to be replaced. Front cover screws need to be replaced. "External condition of unit: No obvious damage visible. All scratches are caused by normal wear and tear and don't affect functionality."		Modification Status according to Mod-Label B C D E
Action Analog card replaced, out P/N LA2E50300H37200 S/N 220682 replaced by P/N LA2E50300H3720A S/N 000988901. Final acceptance test performed successfully on ATEC S6.		
		Name 25941, Wolfgang Rühmann
The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.		Date (dd mmm yyyy) 12 Dec 2023