

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2.		3. Form Tracking Number: FWO47338		
4. Organization Name and Address: VSE Aviation Services, Inc. 3361 Enterprise Way, Miramar, FL 33025, Fax:954/430-6601, 954/430-6600				5. Work Order/Contract/Invoice Number: FWO47338 / R420673		
6. Item 7. Description:				11. Status/Work:		
1 LIGHT CNTRL PNL				REPAIRED		
8. Part Number: 233A7202-3				10. Serial Number: F04778		
9. Quantity: 1.00				11. Status/Work: REPAIRED		
12. Remarks: This Item was REPAIRED I/A/W Manual # CMM 33-13-03, Revision # 7 Revision Date 10/27/2017						
NO APPLICABLE AD'S AND NO SB'S INSTALLED.						
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval no. EASA.145.5610						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12						
14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.						
13b. Authorized Signature:		13c. Approval Authorization No.:		14c. Approval/Certificate No.: 9QAR940B		
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 26-Dec-2023		
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

WORK ORDER FORM 100

Page No. 1

VSE Aviation Services, Inc.

3361 Enterprise Way
Miramar, FL. 33025
Fax: 954/430-6601
954/430-6600

**FAA CRS No: 9QAR940B****Work Order #: FWO47338**

Step: SH-SHIPPING

Department: Shop FLA

Location: FLA ACC

Customer: **AJW001 / AJ WALTER AVIATION**Cust RO#: **R420673**Mfg: **BAE**Outgoing: **233A7202-3 / LIGHT CNTRL PNL*******NO PMA PARTS*****

S/N: F04778

Warranty Code: 00

Goodthru AD#:

Incoming P/N: 233A7202-3

Incoming S/N: F04778

Incoming work Req: RE

Outgoing Work Req: REPAIRED

Repair Manuals: F1447

RevDate: 10/27/2017

Rev#: 7

ATA: 33-13-03

Tools:

REASON FOR REMOVAL: Date Recvd: 12/1/2023 Date Reqrd 1/1/2024 Date Estmtd: 1/1/2024 Container:

REPAIR

RFR: UNABLE TO SWITCH OFF

PRELIMINARY INSPECTION:

DATE: 12/07/23

INSPECTOR: MAT

VERIFIED P/N AND S/N PER ID PLATE AND RO. UNIT RECEIVED IN POOR CONDITION.

PRE TEST (Yes/No): YES

DATE: 12/07/23

INSPECTOR: MAT

UNIT FAILED FUNCTIONAL TEST.

HIDDEN DAMAGE:

N/A

TEARDOWN FINDINGS:

OPENED UNIT AS REQUIRED FOR INSPECTION AND TROUBLESHOOTING. INSPECTION REVEALS DEFECTIVE KNOBS. ALSO SPRINGS, WASHERS, RINGS AND STUDS NEED REPLACEMENT. TROUBLESHOOTING REVEALS DEFECTIVE TRANSFORMER T1. UNIT REQUIRES CLEANING AND REPAIR.

TECHNICIAN: ZXB

DATE: 12/07/23

INSPECTOR: MAT

FINAL INSPECTION BEFORE ASSEMBLY DATE: 12/22/23 INSPECTOR: MAT

CORRECTIVE ACTION:

THIS UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, REASSEMBLED, AND FUNCTIONALLY TESTED, IN ACCORDANCE WITH MANUFACTURER SPECIFICATIONS.

TECHNICIAN: ZXB

DATE: 12/26/23

INSPECTOR: MAT

MODIFICATION/SERVICE BULLETINS:

NO S/B INSTALLED. NO APPLICABLE AD

TEST DATA USED:

ATA: 33-13-03 REV#: 7 DATED: 10/27/2017

Test Technician: ZXB

Date: 12/26/23

Final Inspection: MAT

Date: 12/26/23

ADDITIONAL COMMENTS:



PACKING SLIP

VSE Aviation Services, Inc.
3361 Enterprise Way
Miramar, FL 33025
Telephone: 954/430-6600
FAA Repair Station 9QAR940B

Bill To:
AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0SH

Ship To:
AJ WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD RH13 0AS

Date		Ship Via		F.O.B.	Terms	
12/26/2023		FX INTL PRIORITY		ORIGIN		
Customer Order Number		Order Date		Sales Person	Contact	Our Order No.
R420673		12/26/2023		JORTIZ	*JEN WELCH	FSM47231
Quantity			Part Number / Description / SN		CD	
Req.	Ship.	B.O.				
1	1		233A7202-3 LIGHT CNTRL PNL SN: F04778		RP	

All returns must have a written RMA. No RMA's of Exchanges after 15 days.
Refused packages will be subject to a 50% restocking fee, plus shipping cost.
Returns may be subject to a 25% restocking fee, plus Shipping cost.