

1. Approving Civil Aviation
Authority/Country:

2.

FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

62792

4. Organization Name and Address:

Silver Wings Aerospace

FAA # 9ARR711Y

25400 S.W. 140 AVENUE

PRINCETON, FL 33032

Ph: 305-258-5950, Fax: 305-258-5953

FAA Approval Holder: 9ARR711Y

5. Work Order/Contract/Invoice
Number:

303040 / U13291

6. Item

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1 MAIN LANDING GEAR LOCK ACTUATOR / 293W3902-2

1

EM-0751

OVERHAULED

12. Remarks:

Overhauled in accordance with Boeing CMM 32-32-07 Revision # 29, dated 03/01/2016. No AD's or SB's were performed at this visit. Full details of work carried out per work order no. 303040 TSN: Unknown, TSO: 0.00

Silver Wings Aerospace, Inc. certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the aircraft component is considered ready for release to service under EASA Part 145 approval no. EASA.145.6394

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No:

14b. Authorized Signature:

14c. Approval/Certificate No:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

Noron M. Rawes

9ARR711Y

06/Jun/2017

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Silver Wings Aerospace
FAA # 9ARR711Y
25400 S.W. 140 AVENUE
PRINCETON, FL 33032
Ph: 305-258-5950, Fax: 305-258-5953
sales@silverwingsaerospace.com

Tear Down/Inspection

Work Order #: 303040

Date Printed: 6/6/2017

Page: 1

Customer:

ATTN: Thomas White
AJ Walter Aviation Limited
The Headquarters
Maydwell Avenue
Slinfold, West Sussex RH13 0AS
UNITED KINGDOM

Ship To:

AJ Walter Aviation Limited
The Headquarters
Maydwell Avenue
Slinfold, West Sussex, RH130AS UNITED KINGDOM

Part Number: 293W3902-2

Description: MAIN LANDING GEAR LOCK ACTUATOR ASSEM

Serial Number: EM-0751

Customer R/O: U13291

Symptoms:

Customer Request

Work Requested: Please Repair under T&M

Discrepancy/Reason for Removal: Please repair as part of BER project. Unit came disassembled

Faults:

Preliminary Inspection

Verified P/N as 293W3902-2 IAW Boeing CMM 32-32-07, Revision 29, Revision Date 03/01/2016.

Verified S/N as EM-0751 IAW Id plate and customer's repair order.

Visual Inspection: The unit was received disassembled in a bag.

Pre-test

Unable to perform functional test IAW Boeing CMM 32-32-07, Revision 29, Revision Date 03/01/2016

Reason: Unit received disassembled.

Customer complaint verified: Yes

Hidden Damages

N/A

Teardown Findings (OH)

Unit disassembled, cleaned and inspected IAW Boeing CMM 32-32-07, Revision 29, Revision Date 03/01/2016

The following parts require replacement: Bearings, seals, packing's, back ups, strap, and hardware.

The following parts require services/rework: NDI

AJ Walter Limited has no specialized work instructions.

** Overhaul Estimate **

AD & SB Status

N/A

Corrective Actions:

Corrective Action

Replaced parts and performed services listed under teardown findings.

Unit assembled and final tested.

The Unit was overhauled IAW Boeing CMM 32-32-07, Revision 29, Revision Date 03/01/2016

Modifications

N/A

Additional Comments

N/A

2f 06/04/2017



Silver Wings Aerospace
FAA # 9ARR711Y
25400 S.W. 140 AVENUE
PRINCETON, FL 33032
Ph: 305-258-5950, Fax: 305-258-5953
sales@silverwingsaerospace.com

Tear Down/Inspection

Work Order #: 303040

Date Printed: 6/6/2017

Page: 2

Assets

American labs test stand
HC0002
HC0004

PN	Description	Qty Issued	CD	Disposition
NAS1612-3A	PACKING	2	NE	STOCK
293W2515-3	CUP LOCK WASHER	1	NE	STOCK
BACS34A1A	SCRAPER	1	NE	STOCK
S33121-112-99	FOOT SEAL	1	NE	STOCK
NAS1611-112	O-RING	1	NE	STOCK
NAS1611-212	PACKING, O-RING	1	NE	STOCK
BACR12BM212	RING, BACKUP	1	NE	STOCK
S30662-116-99N	PISTON SEAL	1	NE	STOCK
NAS1611-116	PACKING	1	NE	STOCK
273T0050-4	STRAP	1	NE	STOCK
293W2521-3	BEARING	1	SV	STOCK
MS15004-1	FITTING-LUBE	3	NE	STOCK
293W3902-2	MAIN LANDING GEAR LOCK ACTUATOR	1	SV	REPAIR ORDER

2/ 06/06/2017