


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 139472-2	
4. Organization Name and Address: SOUTHERN AEROPARTS 4157 SOUTHWEST BLVD TULSA, OK. 74107 US				5. Work Order, Contract or Invoice Number: Work Order No.: SPN103418 Customer RO.: W49467	
Repair Station No.: QAKR523K					
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	ACTUATOR FEEDBACK SUBSYSTEM	3269264-9	1.00	AEX13240C	REPAIRED
12. REMARKS IN ACCORDANCE WITH CMM: 78-32-41 REV: 7 DATE: 07-FEB-2014					
NO APPLICABLE AND/OR ADDITIONAL A/D'S OR S/B'S NOTED ON THIS UNIT AT THIS TIME. Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number 145.5539					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval Authorization No:		14b. Authorized Signature: 	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14c. Approval/Certificate No: QAKR523K	
				14d. Name (Typed or Printed): SAMANTHA TALLY	
				14e. Date (dd/mm/yyyy): 01/Feb/2022	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. 国家 中国	2. 符合性 ☐ 符合性 ☒ 适航性	Conformity Airworthiness	中国民用航空局 批准放行证书/适航批准标签	CAAC	3. 证书编号 139472-3	Certificate Ref. No.:
4. 单位 Organization	Southern Aeroparts 4157 Southwest Blvd Tulsa, OK. 74107 US			5. 工作单/合同单/货单 Work Order: SPN103418 Customer RO: W49467		
6. 序号 Item	7. 内容 Description	8. 件号 Part No.	9. 适用性 Eligibility (*)	10. 数量 Qty	11. 系列号/批号 Serial/Batch No.	12. 产品状态 Status/Work
1	ACTUATOR FEEDBACK SUBSYSTEM	3269264-9	A330	1.00	AEX13240C	REPAIRED
13. 备注 REMARKS IN ACCORDANCE WITH CMM: 78-32-41 REV: 7 DATE: 07-FEB-2014						
14. 新产品 New Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该产品(出口产品)符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the Part(s) identified above except as otherwise specified in block 13 was(were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.			15. 使用过的产品 Used Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例和进口国通知的特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service.			
16. 批准人签名 Signature 		18. 批准日期 Date Feb/01/2022		19. 中国民航局授权 Issued by or on behalf of the CAAC		
17. 批准人姓名(打印的) Name (Printed): Samantha Tally		Approval No. F00100388				
AAC-038(12/94)						
参阅产品目录详细查看适用性。 () Cross-check eligibility for more details with parts catalog.						



Southern Aeroparts
4157 Southwest Blvd
Tulsa, OK. 74107
US

Tear Down/Inspection

Work Order #: SPN103418

Date Printed: 01-Feb-22

Page: 1 of 1

To:

AJ WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
WEST SUSSEX RH13 0AS
UNITED KINGDOM

Ship To:

AJ WALTER AVIATION LTD
The Headquarters
Maydwell Avenue
West Sussex
Slinfold, RH13 0AS UNITED KINGDOM

Cust.PO Ref.: W49467

Cust.Phone: 44 1 40 371 1777

Cust.Email:

Cust.Code: 310220

Cust.Fax: 1-441403710936

Station: SAI

IN. PN: 3269264-9

Descr: ACTUATOR FEEDBACK SUBSYSTI Qty: 1

OUT PN: 3269264-9

Serial Numbers: AEX13240C

Symptoms:

See PO

Faults:

*****SHOP REPORT*****

TECHNICIAN / NUMBER / DATE: Bmorgan 150103 10/13/21

P/N & SN ON DATA PLATE MATCHES PO/RO/WO: yes

REASON FOR REMOVAL: repair

TEAR DOWN FINDINGS: Unit missing 2 cover bolts. Unit missing NHA P/N ID plate. Loop clamp bent. Brake housing cracked.

NOTES: Unit sent in for warranty, but has never been here before. NHA P/N 3269264-9 S/N AEX 13240C, CDU P/N 126784-6. FEEDBACK P/N 3282936-1, S/N AEX11086. SWITCH P/N 3282812-2, S/N AEX03807

RECOMMENDED WORK SCOPE: REPAIR

Corrective Actions:

Unit has 2 new cover bolts. Unit has new NHA P/N ID plate. Loop clamp replaced. Brake housing replaced. Unit REPAIRED
Bmorgan 150103 1/19/22

CMM: 78-32-41 Rev: 7 Date: 07-Feb-2014