


1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 30221	
4. Organization Name and Address: JJA Aviation, Inc. 14450 COMMERCE WAY MIAMI LAKES, FL 33016 J30R252Y / EASA 145.5947				5. Work Order/Contract/Invoice Number: PO#: R415805 WO#: 30221	
6. Item 1		7. Description AUTO SPEED BRAKE CONTROL		8. Part Number 65-84209-21	9. Quantity 1
				10. Serial/Batch Number: D02589	11. Status/Work REPAIRED
12. Remarks: REPAIRED IN ACCORDANCE WITH CMM ATA 27-62-51, REV 30, DATED Oct 18, 2019. FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NO. : 30221					
Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part - 145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA 145.5947"					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.				14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12	
13b. Authorized Signature:				14b. Authorized Signature: 	
13c. Approval/Authorization No.:				14c. Approval/Certificate No.: J30R252Y	
13d. Name (Typed or Printed):				14d. Name (Typed or Printed): RAMON X MOMPPELLER	
13e. Date (dd/mm/yyyy)				14e. Date (dd/mm/yyyy): 11/Oct/2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



JJA AVIATION, INC.

14450 Commerce Way,
Miami Lakes, FL 33016
Phone: 305-498-7920 Fax: 786-558-4622
FAA CRS NO: J30R252Y / EASA: 145.5947

WORK ORDER

No.30221



Customer	AJ WALTER AVIATION LTD	Cust RO	R415805
Outg. P/N	65-84209-21 / AUTO SPEED BRAKE CONTROL	Outg. S/N	D02589
Manufact	BAE SYSTEMS	Warranty	00 / 1
Dept	ACCESSORIES	Goodthru AD#	

Manual #:684 Pub. Type: ATA 27-62-51 Rev #: 30 RevDate: Oct 18, 2019 Revised Date: Oct 3, 2023

Assets: H-0268, A-0281

Incoming P/N: 65-84209-21

Incoming S/N: D02589

Incoming Work Req: REPAIR

Work Performed: REPAIRED

Reason/RM:

AUTO SPEED NEVER ENGAGED

Date Recvd: Aug 22, 2023

Date Reqr'd:

Date Estmtd: Oct 12, 2023

PRELIMINARY INSPECTION: DATE: Aug 26, 2023

INSPECTOR: OXV

VERIFIED PART NUMBER AND SERIAL NUMBER WITH R.O. DIRTY EXTERIOR.

PRE TEST (Yes/No) : Y DATE: Aug 26, 2023

INSPECTOR: OXV

UNIT FAILED FUNCTIONAL TEST. UNABLE TO VERIFY MALFUNCTION AS REPORTED.

HIDDEN DAMAGE:

N/A.

TEARDOWN FINDINGS:

DISASSEMBLED UNIT AS REQUIRED FOR INSPECTION AND TROUBLESHOOTING.

INSPECTION REVEALED DIRTY EXTERIOR.

TROUBLESHOOTING REVEALED DEFECTIVE K6 RELAY DUE TO DEFECTIVE CONTACTS BETWEEN 22B Y 24B PINS. IN ORDER TO AVOID OTHER POSSIBLE FAILURES ALL RELAYS AND PRINTED CIRCUIT CARDS MUST BE CLEANED.

FUNCTIONALLY TESTED UNIT IN ACCORDANCE WITH MANUFACTURER SPECIFICATIONS.

PART AND REMOVAL OF DIRTY IS REQUIRED.

UNIT REQUIRES REPAIR.

TECHNICIAN: JCB

DATE: Sep 11, 2023

INSPECTOR: OXV

FINAL INSPECTION BEFORE ASSEMBLY:

DATE: Oct 5, 2023

INSPECTOR: RXM



JJA AVIATION, INC.

14450 Commerce Way,
Miami Lakes, FL 33016
Phone: 305-498-7920 Fax: 786-558-4622
FAA CRS NO: J30R252Y / EASA: 145.5947

WORK ORDER

No.30221



Customer AJ WALTER AVIATION LTD
Outg. P/N 65-84209-21 / AUTO SPEED BRAKE CONTROL
Manufact BAE SYSTEMS
Dept ACCESSORIES

Cust RO R415805
Outg. S/N D02589
Warranty 00 / 1
Goodthru AD#

CORRECTIVE ACTION:

REPLACED DEFECTIVE COMPONENTS LISTED ON TEARDOWN FINDINGS. CLEANED UNIT, REASSEMBLED UNIT. FUNCTIONALLY TESTED UNIT IN ACCORDANCE WITH MANUFACTURER SPECIFICATIONS. REPAIRED UNIT.

TECHNICIAN: JCB

DATE: Oct 5, 2023

INSPECTOR: RXM

MODIFICATION/SERVICE BULLETINS:

NO S/B INSTALLED AND N/A AD'S.

Test Data Used: Pub. Type: ATA 27-62-51

REV #: 30

DATED: Oct 18, 2019

Test Technician: JCB

DATE: Oct 5, 2023

Inspector: RXM

DATE: Oct 5, 2023

Final Inspection: RXM

DATE: Oct 5, 2023

ADDITIONAL COMMENTS:

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE, OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved return to Service By RAMON X MOMPPELLER

Date Oct 11, 2023