

AUTHORISED RELEASE CERTIFICATE

EASA FORM 1

1. Approving Competent Authority/Country CIVIL AVIATION AUTHORITY / UNITED KINGDOM		2		3. Form Tracking Number 75S47272-001	
4. Organisation Name and Address EATON LIMITED LARCHWOOD AVENUE BEDHAMPTON HAVANT HAMPSHIRE PO9 3QL				5. Work Order/Contract/Invoice RO 21563766-33	
Phone: +44-2392 487260 Fax: +44-2392 492400 Email: bdhuk_customerservices@eaton.com		9. Qty. 		10. Serial No. 	
6. Item 001		7. Description PV3-300-13L HYDRAULIC PUMP		8. Part No. 974800	
				11. Status/Work REPAIRED	

12. Remarks

REPAIRED IN ACCORDANCE WITH CMM29-10-55 REV: 10

MODs ON RECEIPT: B,C,D,E.

MODs INCORPORATED THIS VISIT: H,K,L,N.

IAW SB974800-29-02 REV: 1, SB974800-29-03 REV: 0, SB974800-29-04 REV: 1 & SB974800-29-05 REV: 0.

13a. Certifies that the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation
☐ Non-approved design data specified in block 12

14a. ☒ Part 145.A.50 Release to Service
 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service

13b. Authorised Signature

14b. Authorised Signature

13c. Approval/Authorisation Number

14c. Certificate/Approval Ref. No.

13d. Name

14d. Name

13e. Date (dd mmm yyyy)

14e. Date (dd mmm yyyy)



INSPECTION REPAIR REPORT

EATON LIMITED LARCHWOOD AVENUE BEDHAMPTON PO9 3QL GREAT BRITAIN			Call No:	T222963
			Line Item:	1
Customer Service Rep: LUCIEN NDIKUM	Date Recv'd	05/12/17	Work Release Date	12/12/17
Tel:	Service Type:	75REP	Administrator:	LUCIEN NDIKUM
Fax:				
Email: Customer Service Rep:	Customer Approved Direction:			

RECEIVED ORDER DETAILS

Returned By:	QATAR AIRWAYS	Operator/End User	QATAR AIRWAYS - TECH STO	
Model Number:	PV3-300-13L	Purchase Order #:	RO 21563766-33	
Part Number:	974800	Contract#:		
Serial Number:	G0210570	NSN or Ref P/N:	N/A	
Serial Number Suffix:		Customer Part #:		
Modifications:	B,C,D,E.	Customer Serial #:	G0210570	Suffix:
Customer Container:	no	Original Mfg Date:		

REMOVAL/RECEIPT DETAILS per customer documents

Date Removed:	22/11/17	TSN Hours:	44606	CSN:	8974
Aircraft Type:		TSO Hours:	44606	CSO:	8974
Aircraft Tail No:	A7-AEJ	TSR Hours:	0	CSR:	0
Fit Location on Aircraft:	NO.1				

WORK DOCUMENTS

CMM:	29-10-55	Date:	26/01/09	Rev:	10
Tech Manual/Drawing No:		Date:		Rev:	
ATP:	IAW CMM 29-10-55	Date:		Rev:	
Sales Order Control Instructions					

Customer Specifications/Documents

Special Instructions

EASA,FAA,TEARDOWN /STRIP REPORT,SHOP FINDINGS REPORT

Scheduled Removal Yes ☐ No ☒ Failure Analysis Required: Yes ☐ No ☒

Reason for Removal

FOR REPAIR

LEAK FROM DRIVE PAD AS PER THE USLR 2086357



INSPECTION REPAIR REPORT

*TEST FAILURE (02/02/18): LOW CASE FLOW WITH EDV SOLENOID ENERGISED.

ORIGINAL EDV SOLENOID RE-ISSUED TO THE PUMP DUE TO NO CHANGE TO THE TEST RESULTS ON THE RIG, MULTIPLE DEPARTMENTS CONSULTED ON CAUSES OF THE FAILURE MODE, THESE LEAD TO THE COMPENSATOR S/A WITHIN THE PUMP. NEW COMPENSATOR FITTED (SUBJECTED TO TEST).

*PASSED TEST (15/02/18): COMPENSATOR FOUND TO BE THE ROOT CAUSE OF THE FAILURE MODE, UNIT RETURNED TO MRO TO REJECT OFF THE SUSPECT COMPENSATOR S/A. PUMP PASSED TO FINAL INSPECTION.

Work Instructions:

MODIFICATION, REPAIR AND RECERTIFICATION.

Reason For Failure:

WORK ACCOMPLISHED



Svc Bulletin Incorporated

SB974800-29-02 REV 1, SB974800-29-03 REV 0, SB974800-29-04 REV 1

SB974800-29-05 REV 0.

Service Letters Inc		Status/Work Completed	
Mods Inc This Visit	H,K,L,N.	Mods Id'd on Name Plate	B,C,D,E,H,K,L,N.
Product Mod/Upgrd From	N/A	Product Mod/Upgrade To	N/A

APPROVALS

Stamp or Signature 		Date: 20 FEB 2018	Authorized Signature 	Date:
--	---	----------------------	--	-------

SHIPMENT DETAILS

SHIPMENT DETAILS

Ship to Customer	00017449	Bill to Customer	95853400		
Part Number:	974800	Model Number:	PV3-300-13L		
Serial Number:	G0210570	Serial Number Suffix			
Customer Part#:		Customer Serial #	G0210570	Suffix:	