

1. Approving Competent Authority / Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number E3254730	
4. Organisation Name and Address: Panasonic Avionics Services Singapore Pte. Ltd No. 9 Loyang Lane, Singapore 508927 Tel: 65-6381-6101 Fax: 65-6545-7484				5. Work order/Contract/Invoice 3254730 / IFE800195	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
1	TAPPING UNIT (TU)	RD-FA2051-02	1	E725493	INSPECTED/TESTED
12. Remarks PERTINENT DETAILS OF MAINTENANCE ACTIONS ARE HELD AT THIS FACILITY UNDER WORK ORDER NO. AS STATED ABOVE. MODIFICATION STATUS : 1 CMM 44-26-44 Rev 5 Dated 28-Oct-11					
Reference Detail Work in: attached Repair Report					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12					
14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature		13c. Approval/ Authorisation Number		14c. Certificate / Approval Ref. No. EASA.145.0475	
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature  14d. Name LOW TECK ENG	
14e. Date (dd mmm yyyy) 25 Jun 2013					
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the items(s). Where the user/ installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/ installer ensures that his/ her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must obtain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

REPAIR REPORT / DELIVERY ORDER

SHIP TO TRANSAERO AIRLINES
11A, ZUBOVSKY BOULEVARD
MOSCOW, 119021, RU

SHIP TRANSACTION:



CUSTOMER P.O. NUMBER IFE800195		CUSTOMER 1189	TAIL NO. EI-XLP	CUST PROD REF 9658050	SERVICE REQUEST 3254730	
PART NUMBER RD-FA2051-02		NOMENCLATURE TAPPING UNIT			DATE REMOVED	DATE RECEIVED 12-JUN-2013
SERIAL NUMBER E725493		DATE OF MFG 31-DEC-2010	WTY START DATE 31-DEC-2010	WTY END DATE 30-MAR-2014	DATE REPAIRED 19-JUN-2013	SHIP DATE
MOD IN 1						
REASON FOR CUSTOMER REJECTION	THE UNIT WAS REPLACED AFTER A MODERNIZATION OF THE PASSENGER CABIN					
INTERNAL INSPECTION	No Physical Damage ,HIDDEN DAMAGE INSPECTION: NA.					
EXTERNAL INSPECTION	No Physical Damage ,PRELIMINARY INSPECTION: NO SEAL.					
ACTUAL FAILURE / CORRECTIVE ACTION	PRETEST: PASSED. CLEANED LRU. UNIT TESTED PASSED AS PER CMM 44-26-44 REV 5, 28 OCT 2011.					

MOD OUT: 1

INSPECTED BY: LOW, TECK ENG

REPAIRED BY: Ho Kian Soon, Andy

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
A/V DISTRIBUTION N	A/V DISTRIBUTION NFF FEE	1	300.00	300.00	300.00	

Cost of Labor	300.00
Cost of Material	
Total Cost	300.00

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged