It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.  Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1.  It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.  Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance_records must contain an installation certification issued in accordance with the national regulations by the user/installation before the aircraft may be flown	User/Installer Responsibilities	13d. Name (Typed or Frinted): 13a. Data (dd/mmm/yyyy)	тан жана адпанта	entified above were manufacturi and are in a condition for safe data specified in Block 1.2	U BLOCK 11/12 WAS CARRIED OU.	12. Remarks: REPAIRED UNIT IAW BOEING CMM 32-35-25, REV #19 DATED JUL 01/16/	6. Item: 7. Description: 8. Part Number: 273N4006-3 ACTUATOR ASSY		Components	4. Organization Name and Address: 人は てアタルシャル	FAA/United States FA	Approving Civil Aviation     Authority/Country:     2.	
		(Kyyyy): 15d-Name (Typed or Printe) JASON CHEVALIER	offization was			EV #19 DATED JUL 01/16)		nber: 9. Quantity:	Gilbert, AZ 85233 480-831-1268 FAX 480-831-1314		FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	AUTHORIZED RELEASE CERTIFICATE	
ft engine/propeller/article. vorthiness authority of the country specified in B airworthiness authority of the country specified istallation certification issued in accordance with		nted): 14e. Date (dd/mmm/yyyy): 31/OCT/2017	Z6AR209Y	n to Service wise specified in Block 12, wi in accordance with Title tems are approved for retu	E WITH PART-145 AND IN RESPECT TO THAT NO: EASA.145.5116."			91-1547	10. Serial Number:		76 A B 200 V 5. Work		
Block 1, In block 1.		nm/yyyy): 7	orthicate No:	Other regulation specified in Block 12 the work identified in Block 11 and described in 14, Code of Federal Regulations, part 43 and in rn to service.				ARED	11. Status/Work:	W0104014	5. Work Order/Contract/Invoice Number:	R328282	3. Form Tracking Number:



900 N. Fiesta Blvd. Gilbert, AZ 85233 Ph: 480-831-1268

FAA Repair Station # Z6AR209Y Fx: 480-831-1314

## COMPONENT TEARDOWN/CONDITION REPORT

Customer 10109 AJ WALTER Nomenclature ACTUATOR ASSY Part Number 273N4006-3	MFG	WC CUST-F 1-1547 A/	DRK ORDER# W0104014 PO# R328282 /C
Reason For Removal/Custome: REPAIR AS REQUIRED IAW MI DUAL RELEASE REQUIRED.	r Instructions Mo FG SPECS.	difications/S.B/	A.D Compliance
Visual Inspection Prior To UNIT DIRTY. PAINT CHIPPEI	Teardown: ) / WORN.		
Preliminary Test Results: TESTED IAW CURRENT OEM/MI ALL TESTS PASSED.	FG SPECS.		
Teardown And Inspection Fir BACK-UPS, PACKINGS, SEALS REQUIRED. PERFORMED SIDE THE BEARING MIGRATED LESS	S, SCRAPER, BEARING LOAD TEST. WITH A I	, CAD PLATING WO	RN. REFINISH
Corrective Action Taken: REPAIRED UNIT IAW BOEING	CMM 32-35-25, REV :	#19 DATED JUL 01	./16.
Final Disposition: REPAIRE	ED		
TECH JT JOE TREMONT	INSPECTOR JC J		DATE OCT/31/2017
For further info contact _	Roy Hyde	at 480-831-1268	
			ATC009



900 N. Fiesta Blvd. Gilbert, AZ 85233 Ph: 480-831-1268

FAA Repair Station # Z6AR209Y Fx: 480-831-1314

## COMPONENT TEARDOWN/CONDITION REPORT

Customer Nomencla	10109 ature ACT ========	AJ WALTER UATOR ASSY	AVIATION LTD. MFG		WORK ORDER# W0104014 CUST-PO# R328282			
=======	=======	**** ========	PARTS	REPLACEMENT	RECORD	****	Page 1 of 1	
QTY ======	Item #	===	Part	Number	Nomenclature			
2 1 1 1	70 65 40 30 57C		NAS16 BACS3 BACB1	782-22 511-217 64A2A .0FE05C	SC	CKING RAPER ARING	=======================================	

ATC009