

1. Approving Civil Aviation
Authority/Country:

2.

FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

F40698

4. Organization Name and Address:

VSE Aviation Services, Inc.
3361 Enterprise Way, Miramar, FL. 33025, Fax:954/430-6601, 954/430-6600

Repair Station: 9QAR940B

5. Work Order/Contract/Invoice
Number:

F40698 / R376434

6. Item

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1 WINGTIP LIGHT

30-3083-1

1.00

0761

REPAIRED

12. Remarks: This item was REPAIRED I/AW Manual # CMM 33-42-63, Revision # 5 Revision Date 5/14/2020

NO APPLICABLE ADS AND NO SBS INSTALLED.

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval no. EASA.145.6610

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

LUIS MANUEL

22-Jun-2021

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

WORK ORDER FORM 100

Page No. 1

VSE Aviation Services, Inc.

3361 Enterprise Way
Miramar, FL. 33025
Fax: 954/430-6601
954/430-6600

**FAA CRS No: 9QAR940B****Work Order #: F40698**

Step: SH-SHIPPING

Department: Shop FLA

Location: FLA ACC

Customer: **AJW001 / AJ WALTER AVIATION**Cust RO#: **R376434*******NO PMA PARTS*****

Warranty Code:

Goodthru AD#:

Mfg: **HONEY**Outgoing: **30-3083-1 / WINGTIP LIGHT**

S/N: 0761

Incoming P/N: 30-3083-1

Incoming S/N: 0761

Incoming work Req:

Outgoing Work Req: REPAIRED

Repair Manuals: F2167

RevDate: 5/14/2020

Rev#: 5

ATA: 33-42-63

Tools:

REASON FOR REMOVAL: Date Recvd: 6/25/2020 Date Reqrd 7/15/2020 Date Estmtd: 7/15/2020

PLEASE REPAIR UNDER T&M-QUOTE AND HOLD

PRELIMINARY INSPECTION: DATE:25/JUN/2020 INSPECTOR:RBO

VERIFIED P/N AND S/N PER UNIT AND R/O. UNIT RECEIVED IN FAIR CONDITION.

PRE TEST (Yes/No): Y DATE:25/JUN/2020 INSPECTOR:RBO

UNIT FAILED FUNCTIONAL TEST. LED MODULE 1 FAILED TO ILLUMINATE.

HIDDEN DAMAGE:

NONE NOTED

TEARDOWN FINDINGS:

OPENED UNIT AS REQUIRED FOR INSPECTION AND TROUBLE SHOOTING. NO UNUSUAL CONDITION NOTED. TROUBLE SHOOTING REVEALED DEFECTIVE LED MODULE 1. REPAIR QUOTE

TECHNICIAN: EXG

DATE: 25/JUN/2020

INSPECTOR: RBO

FINAL INSPECTION BEFORE ASSEMBLY DATE:06/18/21 INSPECTOR:LAM

CORRECTIVE ACTION:

THIS UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, REASSEMBLED, AND FUNCTIONALLY TESTED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.

TECHNICIAN: EXG

DATE: 06/18/21

INSPECTOR: LAM

MODIFICATION/SERVICE BULLETINS:

NO APPLICABLE AD'S AND NO SB'S INSTALLED.

TEST DATA USED:

ATA:33-42-63 REV#5 18JUN2021

Test Technician: EXG

Date: 06/18/21

Final Inspection: LAM

Date: 06/18/21

ADDITIONAL COMMENTS:

WORK ORDER FORM 100

Page No. 2

VSE Aviation Services, Inc.

3361 Enterprise Way
Miramar, FL. 33025
Fax: 954/430-6601
954/430-6600



FAA CRS No: 9QAR940B

Work Order #: F40698

Step: SH-SHIPPING

Department: Shop FLA

Location: FLA ACC

Customer: **AJW001 / AJ WALTER AVIATION**

Cust RO#: **R376434**

Mfg: **HONEY**

Outgoing: **30-3083-1 / WINGTIP LIGHT**

*****NO PMA PARTS*****

S/N: 0761

Warranty Code:

Goodthru AD#:

Incoming P/N: 30-3083-1

Incoming S/N: 0761

Incoming work Req:

Outgoing Work Req: REPAIRED

N/A

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by


LUIS MANUEL

Date: 6/22/2021 10:58:49 AM

