



1. Approving Competent Authority/Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 2022001137852Y02 344695386	
4. Organisation Name and Address: HONEYWELL UK LIMITED, 1/a HONEYWELL AEROSPACE BASINGSTOKE, EDISON RD BASINGSTOKE HAMPSHIRE RG21 6QD TEL:+44(0)1256 722200 FAX: +44(0)1256 722201				5. Work Order/Contract/Invoice R396379 344617811 Page 1 of 1	
6. Item 001	7. Description PANEL	8. Part No 4082260-939	9. Qty 1	10. Serial No. 000822233	11. Status/Work REPAIRED
12. Remarks WORK PERFORMED AS DETAILED IN SERVICE REPORT THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 22-19-20 Rev 10, AUG/09/2019 TESTED IAW SA4082260-111 REV B. THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER GENERATED SIGNATURE PROCEDURE MODS: A-F. PRINTED FROM EASA TECHNICAL FILE					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12			14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		
13b. Authorised Signature			14b. Authorised Signature <i>Rich</i>		14c. Certificate/Approval Ref. No EASA.UK.145.00879
13d. Name			14d. Name Richard Wilson		14e. Date (dd mmm yyyy) 05 JUL 2022
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulation of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

CAA
UK

AUTHORISED RELEASE CERTIFICATE

CAA FORM 1

4. Organisation Name and Address:

HONEYWELL UK LIMITED t/a HONEYWELL AEROSPACE BASINGSTOKE,
EDISON RD BASINGSTOKE HAMPSHIRE RG21 6QD
TEL: +44(0)1256 722200 FAX: +44(0)1256 722201

3. Form Tracking Number
20220011137854Y32
344695386

5. Work Order/Contract/Invoice
#396379

344617811
Page 1 of 1
11. Status/Work
REPAIRED

6. Item	7. Description	8. Part No	9. Qty	10. Serial No.
001	PANEL	4082260-939	1	00082233

12. Remarks

WORK PERFORMED AS DETAILED IN SERVICE REPORT
THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH:
CMM 22-19-20 Rev 10, AUG/09/2019

TESTED IAW SA4082260-111 REV B.

THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER
GENERATED SIGNATURE PROCEDURE
MODS: A-F.

THE WORK IDENTIFIED IN BLOCK 11 AND DESCRIBED HEREIN HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH 14 CFR PART 43 AND IN RESPECT TO THAT WORK,
THE ITEMS ARE APPROVED FOR RETURN TO SERVICE UNDER CERTIFICATE NO. XYWY939L

13a. Certifies that the items identified above were manufactured in conformity to:
☐ approved design data and are in condition for safe operation
☐ non-approved design data specified in block 12

14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work identified in block 11
and described in block 12, was accomplished in accordance with Part-145 and in
respect to that work the items are considered ready for release to service.

13b. Authorised Signature

13c. Approval/Authorisation Number

14b. Authorised Signature

14c. Certificate/Approval Ref. No

UK.145.00879

14d. Name

Richard Wilson

14e. Date (dd mm yyyy)

05 JUL 2022

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulation of an airworthiness authority different than the airworthiness authority specified in block 1,
ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national
regulations by the user/installer before the aircraft may be flown.

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5016630180		344695386	FAA: XYWY939L	EASA: UK.145.00879
PO: R396379	CUSTOMER PART NUMBER:		CONTRACT NUMBER: 440082821	
DATE REJECTED: 10 JUN 2022	DATE RECEIVED: 21 JUN 2022		DATE COMPLETED: 05 JUL 2022	
A/C TYPE: UNK	A/C TAIL NUMBER: EI-AZA		A/C SERIAL NUMBER: 28655	
PACKING STATUS: No	SEALS INTACT: None		PHYSICAL DAMAGE: No	
REASON FOR REMOVAL: HDG WINDOWS MIDDLE DIGIT UNREADABLE D201501000033				
PART NUMBER	AS RECEIVED:		AS RELEASED:	
	4082260-939		4082260-939	
DESCRIPTION:	PANEL		PANEL	
SERIAL NUMBER	00082233		00082233	
UID(MFR/SPL PNO SER/UCN)	58960 2378262		58960 2378262	
HW MOD STATUS:	A-F.		A-F.	
SW MOD STATUS:				
SOFTWARE LOAD:				
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed			ESTIMATE SUPPLIED: Yes	
PRIMARY SHOP FINDING: Hardware Fault Found			WARRANTY: Warranty Denied	
TYPE OF SERVICE: REPAIRED			TECHNICIAN: Richard Wilson	
MAINTENANCE STATEMENT: PAGES DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, ARE ATTACHED IN PAGES 2 THROUGH 4				
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____				
SIGNATURE OF AUTHORIZED PERSON: _____				
Complied With CMM/Eng Documentation: 22-19-20/Rev 10/Rev Date 09 AUG 2019; Service Bulletins: Customer Manuals/Documentation:				
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.				

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5016630180		FAA: XYWY939L	EASA: UK.145.00879
PO: R396379	CUSTOMER PART NUMBER:	CONTRACT NUMBER: 440082821	

Previously Complied With CMM/Eng Documentation: Service Bulletins: Customer Manuals/Documentation:								
Evaluation Findings CUSTOMER'S FAULT CONFIRMED:-HEADING DISPLAY DEFECTIVE. V/S PUSHBUTTON INTERMITTENT. CRS#1, CRS#2, BANK ANGLE & ALT SEL KNOBS WORN. V/S THUMBWHEEL CRACKED. CRS#1, CRS#2, IAS/MACH AND HEADING DETENT SHAFTS WORN. DETENT PLUNGERS WORN. MODS F AND G REQUESTED, MOD F ALREADY CARRIED OUT, MOD G NOT REQUIRED. SIL D201501000033 PREVIOUSLY CARRIED OUT. UNIT TO BE REPAIRED, INSPECTED AND TESTED TO SPEC.								
Work performed / Comments to Customer WORN DETENT SHAFTS REPLACED. DETENT PLUNGERS REPLACED. V/S THUMBWHEEL REPLACED. V/S & IAS/MACH ASSY'S CALIBRATED. CRS#1, CRS#2 & HDG ASSY'S CALIBRATED. FRONT PANEL REPLACED. INSPECTED IAW CMM. TESTED IAW SA4082260-111 REV B.								
DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
Replace		4045626-901		4045626-901		2		
KNOBS WORN.								
Replace		4045621		4045621		1		
KNOB WORN.								
Replace		4045626-903		4045626-903		1		
KNOB WORN.								

SERVICE REPORT

AJW AVIATION LTD

+44(0)1256 722200 (T) +44(0)1256 722201 (F)

SR NUMBER: 5016630180						FAA: XYWY939L		EASA: UK.145.00879	
PO: R396379			CUSTOMER PART NUMBER:			CONTRACT NUMBER: 440082821			
DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB	
Exchange		4077790-2	297	4077790-2	761	1			
HEADING DISPLAY DEFECTIVE.									
Replace		4048439-5		4048439-5		1			
PLUNGER WORN.									
Replace		4082515		4082515		1			
DETENT GEARSHAFT WORN.									
Replace		4048439-5		4048439-5		1			
PLUNGER WORN.									
Replace		4082507		4082507		1			
DETENT GEAR WORN.									
Replace		4048439-5		4048439-5		1			
PLUNGER WORN.									
Replace		4082543		4082543		1			
DETENT GEARSHAFT WORN.									
Replace		4071842-1		4071842-1		1			
PLUNGER WORN.									
Replace		4048439-5		4048439-5		1			
PLUNGER WORN.									
Replace		4048439-5		4048439-5		1			
PLUNGER WORN.									

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5016630180	FAA: XYWY939L	EASA: UK.145.00879
------------------------------	-------------------------	------------------------------

PO: R396379	CUSTOMER PART NUMBER:	CONTRACT NUMBER: 440082821
-----------------------	------------------------------	--------------------------------------

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
Replace		4082515		4082515		1		

DETENT GEARSHAFT WORN.

Replace		4045636-1		4045636-1		1		
---------	--	-----------	--	-----------	--	---	--	--

THUMBWHEEL CRACKED.

MEASUREMENT DESCRIPTION	MEAS. VALUE (DECIMAL)	MEAS. VALUE (HH:MM)
Time Since Repair		0:00
Cycles Since Repair		

RTS TECHNICIAN 	DATE 05 JUL 2022
--	------------------