

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 351326-21	
4. Organization Name and Address: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300				5. Work Order/Contract/Invoice Number: 351326 / 1294324		
6.Item: 7. Description:		8. Part Number:	9. Quantity:	10.Serial Number:	11.Status/Work:	
1 MOUNT ASSY-ENG, AFT		310A2030-11	1	234	OVERHAULED	
12.Remarks: OVERHAULED IAW CMM ATA 71-21-37 REV: 47 DATE: 03/01/2022 COMPLIED WITH A.D. 2011-18-10 DATE: 11/07/2011 TSO: 0 CSO: 0 Certifies that the work specified in block 11/12 was carried out in accordance with EASA part 145 and, with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number: EASA 145.5893						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 12.						
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy):		14b.. Authorized Signature: 		
				14c. Approval/Certificate No.: GPYR474X		
				14d. Name: (Typed or Printed) Leonardo Saldivar		
				14e. Date (dd/mm/yyyy): 10 MAR 2022		

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.

1. 国家 Country: CHINA		2. 中国民用航空总局 CAAC □ 符合性 Conformity X 适航性 Airworthiness 授权发布证书/航空认证标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG		3. 证书编号 Certificate Ref. No. 351326-21	
4. 单位 Organization: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		5. 工作单/合同单/货单 Work Order/Contract/Invoice Number: 351326 / 1294324			
6. 序号 Item:	7. 内容 Description:	8. 件号 Part Number:	9. 适用性 Eligibility:*	10. 数量 Quantity:	11. 系列号/批号 Serial/Batch Number:
1	MOUNT ASSY-ENG, AFT	310A2030-11	NOT KNOWN	1	234
12. 产品状态 Status/Work: OVERHAULED					
13. 备注 OVERHAULED IAW CMM ATA 71-21-37 REV: 47 DATE: 03/01/2022 Remarks: COMPLIED WITH A.D. 2011-18-10 DATE: 11/07/2011 TSO: 0 CSO: 0					
14. 新产品 New Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该产品 (出口产品) 符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the Parts(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.			15. 使用过的产品 Used Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例和特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in Block 13, the work was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the parts(s) is (are) in condition of safe operation and considered ready for release to service. (over)		
16. 批准人 Signature: 		18. 批准日期 Date 10 Mar, 2022			
17. 批准人姓名 (打印的) Name (Printed) Leonardo Saldivar		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100391			

AAC-038(12/94)

*参阅产品目录详细查找

*Cross-check eligibility for more details with parts catalogue

WORK ORDER FORM 100

Page No. 1



Work Order: 351326-21

Triumph Accessory Services -Grand Prairie

1038 Santerre Drive
Grand Prairie, TX 75050-1937
972/623-9300 FAX (972) 660-1580
FAA CRS No: GPYR474X

CAAC CRS No: F00100391

Customer: 011387 / AAR ALLEN ASSET MANAGEMENT

Dept#: EMT

Cust RO#: 1294324

Step: SHOP COMPLETE

Warranty Code: NW Qty: 1

Work Req: OH

P/N: 310A2030-11 / MOUNT ASSY-ENG, AFT

S/N: 234

Mfg: BOEING

Manual#: 310A2020 RevDate: 03/01/2022 Rev#: 47

ATA: 71-21-37

INSP AND QUOTE TO LATEST MANUAL REV FOR RP

***** COMPLY WITH CUSTOMER P.O. REQUIREMENTS *****

Date Recvd: 12/01/2021 Date Reqr: / / Date Estmtd: 03/10/2022

AD: 2011-18-10

PRELIMINARY INSPECTION:

DATE: 02/08/2022

TECH: Leonardo Saldivar (esign)

P/N IS ILLEGIBLE, VERIFY AND RE-MARK AS NECESSARY

SEE A.D. 2011-18-10

TEARDOWN FINDINGS:

DISASSEMBLED, CLEANED AND INSPECTED IAW

ATA 71-21-37 REV 47 DTD 03/01/2022.

P/N VERIFIED AS 310A2030-11.

4 NUTS COATING CORRODED AND REQUIRE REPLACEMENT.

SPRING CLIP HAS WEAR AND REQUIRES REPLACEMENT.

1 PAWL PIN O/D WORN DOWN TO BASE METAL AND

REQUIRES REPAIR (VENDOR).

1 BUSHING GOUGED AND REQUIRES REPLACEMENT.

5 BEARINGS OUT OF ORIENTATION LIMITS AND REQUIRE REPLACEMENT.

1 BEARING SEIZED AND REQUIRES REPLACEMENT.

3 BEARINGS HAVE WEAR CAUSING EXCESSIVE PLAY AND

REQUIRE REPLACEMENT.

RIGHT LINK HAS WEAR AND REQUIRES BLENDING IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 9.

LEFT LINK HAS WEAR AND REQUIRES BLENDING IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 10.

CENTER LINK HAS WEAR AND REQUIRES BLENDING IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 12.

EVENER BAR HAS WEAR AND REQUIRES BLENDING IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 13.

HANGER FITTING HAS WEAR AND REQUIRES BLENDING IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 2 AND 5.

UNIT REQUIRES OVERHAUL DUE TO REPAIR.

AD 2011-18-10 DTD 11/07/2011 REQUIRES CORRECT INSTALLATION OF

CENTER LINK AND INSPECTION OF HANGER FITTING FOR CRACKS.

TECHNICIAN: Bradley Causer (esign) DATE: 02/17/2022

CORRECTIVE ACTION:

Printed 03/10/2022 09:26:43 TASGP-D55Q Rev IR Dated: 03/09/2011

Labor Task Control#



wopstm

WORK ORDER FORM 100

Page No. 2



Work Order: 351326-21

Triumph Accessory Services -Grand Prairie

1038 Santerre Drive

Grand Prairie, TX 75050-1937

972/623-9300 FAX (972) 660-1580

FAA CRS No: GPYR474X

CAAC CRS No: F00100391

Customer: 011387 / AAR ALLEN ASSET MANAGEMENT

Dept#: EMT

Cust RO#: 1294324

Step: SHOP COMPLETE

Warranty Code: NW Qty: 1

Work Req: OH

P/N: 310A2030-11 / MOUNT ASSY-ENG, AFT

S/N: 234

Mfg: BOEING

CORRECTIVE ACTION:

OVERHAULED IAW ATA 71-21-37 REV 47 DTD 03/01/2022.

REPLACED 4 NUTS, SPRING CLIP, 1 PAWL PIN,

1 BUSHING AND 9 BEARINGS.

RIGHT LINK BLENDED IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 9.

LEFT LINK BLENDED IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 10.

CENTER LINK BLENDED IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 12.

EVENER BAR BLENDED IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 13.

HANGER FITTING BLENDED IAW

SRM 54-70-90 REV 75 DTD 03/10/2022 ALLOWABLE DAMAGE 2 AND 5.

C/W AD 2011-18-10 DTD 11/07/2011.

*

*OVERHAULED IAW CMM ATA 71-21-37 REV: 47 DATE: 03/01/2022

*COMPLIED WITH A.D. 2011-18-10 DATE: 11/07/2011

*TSO: 0 CSO: 0

TECHNICIAN: Bradley Causer (esign) DATE: 03/10/2022

Supervisor: Larry Kline (esign)

DATE: 03/10/2022

Final Inspection: Leonardo Saldivar (esign)

DATE: 03/10/2022

