

1. Approving Civil Aviation  
Authority/Country  
FAA/United States

2.


## AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

176813

4. ORGANIZATION:  
Name and Address



Med-Craft, Inc.

2450 N.W. 110th Avenue  
Miami, Florida 33172  
Tel.: (305) 594-7444  
Fax: (305) 594-9080  
F.A.A. Repair Station N° LZ4R354M

5. Work Order / Contract /  
Invoice Number:

TM-T42817


6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1.	Twin Motor Actuator	53-0014	1	30105015	TESTED

12. Remarks: Work Order 176813 prescribing the actual work performed is attached. Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.4663.  
The work stated in Block 11 was accomplished IAW CMM 24-09-65 Rev Date: 07/16/18 Rev No: 7

13a. ~~Confirm the items identified above were manufactured in conformity to:~~  
\*\*\* ~~Approved design data and are in a condition for safe operation~~ \*\*\*  
\*\*\* ~~Not approved design data specified in Block 12~~ \*\*\*  
\*\*\*\*\*

14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulations specified in Block 12  
Certified that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature: \*\*\*\*\*  
13c. Approval/Authorization No.: \*\*\*\*\*

14b. Authorized Signature:  14c. Approval/Certificate Number: LZ4R354M

13d. Name (Typed or Printed): \*\*\*\*\*  
13e. Date (dd/mm/yyyy): \*\*\*\*\*

14d. Name (Typed or Printed): CARLOS SANCHEZ  
14e. Date (dd/mm/yyyy): 06 DEC 2023

### User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



# WORK ORDER

Work Order :176813  
Part Number :53-0014  
Serial Number :30105015  
ATA Number :24-09-65  
Service Req. :Test

Repair Order :TM-T42817  
Description :Twin Motor Actuat  
Manufacturer :Eaton  
Revision Date :07/16/18  
Date :11/28/23

**FAA REPAIR STATION LZ4R354M**

## PRELIMINARY VISUAL INSPECTION

VISUAL INSPECTION APPEARS NORMAL

## HIDDEN DAMAGE INSPECTION

N/A

Receiving Clerk: Giovanni Acosta

DATE: 11/28/2023

## CONDITION REPORTED

NONE

## REMARKS

NONE

## AD NOTES, Customer Specs

THERE ARE NO A.D. NOTES FOR THIS UNIT

Verified by: *Carls J. Lang*

DATE: 06 DEC 2023





# WORK ORDER

Work Order :176813  
Part Number :53-0014  
Serial Number :30105015  
ATA Number :24-09-65  
Service Req. :Test

Repair Order :TM-T42817  
Description :Twin Motor Actuat  
Manufacturer :Eaton  
Revision Date :07/16/18  
Date :11/28/23

## FAA REPAIR STATION LZ4R354M

### PRELIMINARY FUNCTIONAL TEST/TEARDOWN REPORT

1. Unit was inspected and functionally tested in accordance with the manufacturer's procedures.
2. Unit passed the functional test.
3. No discrepancies noted.

TECHNICIAN: Claudio Heredia

SUPERVISOR: 





# WORK ORDER

Work Order :176813  
Part Number :53-0014  
Serial Number :30105015  
ATA Number :24-09-65  
Service Req. :Test

Repair Order :TM-T42817  
Description :Twin Motor Actuat  
Manufacturer :Eaton  
Revision Date :07/16/18  
Date :11/28/23

## FAA REPAIR STATION LZ4R354M

### CORRECTIVE ACTION

1. Unit was tested in accordance with the specifications of ATA 24-09-65.
2. Unit passed final test.

Unit tested and certified for return to service.

Tech : Claudio Heredia

Spvsr : *Claudio Heredia*

Date : 06 DEC 2023

### SERVICE PERFORMED

Tested

### FINAL INSPECTION/RETURN TO SERVICE

Issued with respect to job performed as checked above.  
The component identified above was inspected in accordance with current regulations of the F.A.A. and is approved for return to service. Pertinent details of the repair are on file at this agency under

W.O.# 176813

Date

06 DEC 2023

Signed

*Carl Zang*