

| | | | | | | | |
|---|----------------|--|---------|---------------|-------------------|--|--|
| 1. Approving Competent Authority / Country: United Kingdom Civil Aviation Authority | | 2 AUTHORISED RELEASE CERTIFICATE EASA FORM 1 | | | | 3. Form Tracking Number: L 2787689 | |
| 4. Organization Name and Address: Panasonic | | Panasonic Avionics Corporation Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK | | | | 5. Work Order/Contract/Invoice R308928 | |
| 6. Item | 7. Description | 8. Part No. | 9. Qty. | 10. Serial No | 11. Status / Work | | |
| 1 | PCU | RD-AX6739-51 | 1 | D693703 | REPAIRED | | |
| 12. Remarks PLEASE REFER TO SR NUMBER 4602442. | | | | | | | |

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X.
Panasonic Avionics Corporation internal reference **SR4602442**

| | | | |
|---|------------------------------------|---|--|
| 13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in a condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 12. | | 14a. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service. | |
| 13b. Authorised Signature: | 13c. Approval/Authorization Number | 14b. Authorized Signature: | 14c. Certificate/Approval Ref No: UK.145.00297 |
| 13d. Name | 13e. Date (dd mmm yyyy) | 14d. Name Kalwinder Dogra | 14e. Date (dd mmm yyyy) 17-JAN-2017 |

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

**Panasonic Avionics Corporation**Quadrant House, Heron Drive, Parlaunt Road,
Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

REPAIR REPORT / DELIVERY ORDERSOLD TO **AJ WALTER AVIATION**
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GBSHIP TO **AJ WALTER AVIATION**
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

PAGE 1 of 1

SHIP TRANSACTION:

| | | | | | | |
|--|--|-----------------------------------|--------------------------------------|------------------------------------|-------------------------------------|-------------------------------------|
| CUSTOMER P.O. NUMBER R308928 | | CUSTOMER 1001 | TAIL NO. P4-YAS | CUST PROD REF 5826692 | SERVICE REQUEST 4602442 | |
| PART NUMBER RD-AX6739-51 | | NOMENCLATURE PCU | | | DATE REMOVED | DATE RECEIVED 30-DEC-2016 |
| SERIAL NUMBER D693703 | | DATE OF MFG 31-DEC-2007 | WTY START DATE 14-JAN-2008 | WTY END DATE 13-JAN-2011 | DATE REPAIRED 13-JAN-2017 | SHIP DATE |
| MOD IN 1.2 | | | | | | |
| REASON FOR CUSTOMER REJECTION | PCU SEAT 11A INOP. BROKEN PIN INSIDE. | | | | | |
| INTERNAL INSPECTION | No Physical Damage - DIRTY. | | | | | |
| EXTERNAL INSPECTION | Physical Damage - DIRTY. MINOR SCRATCHES ON FRONT COVER & BACK COVER NO ACTION TAKEN - PIN STUCK INSIDE JACK SOCKETS - | | | | | |
| ACTUAL FAILURE / CORRECTIVE ACTION | CUSTOMER COMPLAINT CONFIRMED REPLACED JACK SOCKETS - UNIT CLEANED , TESTED AND PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-35-71 REV 45 DTD MAY 2016. | | | | | |

MOD OUT: **1.2**INSPECTED BY: **Kalwinder Dogra**REPAIRED BY: **Patel, Ashokkumar Raojibhai**

| PART NUMBER | DESCRIPTION | QTY | UNIT PRICE | EXTENDED PRICE | CHARGED AMOUNT | WTY* |
|-------------|------------------------|-----|------------|----------------|----------------|------|
| CUST LABOR | OUT OF WARRANTY CHARGE | 105 | 2.33 | 244.65 | | |
| R5J1D23ZA | JACK | 1 | 8.51 | 8.51 | 8.51 | |
| R5J1D24ZA | JACK | 1 | 8.95 | 8.95 | 8.95 | |

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Cost of Material

13.46

Total Cost

223.46