

1. Approving Competent Aviation Authority / Country:  
United Kingdom  
Civil Aviation Authority

2 **AUTHORISED RELEASE CERTIFICATE**  
**EASA FORM 1**

3. Form Tracking Number:  
**L 2285432**

4. Organisation Name and Address:

**Panasonic**

**Panasonic Avionics Corporation**  
Quadrant House, Heron Drive, Parlant Road, Langley Berks, SL3 8XP, UK

5. Work Order/Contract/Invoice  
R241492

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
1	9-IN LCD CEILING MOUNT INST	RD-AA902125-01	1	100551	REPAIRED
12. Remarks INNER UNIT RD-AV9811-01 S.N. 100551 CONFORMED IAW CMM 23-32-58 REV 26 DTD JUL 2014. LRU CONFORMED IAW CMM 23-09-90 REV 13 DTD DEC 2007.					

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X.  
Panasonic Avionics Corporation internal reference SR 3686994

13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are fit for operation <input checked="" type="checkbox"/> non-approved design data specified in block 12		14a. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature:	14c. Certificate/Approval reference No: <b>UK.145.00297</b>
13d. Name	13e. Date (dd mm yy)	14d. Name Mick White	14e. Date (dd mm yy) 09-SEP-2014

**USER/INSTALLER RESPONSIBILITIES**

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.





## Panasonic Avionics Corporation

Quadrant House, Heron Drive, Parlaunt Road,  
Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

## REPAIR REPORT / DELIVERY ORDER

SOLD TO AJ WALTER AVIATION  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SINFOLD, ENGLAND RH13 0AS, GBSHIP TO AJ WALTER AVIATION  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SINFOLD, ENGLAND RH13 0AS, GB

PAGE 1 of 1

## SHIP TRANSACTION:



CUSTOMER P.O. NUMBER <b>R241492</b>		CUSTOMER <b>1001</b>	TAIL NO. <b>NOT GIVEN</b>	CUST PROD REF <b>282179</b>	SERVICE REQUEST <b>3686994</b>	
PART NUMBER <b>RD-AA902125-01</b>		NOMENCLATURE <b>9-IN LCD CEILING MOUNT INSTL</b>			DATE REMOVED	DATE RECEIVED <b>30-JUL-2014</b>
SERIAL NUMBER <b>100551</b>		DATE OF MFG <b>30-SEP-1999</b>	WTY START DATE <b>30-SEP-1999</b>	WTY END DATE <b>30-DEC-2002</b>	DATE REPAIRED <b>09-SEP-2014</b>	SHIP DATE
MOD IN <b>1-4</b>						
REASON FOR CUSTOMER REJECTION	<b>DEFECT CONNECTOR DAMAGED</b>					
INTERNAL INSPECTION	<b>Physical Damage - DIRTY; 2 MISSING SCREWS; 1 MISSING WASHER; MONITOR STOPPER DEFORMED; FLEXI FIXING TAPES FAILING</b>					
EXTERNAL INSPECTION	<b>Physical Damage - DIRTY; 1 SHEARED LATCH ASSY; P/N ON IDENT LABEL INCORRECT.</b>					
ACTUAL FAILURE / CORRECTIVE ACTION	<b>CUSTOMER COMPLAINT CONFIRMED. REPLACED OUTER UNIT IDENT LABEL. BACKLIGHT FADING; REPLACED. REPLACED 2 O/C BULBS IN NS/FSB SIGN. REPLACED LATCH ASSY, FLEXI FIXING TAPES, SCREWS, WASHER AND MONITOR STOPPER. MEC ASSY CLUTCH WEARING OUT; MEC ASSY REPLACED. MOD 8 ON INNER UNIT MOD 5 ON OUTER UNIT PREVIOUSLY EMBODIED; MOD 5 MARKED ON OUTER UNIT. UNIT CLEANED AND TESTED, PASSED FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-09-90 REV 13 DTD DEC 2007.</b>					

MOD OUT: 1-5

INSPECTED BY: Mick White

REPAIRED BY: Norton-Child, Ian

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR	OUT OF WARRANTY CHARGE	420	1.92	805.00	805.00	
417N3180-1	LATCH ASSY	1	164.61	164.61	164.61	NO
R8KAV981101A	MECHANISM	1	2,354.13	2,354.13	2,354.13	NO
R8K8V980901	BACK LIGHT	1	599.36	599.36	599.36	NO
R6HR75A	CABLE TIE	8	0.48	3.84	3.84	NO
R6HR132ZA	SHEET, POLYIMIDE	1	1.27	1.27	1.27	NO
R6HR197YA	SHEET, POLYIMIDE	1	1.79	1.79	1.79	NO
R6MX2A	WASHER, EPOXY RESIN	1	1.14	1.14	1.14	NO
R6XSS28P8	TERMINAL SCREW, STEEL	2	0.50	1.00	1.00	NO
R6HM775ZA	STOPPER	1	4.21	4.21	4.21	NO
7387	BULB	2	10.16	20.32	20.32	NO

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

\* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty  
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Cost of Labor	805.00
Cost of Material	3,151.67
Total Cost	3,956.67

<b>1. ATA SPEC 106 MATERIAL CERTIFICATION FORM</b>						
2. Seller's Name: <div style="text-align: center;">A J Walter Aviation Ltd</div>					3. EX ESN <div style="text-align: center;">559660</div>	
4. Organization: A J Walter Aviation Ltd  Address: The Headquarters Maydwell Avenue West Sussex Slinfold, United Kingdom RH13 0AS			Phone#: +44 (0) 1403 711 777 Fax#: +44 (0) 1403 710 936 SITA/Wire Code: LGWJWCR Status: Distributor / Stockist Certificate Type and #: EASA F1 + FAR STATEMENT			
5A. Seller's Contract #: 585184			5B. Buyer's PO #: PX0297815			
6. Item	7. Description	8. Manufacturer & Part Number	9. Eligibility	10. Qty	11. Serial/Batch #	12. Status
1	VIDEO MONITOR 9"	RD-AA902125-01 None Specified	B757	1	SN: 100551	REP
13A. Remarks:						
TSN: _____ CSN: _____ (applicable for LLP's)						
The supplied part(s) have not been subjected to severe stress or heat (as in major engine failure, accident or fire) and was (were) not obtained from any US Government or Military Source unless so stated.						
13B. Obtained From: GERMANIA FLUGGESELLSCHAFT PBH			13C. Last Certificated Agency: PANASONIC AVIONICS CORPORATION			
14. New Parts/Material Verification <small>THE FOLLOWING SIGNATURE ATTESTS THAT THE PART(S) OR MATERIAL(S) IDENTIFIED ABOVE WAS (WERE) MANUFACTURED BY A FAA PRODUCTION APPROVAL HOLDER (PAH), OR TO AN INDUSTRY COMMERCIAL STANDARD.</small>			18. Used, Repaired or Overhaul Parts Verification: <small>THE FOLLOWING SIGNATURE ATTESTS THAT THE DOCUMENTATION SPECIFIED ABOVE OR ATTACHED IS ACCURATE WITH REGARD TO THE ITEM(S) DESCRIBED.</small>			
15. Signature			19. Signature			
16. Name			20. Name			
17. Date 03/05/2015			21. Date 03/05/2015			

NOTICE: The above signature binds the seller and the SIGNER to the accuracy of the information provided in the FORM. Should the information provided in this Form contain inaccuracies or misrepresentations, the signer and SELLER may be liable for damages and be subject to criminal prosecution under state and federal law. AJW039/1