

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: CWO13814	
4. Organization Name and Address: VSE Aviation Services, Inc. 3000 Kustom Dr, Hebron, KY 41048, Fax: 859/283-0509, 859/283-2264				5. Work Order/Contract/Invoice Number: CWO13814 / R396425	
6. Item		7. Description:		8. Part Number:	9. Quantity:
1		CREW SEAT		3A258-0008-01-2	1.00
10. Serial Number:		11. Status/Work:		OVERHAULED	
12. Remarks: The component listed above was maintained in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair on the file at this repair station and are available upon request. This item was Overhauled I/A/W Manual # CMM 25-11-26, Revision # 36 Revision Date 8/17/2021					
EASA AD 2013-0020R4C1: RESTRAINT SYSTEM INSPECTED AND FOUND COMPLIANT					
VSE Aviation Services, Inc. certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval no. EASA.145.6132					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Authorized Signature:		13c. Approval Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: 	
				14c. Approval/Certificate No.: A8QR552Y	
				14d. Name (Typed or Printed): SHAYNE SCOTT	
				14e. Date (dd/mm/yyyy): 28-Jul-2022	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

WORK ORDER FORM 100



VSE Aviation Services, Inc.

3000 Kustom Dr
Hebron, KY 41048
Fax: 859/238-0509
859/283-2264

FAA CRS No: A8QR552Y

Work Order #: CWO13814

Step: SH-SHIPPING Department: Shop CVG Location: CVG INS

Customer: AJW001 / AJ WALTER AVIATION

Cust RO#: R396425

Warranty Code: 00

Goodthru AD#:

Mfg: IPECO

Outgoing: 3A258-0008-01-2 / CREW SEAT

S/N: 98097

Incoming P/N: 3A258-0008-01-2

Incoming S/N: 98097

Incoming work Req: OVERHAUL

Outgoing Work Req: OVERHAULED

Repair Manuals: C0652

RevDate: 8/17/2021

Rev#: 36

ATA: 25-11-26

Tools:

REASON FOR REMOVAL:

Date Recvd: 6/21/2022

Date Reqrd 6/22/2022

Date Estmtd: 6/22/2022

NO REMOVAL REASON ON RO-IRAN

Container:

PRELIMINARY INSPECTION:

DATE: 7/11/2022

INSPECTOR: ANM 1128

VERIFIED PN & SN

PRE TEST (Yes/No): Y

DATE: 7/11/2022

INSPECTOR: ANM 1128

PRETEST PASSED

HIDDEN DAMAGE:

NA

TEARDOWN FINDINGS:

FOUND SHOULDER STRAP FRAYED. LAP BELT TAG ILLEGIBLE. CROTCH BELT TAGE ILLEGIBLE. SEAT PAN COVER WO
RN. BACK COVER WORN. REPLACE DOME NUTS FOR ACTUATOR AND CIRCLIP FOR PINION.

TECHNICIAN: WKF 1419

Date: 7/11/2022

INSPECTOR: ANM 1128

FINAL INSPECTION BEFORE ASSEMBLY DATE: 07/28/22

INSPECTOR: ANM 1128

CHECK GOOD

CORRECTIVE ACTION:

UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, DEFECTIVE PARTS REPLACED, REASSEMBLED, TESTED AND FOU
ND TO BE SERVICABLE IN ACCORDANCE WITH MANUFACTURER SPECIFICATIONS.

EASA AD 2013-0020R4C1: RESTRAINT SYSTEM INSPECTED AND FOUND COMPLIANT

TECHNICIAN: STK 1384

Date: 07/28/22

INSPECTOR: SRS 1183

MODIFICATION/SERVICE BULLETINS:

NONE

TEST DATA USED:

CMM 25-11-26

Test Technician: STK 1384

Date: 07/28/22

Final Inspection: SRS 1183

ADDITIONAL COMMENTS:

N/A

WORK ORDER FORM 100

VSE Aviation Services, Inc.

3000 Kustom Dr
Hebron, KY 41048
Fax: 859/238-0509
859/283-2264

FAA CRS No: A8QR552Y

Work Order #: CWO13814

Step: SH-SHIPPING Department: Shop CVG Location: CVG INS

Customer: AJW001 / AJ WALTER AVIATION

Cust RO#: R396425

Warranty Code: 00

Goodthru AD#:

Mfg: IPECO

Outgoing: 3A258-0008-01-2 / CREW SEAT

S/N: 98097

Incoming P/N: 3A258-0008-01-2

Incoming S/N: 98097

Incoming work Req: OVERHAUL

Outgoing Work Req: OVERHAULED

PARTS DETAIL:

<u>Part Number/Description</u>	<u>W</u>	<u>CD</u>	<u>RmvCde</u>	<u>Qty</u>	<u>Serial Number</u>
0A254-0212HN SEAT BOTTOM COVER	N	NE		1	
1A254-0215HN SEAT BACK COVER	N	NE		1	
5000-20302A2396 LAP BELT HALF	N	RP		1	
5000-20502A2396 CROTCH STRAP	N	RP		1	
5000-23502A2396 STRAP	N	NE		2	
M1800-0050A CIRCLIP ANDERTON	N	NE		1	
M1800-0090A CIRCLIP EXT. ANDERTON	N	NE		1	
MS51865-6 DOME HD CAP LOCKING N	N	NE		4	

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS OVERHAULED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by SHAYNE SCOTT

Date: 7/28/2022 9:15:52 AM