



1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 20220010815564Y15 344021454	
4. Organization Name and Address: Honeywell International Inc. 23500 W 105th Street Olathe KS 66061		Repair Station PR2R093L		5. Work Order/Contract/Invoice Number: R392860 343964248 Page 1 of 1	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
001	INTEGRATED NAVIGATION RECEIVER FOR BOEIN	940-2001-004	1	INR-00709	REPAIRED
12. Remarks: THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 34-53-37 Rev 8, AUG/30/2019 TSI:12169 CSI:1578 THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER GENERATED SIGNATURE PROCEDURE MODS: NONE SW VERS: NA					
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4140					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval/Authorization No.:		14c. Approval/Certificate No.: PR2R093L	
13d. Name (Typed or Printed):		13e. Date(dd/mm/yyyy):		14d. Name (Typed or Printed): Fatima Durant	
				14e. Date(dd/mm/yyyy): 02/MAY/2022	
User / Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



1. 国家 Country	2. 中国民用航空总局 CAAC	☐ 符合性 Conformity	☒ 适航性 Airworthiness	3. 证书编号 20220010815566Y05 344021454	Certificate Ref. No.	
中国 China	批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG					
4. 单位 Organization	Honeywell International Inc. 23500 W 105th Street Olathe KS 66061				5. 工作单/合同单/货单 Work Order/Contract/Invoice R392860 343964248 Page 1 of 1	
6. 序号 Item	7. 内容 Description	8. 件号 Part No.	9. 适用性 Eligibility	10. 数量 Qty	11. 系列号/批号 Serial/Batch No.	12. 产品状态 Status/Work
001	INTEGRATED NAVIGATION RECEIVER FOR BOEIN	940-2001-004	NOT KNOWN	1	INR-00709	REPAIRED
13 备注 Remarks THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 34-53-37 Rev 8, AUG/30/2019 TSI:12169 CSI:1578 THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER GENERATED SIGNATURE PROCEDURE MODS: NONE SW MODS: NONE SW VERS: NA						
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED						
14. 新产品 New Parts		15. 使用过的产品 Used Parts				
兹声明上述产品除第13项的其它规定以外， 已按照上述国家适航条例进行制造/检查， 并且该产品(出口产品)符合经批准的型号设计和进口国提出的专用要求。 Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and / or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		兹声明上述产品除第13项的其它规定以外， 已按照上述国家适航条例和进口国通知的特殊要求进行了工作， 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is(are) in condition for safe operation and considered ready for release to service. (over)				
16. 批准人签名 Signature <i>Fatima Durant</i>		18. 批准日期 Date MAY/02/2022				
17. 批准人姓名 (打印的) Name (Printed) Fatima Durant		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100519				

* 参阅产品目录详细查找适用性

Cross - check eligibility for more details with parts catalogue

AAC - 038(12/94)

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5016380551		344021454	FAA: PR2R093L	EASA: EASA.145.4140
PO: R392860	CUSTOMER PART NUMBER:		CONTRACT NUMBER: 440115439	
DATE REJECTED: 11 MAR 2022	DATE RECEIVED: 17 MAR 2022		DATE COMPLETED: 02 MAY 2022	
A/C TYPE: BOEING 787-8	A/C TAIL NUMBER: JA841J		A/C SERIAL NUMBER: 34855	
PACKING STATUS: No	SEALS INTACT: Intact		PHYSICAL DAMAGE: No	
REASON FOR REMOVAL: Capt vor I flag appeared on nd indicator				
PART NUMBER	AS RECEIVED: 940-2001-004	AS RELEASED: 940-2001-004		
DESCRIPTION:	INTEGRATED NAVIGATION RECEIVER FOR		INTEGRATED NAVIGATION RECEIVER FOR	
SERIAL NUMBER	INR-00709	INR-00709		
UID(MFR/SPL PNO SER/UCN)	97896 INR-00709	97896 INR-00709		
HW MOD STATUS:	None	None		
SW MOD STATUS:	None	None		
SOFTWARE LOAD:	NA	NA		
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed		ESTIMATE SUPPLIED: Yes		
PRIMARY SHOP FINDING: Hardware Fault Found		WARRANTY: Warranty Denied		
TYPE OF SERVICE: REPAIRED		TECHNICIAN: Bryan Morris		
MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.				
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____				
SIGNATURE OF AUTHORIZED PERSON: _____				
Complied With CMM/Eng Documentation: 34-53-37/Rev 8/Rev Date 30 AUG 2019; Service Bulletins: Customer Manuals/Documentation:				
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.				

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5016380551		FAA: PR2R093L	EASA: EASA.145.4140
PO: R392860	CUSTOMER PART NUMBER:	CONTRACT NUMBER: 440115439	

Previously Complied With
CMM/Eng Documentation:
Service Bulletins:
Customer Manuals/Documentation:

Evaluation Findings
FC 68, 84, 85 logged in BITE memory
Repair actions:
-Will need a new main GNSS to correct all faults and failures

Work performed / Comments to Customer
Replaced main GNSS card and thermal pads.

Unit passes final test and recertified for service.

This component is airworthy with respect to work preformed. Test equipment calibration dates checked and final tested by Bryan Morris April 30, 2022.

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
Replace		205-00948-3302	SF33190005	205-00948-3302	03312022BM	1		
Replace		405-0510-003		405-0510-003		4		
Replace		405-0510-002		405-0510-002		1		
Replace		405-0510-001		405-0510-001		1		