Approving Civil Aviation Authority/Country:		AUTHORIZED RELEASE CERTIFICATE				3. Form Tracking Number	720202	
FAA/U	NITED STATES	,	FAA FORM 8130-3, All	RWORTHINES	S APPROVAL TAG			
Accesso	nization Name and Addres ry Technologies Corp air Station Certificate	oration,	41 Mercedes Way U			5. Work Order, Contract, Number:	T36372	
6. Item:	7. Description:	8.	Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
1	ACTUATOR, ROTARY		692D100-15	1	4778B		REPAIRED	
12. REMA Item depi Manufact Modificati	cted in blocks 6 through urer Name <u>EATON</u> , Ov	n 10 has verhaul N	been serviced as ind Manual Report Numbe	icated in block er <u>52-34-02</u> Re	11, in accordance with vision <u>16,</u> Dated <u>07/26</u>	n the following FAA approve 119, Service Bulletin(s) and/	d data: or 2	
	COMPLIANCE WITH A				2-4.		2	
accorda	ory Technologies C ance with EASA Par ce under EASA Acc	t 145 a	nd with respect to	that work, to	ne aircraπ compone 5.4014.	and 12 was performed ent is considered ready	TOT Telease	
☐ Approv	ies the items identified above yed design data and are in oproved design data speci	a conditi	on for safe operation.	Certifies the code of F	nat unless otherwise spec	vice Other regulation specified in Block 12, the work ide s accomplished in accordance 43 and in respect to that work	entified in Block	
13b. Auth	orized Signature:	13c. No:	Approval Authorization	14b. Auth	14b. Authorized Signature:		ertificate No:	
13d. Nam	ne (Typed or Printed):	13e.	Date (dd/mmm/yyyy):	14d. Nam	ne (Typed or Printed):	14e. Date (dd/n	nmm/yyyy):	
					Raheel Khan		02/MAR/2022	
	<u>4174,000,000,400,400,000,000,000</u>		User/Ins	taller Respo	onsibilities			
It is impor	tank to understand that the	existenc	e of this Document alone	e does not autor	natically constitute authori	ity to install the part/component	t/assembly.	
Where the		ork in accessentia	cordance with the nation I that the user/installer e	al regulations of	f an airworthiness authorit	y different than the airworthine y accepts parts/components/as	ss authority of	
Statemen	ts in Blocks 13a and 14 on issued in accordance w	a do not th the na	constitute installation of tional regulation by the u	certification. In ser/installer bef	all cases, aircraft maint ore the aircraft may be flo	tenance records must contain wn.	an installation	
	8130-3 (02-14)	-					2-00-012-9005	

ACCESSORY TECHNOLOGIES AVENCOR GROUP COMPANY ACCESSORY TECHNOLOGIES Corporation

http://www.atcny.com 4 FAA CRS: Y4AR0390 EASA: 145.4014

Accessory Technologies Corporation
41 Mercedes Way Unit #34 Edgewood, NY 11717
4 631-753-2282 (Phone) 631-753-2407 (Fax)

Customer Service Report

Work Order #:

720202

Page: 1

CUSTOMER:	A J WALTER	(AVIATION	LTD
-----------	------------	-----------	-----

REF #: T36372

TAIL #: F-GSPS

ATA: 52-34-02

OEM: EATON

DESCR: ROTARY ACTUATOR - LARGE CARGO DOOR

The second second

P/N RECEIVED: **692D100-13** P/N SHIPPED: **692D100-15**

S/N: 4778B

OPEN DATE: 1/25/2022

WARRANTY No

CONTAINER: N/A

WORK REQUESTED: Repair

REASON FOR REMOVAL: Unknown.

CONFIRMED: Yes.

INCOMING INSPECTION: O.K. Externally

TEARDOWN INSPECTION: Disassembly reveals No Back assembly heavily contaminated. Minor repairs required. Compliance plate required. Unit in C/W SB 692D100-52-4

WORK PERFORMED: Partially disassembled Unit. Performed required inspections. Replaced all material as required. Reassembled and tested. All work performed I/A/W the latest Eaton CMM. O.K. to return to service.

PN	Description	Qty Issued	CD	
999803-02	PLATE COMPLIANCE	1.00	NE	

AUTHORIZED	SIG	NATU	RE:

NOTE: Unit serviced in accordance with AD: 2015-12-11.

DATE:

Mar/02/2022

Form ATC-002

Rev 2 12/14/20