


AOG Reaction

526 Aviator Drive
Fort Worth, TX 76179-5425

F.A.A. REPAIR STATION TU1R519K

(817) 439-0700

FAX (817) 439-9700

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 140247	
4. Organization Name and Address: AOG Reaction, Inc. 526 Aviator Drive, Fort Worth, TX 76179 (TU1R519K)						5. Work Order/Contract/Invoice Number: W.O.# 140247	
6. Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	Rotary Switch Lucas Ledex	172938-001	N/A	1	7047	TESTED	
13. Remarks: TESTED in accordance with DWG 172938-001, REV 6, dated Oct 23 1995 MEETS OEM SPECIFICATIONS See Teardown/Analysis Report for further details and back side of form for User/Installer Responsibilities statements Certifies that the work specified in Blocks 12/13 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.4164.							
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work the items are approved for return to service.			
15. Authorized Signature: N/A		16. Approval/Authorization No: N/A		20. Authorized Signature: 		21. Approval/Certificate No: TU1R519K	
17. Name (Typed or Printed): N/A		18. Date (m d y): N/A		22. Name (Typed or Printed): Edward Roberts		23. Date (m d y): Apr 11 2011	

FAA Form 8130-3 (6-01)

* Installer must cross-check eligibility with applicable technical data

NSN 0052-00-012-9005

TEARDOWN/ANALYSIS REPORT

Customer: AJ Walter Aviation

Customer Agent: Repairs-AJ Walter

Part Number: 172938-001

Part Nomenclature: Rotary Switch

Manufacturer: Lucas Ledex

Removed From: AJ WALTER AVIATION STOCK

Time on Part: NTC

Defect Reported: AIRWORTHINESS INSPECTION

Defect Confirmed?: N/A

AD Notes, Service Bulletins Applicable: None

Shop Inspection/Test Findings: TESTED OK. NO DEFECTS NOTED

Work Accomplished: TESTED in accordance with DWG 172938-001, REV 6, dated Oct 23 1995
MEETS OEM SPECIFICATIONS

Customer's RO: 149563

Date received: Apr/01/2011

Serial number: 7047

AOG Reaction, Inc
FAA Repair Station - TU1R519K
526 Aviator Drive
Fort Worth, TX 76179-5425
(817) 439-0700

Teardown/Analysis Report

Work Order 140247

Customer AJ Walter Aviation
Customer's Agent Repairs-AJ Walter

Customer's RO Number: 149563

Date Received: 4/1/2011

Part Number 172938-001 Serial number 7047

Nomenclature Rotary Switch

Manufacturer Lucas Ledex

Removed From AJ WALTER AVIATION STOCK

Time On Unit NTC

Defect Reported AIRWORTHINESS INSPECTION

Defect Confirmed? N/A

Shop Inspection Findings: TESTED OK. NO DEFECTS NOTED

Work Accomplished: TESTED PER 172938-001 REV 10/23/1995

MEETS OEM SPECIFICATIONS

Work Performed By:

Bill Foreman

4/11/2011

Edward Roberts

4/11/2011

Technician

Date

Inspector

Date