

1. Approving Competent Authority / Country: United Kingdom Civil Aviation Authority		2		AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. Form Tracking Number: L 3116043	
4. Organization Name and Address: Panasonic		Panasonic Avionics Corporation Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK					5. Work Order/Contract/Invoice R337853	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No	11. Status / Work			
1	SOLID STATE WALL MOUNT PRAM	RD-AX7360-01	1	E495173	REPAIRED			
12. Remarks ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-31-18 REV 24 DTD JAN 2018. PLEASE REFER TO SR NUMBER 5071984.								
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X. In accordance with TCCA Approval 808-03. Panasonic Avionics Corporation internal reference SR5071984								
13a. Certifies the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation. ☐ non-approved design data specified in block 12.								
13b. Authorised Signature:		13c. Approval/Authorization Number		14a. ☒ PART 145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		14c. Certificate/Approval Ref No: UK.145.00297		
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorized Signature: 		14e. Date (dd mmm yyyy) 09-MAY-2018		
USER/INSTALLER RESPONSIBILITIES								
This certificate does not automatically constitute authority to install the item(s).								
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.								
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.								

Panasonic

Panasonic Avionics CorporationQuadrant House, Heron Drive, Parlaunt Road,
Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

REPAIR REPORT / DELIVERY ORDERSOLD TO **AJ WALTER AVIATION**
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GBSHIP TO **AJ WALTER AVIATION**
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, ENGLAND RH13 0AS, GB

PAGE 1 of 1

SHIP TRANSACTION:

CUSTOMER P.O. NUMBER R337853		CUSTOMER 1001	TAIL NO. DQ-FJM	CUST PROD REF 16410776	SERVICE REQUEST 5071984
PART NUMBER RD-AX7360-01		NOMENCLATURE SOLID STATE WALL MOUNT PRAM			DATE REMOVED
SERIAL NUMBER E495173		DATE OF MFG 30-APR-2010	WTY START DATE 22-APR-2010	WTY END DATE 21-APR-2014	DATE RECEIVED 12-APR-2018
MOD IN 1-12		DATE REPAIRED 08-MAY-2018			SHIP DATE
REASON FOR CUSTOMER REJECTION	INOP.				
INTERNAL INSPECTION	No Physical Damage - DIRTY. PINS MISSING ON INTERFACE A CARD ASSEMBLY,				
EXTERNAL INSPECTION	No Physical Damage - DIRTY. MINOR MARKS ON COVER, NO ACTION TAKEN. .				
ACTUAL FAILURE / CORRECTIVE ACTION	UNIT FAILED ON TEST, ERRORS ON INTERNAL FLASH CARD. REPORTED FAILURE CONFIRMED. REPLACED CPU CARD ASSEMBLY. FORMTTING OF FLASH CARD. RE - TEST UNIT FAILED TO DOWNLOADING TEST FLASH CARD FILES. REPLACED INTERFACE A CARD ASSEMBLY. EMBODIED MOD 13. UNIT CLEANED AND TESTED PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-31-18 REV 24 DTD JAN 2018.				

MOD OUT: 1-13

INSPECTED BY: **Junior Welsh**REPAIRED BY: **Adom, David E.**

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR	OUT OF WARRANTY CHARGE	390				
R8U3X7360ZAA	PC BOARD W/COMPONENT	1				NO
R7AKE3494	SILICON GLUE	0				NO
R6HR937ZA	SHEET,POLYIMIDE	2				NO
R8U2AX7360ZD	PC BOARD W/COMPONENT	1				NO

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Cost of Labor
Cost of Material
Total Cost