




1. Approving Civil Aviation Authority/Country: FAA/United States	2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	3. Form Tracking Number: 20190007138177Y15 337383352
4. Organization Name and Address: Honeywell International Inc 8840 Evergreen Blvd. COON RAPIDS MN 55433-6040	Repair Station KE2R949K	5. Work Order/Contract/Invoice Number: 9447613 337379036 Page 1 of 1
6. Item: 7. Description:	8. Part Number:	9. Quantity:
001 MODAL SUPPRESSION ACCEL - ASSEMBLY AND I	HG2280AB01	1
10. Serial Number:	11. Status / Work:	
56055327	REPAIRED	

12. Remarks:

THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH:
CMM 27-20-03 Rev 5, JAN/31/2019
COMPLY WITH SPOC 008

SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED

CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4538

13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.	14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
13b. Authorized Signature:	14b. Authorized Signature: 
13c. Approval/Authorization No.:	14c. Approval/Certificate No.: KE2R949K
13d. Name (Typed or Printed):	14d. Name (Typed or Printed): Mai Tran
13e. Date(dd/mm/yyyy):	14e. Date(dd/mm/yyyy): 24/SEP/2019

User / Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA FORM 8130 - 3 (02-14)

NSN : 0052 - 00 - 012 - 9005



1. 国家 Country	2. 中国民用航空总局 CAAC	☐ 符合性	☒ 适航性	Conformity	Airworthiness	3. 证书编号 20190007138176Y05 337383352	Certificate Ref. No.
中国 China	批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG						
4. 单位 Organization	Honeywell International Inc 8840 Evergreen Blvd. COON RAPIDS MN 55433-6040						5. 工作单/合同单/货单 Work Order/Contract/Invoice 9447613 337379036 Page 1 of 1
6. 序号 Item	7. 内容 Description	8. 件号 Part No.	9. 适用性 Eligibility	10. 数量 Qty	11. 系列号/批号 Serial/Batch No.	12. 产品状态 Status/Work	
001	MODAL SUPPRESSION ACCEL - ASSEMBLY AND I	HG2280AB01	NOT KNOWN	1	56055327	REPAIRED	
13 备注 Remarks THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 27-20-03 Rev 5, JAN/31/2019 COMPLY WITH SPOC 008							
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED							
14. 新产品 New Parts		15. 使用过的产品 Used Parts					
兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例进行制造/检查，并且该产品(出口产品)符合经批准的设计资料和进口国提出的专用要求。 Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例和进口国通知的特殊要求进行了工作，该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is(are) in condition for safe operation and considered ready for release to service. (over)					
16. 批准人签名 Signature		18. 批准日期 Date		19. 中国民航总局授权 Issued by or on behalf of the CAAC			
		SEP/24/2019		F00100463			
17. 批准人姓名 (打印的) Name (Printed)		Mai Tran					

SERVICE REPORT

HAT - Phoenix

SR NUMBER: 5014107199 337383352		FAA: KE2R949K	EASA: 145.4538
PO: 9447613	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	
DATE REJECTED: 13 SEP 2019	DATE RECEIVED: 21 AUG 2019	DATE COMPLETED: 23 SEP 2019	
A/C TYPE: UNK	A/C TAIL NUMBER: UNK	A/C SERIAL NUMBER: UNK	
PACKING STATUS: No	SEALS INTACT: Intact	PHYSICAL DAMAGE: No	

REASON FOR REMOVAL:
THIS IS ZRIT INTERNAL REPAIR ORDER # REPAIR & RELEASE WITH FAA & EASA & CAAC RELEASE TAG & REPAIR REPORT. Customer requirement: Blocked 12 must be repaired tag COMPLY WITH SPOC008 Note: NO conversion/exchange prior to Maureen Koh approval. CONTACT MAUREEN KOH FOR ANY QUESTIONS.

PART NUMBER	AS RECEIVED: HG2280AB01	AS RELEASED: HG2280AB01
DESCRIPTION:	MODAL SUPPRESSION ACCEL - ASSEMBLY	MODAL SUPPRESSION ACCEL - ASSEMBLY
SERIAL NUMBER	56055327	56055327
UID(MFR/SPL PNO SER/UCN)	65507 56055327	65507 56055327
HW MOD STATUS:	MOD 1	MOD 1
SW MOD STATUS:		
SOFTWARE LOAD:		
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed		ESTIMATE SUPPLIED: No
PRIMARY SHOP FINDING: Hardware Fault Found		WARRANTY:
TYPE OF SERVICE: REPAIRED		TECHNICIAN: Mao Nguyen

MAINTENANCE STATEMENT:
PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.
When work is performed in accordance with Honeywell engineering documentation this documentation is at a minimum equal to current distributed CMM.

SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____

SIGNATURE OF AUTHORIZED PERSON: _____

Complied With
CMM/Eng Documentation: 27-20-03/Rev 5/Rev Date 31 JAN 2019;
Service Bulletins:
Customer Manuals/Documentation:

SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.

SERVICE REPORT

HAT - Phoenix

SR NUMBER: 5014107199		FAA: KE2R949K	EASA: 145.4538
PO: 9447613	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	

Previously Complied With CMM/Eng Documentation: Service Bulletins: Customer Manuals/Documentation:																	
Evaluation Findings 1) REPLACED THE ACCEL CCA WITH NEW DUE TO INCOMING ATP TEST FAILURE. 2) DEVICE PASSED CERTIFICATION TESTS.																	
Work performed / Comments to Customer 1) REPLACED THE ACCEL CCA WITH NEW DUE TO INCOMING ATP TEST FAILURE. 2) DEVICE PASSED CERTIFICATION TESTS.																	
DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB									
Replace	ACCEL CCA	26021119-104	74223994	26021119-104	73362061	1											
REPLACE THE ACCEL CCA WITH NEW DUE TO INCOMING TEST FAILURE.																	
<table border="1"> <tr> <th>MEASUREMENT DESCRIPTION</th> <th>MEAS. VALUE (DECIMAL)</th> <th>MEAS. VALUE (HH:MM)</th> </tr> <tr> <td>Time Since Repair</td> <td></td> <td>0:00</td> </tr> <tr> <td>Cycles Since Repair</td> <td></td> <td></td> </tr> </table>									MEASUREMENT DESCRIPTION	MEAS. VALUE (DECIMAL)	MEAS. VALUE (HH:MM)	Time Since Repair		0:00	Cycles Since Repair		
MEASUREMENT DESCRIPTION	MEAS. VALUE (DECIMAL)	MEAS. VALUE (HH:MM)															
Time Since Repair		0:00															
Cycles Since Repair																	