			The state of the s
Approving Civil Aviation     Authority/Country:	2. AUTHORIZED RELI	RELEASE CERTIFICATE	121792 CTLID 1
FAA/UNITED STATES		RTHINESS APPROVAL TAG	
4. Organization Name and Address:	BP Aero Services		<ol> <li>Work Order/Contract/Invoice</li> <li>Number:</li> </ol>
	1905 HANSON DR. LICA LICA		53781
34	USA Ph: 469-208-0060, Fax: 972-252-2009		
	FAA Approval Holder: 442R874B		Number of attached pages – 1
6. Item 7. Description:	8. Part Number:	9. Quantity: 10. Serial Number:	
$\neg$	336-098-601-0	1 N/A	OVERHAULED
12. Remarks: ATA: 72-09-03 E.S.N. 731266 Repair Order: ER016592 Customer: AJ Walter Aviation Ltd See Workscope Report: 53781	All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision  Also meets the inspection criteria of: CFM56-5A Manual ID: CFMI-TP-SM.7, Revision #: 65, Revision Date: 2/15/2019	All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision #: 75, Revision Date: 9/15/2019  Also meets the inspection criteria of: CFM56-5A Manual ID: CFMI-TP-SM.7, Revision #: 65, Revision Date: 2/15/2019	ate: 9/15/2019
Certificate Number: EASA, 145,6427	Certificate Number: EASA, 145,6427  13a. Certifies the items identified above were manufactured in conformity to:  14a. X 14 CFR 43.9 Return to Service X Other regulation specified in Blo	14a. X 14 CFR 43.9 Return to Service	X Other regulation specified in Block 12
Approved design data and are in a condition for Non-approved design data specified in Block 12	Approved design data and are in a condition for safe operation.    Non-approved design-data specified in Block 12	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to se	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
13b. Authorized Signature:	13c. Approval Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.: 442R874B
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mmm/yyyy):
		Faulo Larrazabal	27-Jan-2020
	User/Installer	User/Installer Responsibilities	
It is important to understand that the Where the user/installer performs wo	It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.  Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is the configuration of the country specified in Block 1.	istitute authority to install the aircraft engine/propiness authority different than the airworthiness are somethiness are somethiness are somethiness.	beller/article.  uthority of the country specified in Block 1. It is authority of the country specified in Block 1.
Statement in Blocks 13a and 14a do not constitute installation or regulations by the user/installer before the aircraft may be flown.	Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.	aintenance records must contain an installation	certification issued in accordance with the national

Name (Printed)	Olgliaturo	16 共產人総名	and/or in the case of pairs to the importing country.	品(出口产品)符合 Certifies that the part(s) manufactured/inspected	14 對方即New Parts	13 条注 Remarks ATA: 72-09-03 E.S.N. 731266 Repair Order: ERO16592 Customer: AJ Walter Aviati See Workscope Report: 53781	1 TUBE-OIL	Item	6 平市		4 単位	P.K. CHINA	The Cu	1国家 Country 2.
Paulo Larrazabal	3	18 批准日期 Date	the importing country.	品(出口产品)体合图共轭的建具设计资料产进口国路出的专用要求。 品(出口产品)体合图共轭的建具设计资料产进口国路出的专用要求。 Certifies that the part(s) identified above; except as otherwise specified in block 13 was (were) manufactured/inspected.in-accordance with the airworthiness regulations of the stated country manufactured/inspected.in-accordance with the approved design data and with the notified	等了。New Parts 转进程,采发有导推135户的其危机商以外,以按照上法国委员	on Ltd		Description	7 内容	IRVING, TX 75038 USA Tel: 972-252-2800, Fax:972-252-2009	BP Aero Services FAA Repair Station # 442R874B	AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS	批准	中国民用航空总局 CAAC
*** 住好品目 专注组督校语用年		集日期 Jan/27/2020			拉堡界进行制造 恰查,并且该产	All work performed in accordance with CFM56-5B Manual ID: CFM1-1P-3M.5, Nevision FAIso meets the inspection criteria of: CFM56-5A Manual ID: CFMI-TP-SM.7, Revision #: 65, Revision Date: 2/15/2019		336-098-601-0	8 件号 Part No.	2-2009	ō	ERTIFICATE/AIRWORTHIN	批准放行证书/适航批准标签	刊符合性 Conformity
4	F00100709	19 中国长机态图域以 Issued by or on beh	1000年1000年1000年100日	Certifies that the work sper accordance with the airwork requirements of the import for safe operation and con	15 使用过的产品 Used Parts 裁审明上按产品除棄13项的其它规定以外,已按照上注图3 进行了工作,该产品出于安全可用状态可以指准效行使用。	-M56-5B Manual I.7, Revision #: 6		CFM56-5B	9 适用性 Eligibility			AFFROYA		X 透別 E MINOR MEAN
		n behalf of the CAAC		cified above exc thiness regulati ing country and sidered ready fo	arts 原的其它规定以外 5安全可用状态可	wision Date: 2		1	10 變圖 Qty	7	σı <b>S</b>	ن ن ن		
		AC		Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in concordance operation and considered ready for release to service. (over)	, 口按照上述国家透凯条则和进口国通知的特殊基块以找 複数行使用,	/15/2019	#: 75 Revision Date: 9/15/2019	N	11 蒸烈号/数号 Serial/Batch No.	Number of attached pages	Work Order / Contract / IIIVorce 53781	工作单/合同单/资单	36690	Certificate Ref. No.
				rk specified above except as specified in block 13 was carried out in airworthiness regulations of the stated country and the notified special importing country and in respect to that work, the part(s) is (are) in condition and considered ready for release to service. (over)	6进口国语知的特殊要求		9/15/2019		Status/Work	1 1		T Project		



## Workscope Report

53781

Date Printed: 1/27/2020

Time: 4:18:56 PM

Page: 1

To:

AJ Walter Aviation Ltd THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM Ship To:

Repairs Group
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH13 0AS
UNITED KINGDOM

Ref #: ERO16592

Phone #: +44 1403 711 777

CFMI-TP-SM.9 CFM56-5B CFMI-TP-SM.7 CFM56-5A

Fax #: +44 1403 710 936

Email: stockmarket@ajw-aviation.com

Code: AJW

Site:

PN: 336-098-601-0

Descr: TUBE-OIL

Qty: 1

Station:

Make:

Model:

Mfg: CFMI

CMM/ESM:

ESN 731266

TSN CSN

Complies With

Entry Date: 1/21/2020

Need Date: 1/31/2020

Compl. Date: 1/27/2020 4:18:39 PM

Warranty: No

Serial Numbers:

Customer Workscope:

Customer requests O/H IAW ESM, CMM or AMM

Per Customer Purchase/Repair Order Work Scope Instructions.

Inspection Findings:

Visual / Dimensional Findings

Within Serviceable Limits

**Corrective Actions:** 

Overhauled - 8130 Issued

T. I. Description	Status	Seq	
Task Description	Complete	0	
RECEIVING INSPECTION	Complete	100	
CFM56-5B-ESM-TASK-72-09-03-100-801 - CLEANING	Complete	200	
CFM56-5B-ESM-TASK-72-09-03-200-001 - INSPECTION	100	249	
CFM56-5B-ESM-TASK-72-09-03-200-001 - PRESSURE TEST	Complete		
FINAL CLEANING AND CONDITIONING	Complete	800000	
	Complete	900000	
FINAL INSPECTION			

