Combined Inventory Receipt & Dispatch Check Sheet

THIS DOCUMENT MAY <u>ONLY</u> BE COMPLETED BY A PERSON THAT HAS RECEIVED TRAINING AND BEEN ISSUED WITH AN INSPECTORS STAMP



B&H Warehouse Reference	Job Number	Date Received
AW582758		12.10.2023

A visual inspection has been performed on this unit and the following information checked:

		RECEIPT			DISPATCH	
	Yes	No	N/A	Yes	No	N/i
EASA Form (8130) / Authorised Release Certificate	√					
Trace Documentation	V					
OEM Certification			•			
DG Declaration			•			
MSDS (Material Safety Data Sheet)			. •			
Shelf Life Applicable			•			
Material Certification / ATA 106			•			
US (unserviceable) Tag			•			
Reason for Removal Stated on Tag			•			
Packing Slip		·	•			
Original Certificates Returned			•			
Unused Statement			•			
Dhysical Charles to be consulated		RECEIPT			DISPATCH	
Physical Checks to be completed	Yes	No	N/A	 Yes	No	N/ı
Part Number on Unit Matches Paperwork	V					
Serial Number on Unit Matches Paperwork	V					
Description on Unit Matches Paperwork	$\overline{\hspace{1.5cm}}$					
All Paperwork carries the same part & serial number	7					
Blanks fitted to ALL ports	√					
FOD evident in ports / connectors			•			
Static Sensitive			•			
Warranty labels INTACT			•			
Following tasks MUST be completed on Receipt AND		RECEIPT			DISPATCH	
Dispatch	Yes	No	N/A	Yes	No	N/i
Interior packaging sufficient to secure unit and weight of unit						
Component wrapped in static sensitive bubble/pouch			•			
Exterior packing condition acceptable for weight of unit						
External Damage customer to inspect photo's			•			
Photos Taken – Package Exterior	$\overline{\mathbb{Z}}$					
Photos Taken – Item and packaging	<u> </u>					
Photos Taken – Component(s)						
Photos Taken – Data Plates and Connectors	<u> </u>					
FirstTrac Updated	<u> </u>					
Other (Specify)			•			
Customer advised / Pre alert sent			•			
Completed by (Trained Inspector Stamp)	<u> </u>					

UK-OPS-FM-29

Uncontrolled Document When Printed

THE TAPE

Version: 6-23/01/2023

12. Remarks The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under FAA certificate no. 05K/452Y. Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 33-42-06, Rev11 2nd May 2023. 13a. Certifies that the items identified above were manufactured in conformity-to: Approved design data and are in condition for safe operation Approved design data specified in block 12 Certifies that unless otherwise specified in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	6. Item 7. Description 8. Part No. 9. Qty. 10. Serial No.	1. Approving Competent Authority/Country CAA / United Kingdom 4. Organisation Name and Address CAA FORM 1 Oakenhurst Aircraft Services Ltd CAA FORM 1 Oakenhurst Aircraft Services Ltd Caa FORM 1
	10. Serial No	CERTIFICATE 1 Tel: +44 (0)1268741622 Email: sales@oakenhurst.com Veb: www.oakenhurst.com
the items are approved for return to service under FAA certificate no. O5KY452Y.	11. Status/Work	3. Form Tracking Number ARC108808 5. Work Order/Contract/Invoice WP91343 / R415867

al regulations by the use installer before the aircraft	cation issued in accordance with the nation	installation certific	. In all cases aircraft maintenance records must contain an i	Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the use installer before the aircraft may be flown.
block 1, it is essential that the user/installer ensures that his/her air-rorthiness authority accepts	n block 1, it is essential that the user/installe	thority specified ir	n airworthiness authority different than the airworthiness aut	Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in thems from the airworthiness authority specified in block 1.
			(6)	USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s).
05 Oct 2023	05	Luke Arnull	Luke	
14e. Date (dd mmr: yyyy)	14	14d. Name	13e. Date (dd mmm yyyy) 14d.	13d. Name 13e. Dal
EASA.UK.145.00524	AVW 41			
14c. Certificate/Approval Ref. No.	Signature 14	14b. Authorised	13c. Approval/Authorisation Number 14b.	13b. Authorised Signature
considered ready for release to service.	described in block 12, was accomplished in accordance when work the items are considered ready for release to service.	work the items are	work	☐ Non-approved design data specified in block 12
the work identified in block 11 and	Certifies that unless otherwise specified in block 12, the work identified in block 11 and	fies that unles	\ 	Approved design data and are in condition for safe operation
Other regulation specified in block 12	45.A.50 Release to Service	✓ Part-1	manufactured in conformity to: 14a.	13a. Certifies that the items identified above were manufactured in conformity to:
			nufacturers manual No. 33-42-06, Rev11 2nd May 2023.	12. Remarks Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 33-42-06, Rev11 2nd May 2023.
Repaired	11951	1	30-2481-5	1 Rear Position Nav Light
11. Status/Work	10. Serial No.	9. Qty.	8. Part No.	6. Item 7. Description
WP91343 / R415867	Email: sales@oakenhurst.com Web: www.oakenhurst.com	Email: Web:	Rayleigh, Essex SS6 7UP United Kingdom	OAKENHUR GT
5. Work Order/Contract/Invoice	Tel: +44 (0)1268741622		Oakenhurst Aircraft Services Ltd Claydons Lane	4. Organisation Name and Address
ARC108809		ORM 1	EASA FORM 1	EASA
3. Form Tracking Number	CERTIFICATE		AUTHORISED RELEASE	1. Approving Competent Authority/Country 2.



Oakenhurst Aircraft Services Ltd Claydons Lane Rayleigh, Essex SS6 7UP United Kingdom Tel: +44 (0)1268741622

EASA Part 145: EASA.UK.145.00524

Completion Report

CAA Part 145: UK.145.00524

No: WP91343 Issue: 04 Date: 05-Oct-23

AJW Aviation
The Headquarters
Maydwell Avenue
Slinfold
West Sussex
RH13 0AS
United Kingdom

Attn: Summer Smythe

Tel: 0044 (0) 1403 798000 Fax: E-Mail: summer.smythe@ajw-group.com

Your Ref: R415867 Our Ref: WP91343 Test Required: N/A Part No: 30-2481-5 **Description:** Rear Position Nav Light TSN: N/A CSN: N/A Workscope: FP&E-M Repair TSO: N/A CSO: N/A Serial No: 11951 DoM: 28-Mar-05 Overhauled: inspected: Serial No: Reg No: OY-JZO Position: Removed From:

Technical Reference: LIB01958 - Issue No: N/A - Rev No: 11

Inspection Findings:

Unit received in for repair with reported defect, lower light not illuminating, bench test carried out and reported defect confirmed. Unit disassembled as required for Inspection and found lamp holders internal contacts tarnished and in poor condition, replace lamp holder and lamps, lens has come away from housing and requires repair. Replace worn and defective parts, reseal, re-assembly and final test for release.

Replacement parts fitted to the unit, the unit was cleaned and final testing/checks carried out before release.

Completion Summary:

Signed:

Replacement parts fitted to the unit, the unit was cleaned and final testing/checks carried out before release.

Name:

For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP

L.ARNULL

Date: 05/0CT/2023