

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO146673	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: R415567	
6. Item 7. Description:		8. Part Number:		9. Quantity:	
1 SMOKE DETECTOR		473597-5		1.00	
10. Serial/Batch Number:		11. Status/Work:		REPAIRED	
8590					
12. REMARKS Repaired as per CMM 26-10-66 Rev. 14 Feb, 10/21. For additional information refer to tear down report.					
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Signature:		13c. Approved Organization Number		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12	
				14b. Signature 	
13d. Name (Typed or Printed):		13e. Date		14c. Approval Organization Number 33-12	
				14d. Name (Typed or Printed) Jacques Moisan	
				14e. Date (dd/mm/yyyy) 31/Aug/2023	
Installer Responsibilities					
This certificate does not constitute authority to install the part.					
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO146673

Date Printed: 8/31/2023

Customer RO: R415567

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: SMOKE DETECTOR

Phone:

P/N: 473597-5

Qty: 1

Email:

S/N: 8590

Mfg: KIDDE TECHNOLOGIES

TSN: UNK

TSO: UNK

TSR: UNK

CSN: UNK

CSO: UNK

CSR: UNK

P/N Out: 473597-5

S/N Out: 8590

Symptoms:

CODE: DEFECT

DETAILS: Fault light comes on when test switch is pushed.

Faults:

CODE: INITIAL TEST FAILURE

DETAILS: Initial test failure is attributed to unit out of calibration.

CODE: CLEANING

DETAILS: Cleaning is required due to unit contaminated.

CODE: REPAIR

DETAILS: The following repair(s) will be performed:

Unit to be calibrated per specs.

Unit to be cleaned.

Repaired as per CMM 26-10-66 Rev.14 Feb,10/21.

Corrective Actions:

CODE: REPAIRED

DETAILS: Unit calibrated per specs.

Unit cleaned.

Repaired as per CMM 26-10-66 Rev.14 Feb,10/21.