

1. Approving Competent Authority/Country FEDERAL OFFICE OF CIVIL AVIATION (FOCA) SWITZERLAND		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 86714396-10300	
4. Organisation Name and Address Meggitt SA Route de Moncor 4, CH-1752 Villars-sur-Glâne, Switzerland Phone: +41 (0)26 407 11 11 Fax: +41 (0)26 407 18 60				5. Work Order/Contract/Invoice Notification: 350514197 PO: R401039 Item:	
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status / Work
1	EIVMU ASSEMBLY (A330/RR)	271-200-027-305	1	4435	REPAIRED
12. REMARKS This document has been issued according to an approved computer generated signature procedure. The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under certificate no. VM8Y694J. SN:(4435);MOD Strike:12,17 Applicable Technical Docs: CMM 73-25-37 REV. 7 DATED MAY 26/2020 For work carried out, refer to Service Breakdown Report for Service Order 45413104					
13a. Certifies that the items identified above were manufactured in conformity to ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in Block 12					
13b. Authorised Signature		13c. Approval/Authorisation Number		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part -145 and in respect to that work the items are considered ready for release to service	
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature  VM-CS COA-14 V. De Campos	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in Block 1.		14c. Certificate/Approval Ref No. CH. 145.0251		14d. Name VICTOR DE CAMPOS	
		14e. Date (dd mmm yyyy) 17OCT2022			

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Service Breakdown Report

Sold to
A.J.WALTER AVIATION
The Headquarters
Maydwell Avenue, Slinfold
WEST SUSSEX
RH13 0AS
UNITED KINGDOM

Page 1 of 2
Date 13.10.2022
Service notification 350514197
Meggitt quality notification
Service order/Report No 45413104
Sales order 9953443805
Customer PO# R401039
Customer quality ref
Customer Part#

Equipment serviced here

Item	Part number/ Description	Serial number	Mod Status/Revision
1	271-200-027-305 Engine Interface and Vibration Monitoring Unit (EIVMU) Applicable Technical Docs:	4435	12,17 / - CMM 73-25-37 REV. 7 DATED MAY 26/2020

Failure / complaint (as reported by customer)

For repair - Fault
@@OE-ITB@@

EASA/FAA

Findings

Seal(s) ok and no physical damage has been noticed.
Failure confirmed.
Power up failed at reception.
Unable to download memory.
Defective OBRM 2 detected and will be replaced.
Warranty not applicable (out of warranty period).

Materials

Item	Qty	UOM	Part Number	Batch Number	Description	Cond
1	1	EA	289-103-000-016	S/N 15131	OBRM UNIT ASSEMBLY FOR APM & G PM	

Work performed

Incoming Inspection (Admin)
Preliminary hidden damage inspection
SB/SIL/AD status check performed
Visual Inspection
Confirm Customer complaint - OK
Check connectors condition
Read & Analyze Internal Memory
Incoming ATP Technician
Incoming ATP Test System

Service Breakdown Report

Sold to
A.J.WALTER AVIATION
The Headquarters
Maydwell Avenue, Slinfold
WEST SUSSEX
RH13 0AS
UNITED KINGDOM

Page	2 of 2
Date	13.10.2022
Service notification	350514197
Meggitt quality notification	
Service order/Report No	45413104
Sales order	9953443805
Customer PO#	R401039
Customer quality ref	
Customer Part#	

Continued

Tested & Repaired IAW CMM listed above
OBRM 2 replaced PNR 289-103-000-016 SER 15131
Final ATP Technician
Final ATP Test System
Final FOD check
Administration

VM-P
17

TEST REPORT

Subject: ACCEPTANCE TEST REPORT
Item: Engine Interface and Vibration Monitoring Unit
Type: EIVMU-101
MFR: S3960
PNR: 271-200-027-305
Cust. PNR: 63-9581-24-00
Mod. Record: 12,14
SER: 004435
DMF: 102014
Applicable Doc.: ATP-1046-07 rev-02
Software PNR: 299-500-000-015
Database PNR: 299-506-520-302
AU SER: AH76031
Operator: J.Mettraux
Test Result: PASS
Started: 12 Oct 2022 10:41:34
Finished: 12 Oct 2022 11:19:45
Report generated: 12 Oct 2022 11:19:45
Report Location: \\ngts\atr\atp1046_07r02_eivmu305/P-004435-20221012-111945.html
GTS Hostname: gtsxp0039
Comment:

Signature: _____

Department Approval: _____

Date of Approval: _____



12 OCT. 2022