

1. Approving Civil Aviation Authority/Country: FAA/United States		2.		3. Form Tracking Number: 106102366	
4. Organization Name and Address: Rockwell Collins, Inc. 32125 32ND AVENUE SOUTH FEDERAL WAY, WA 98001-9345 USA		5. Work Order/Contract/Invoice Number: T36336		RE3R812L	
6. Item: 000010	7. Description: HDD-980 / LRM, Mass Memory HDD-980	8. Part Number: 822-1197-101	9. Quantity: 1	10. Serial Number: 7YNN	11. Status/Work: TESTED
12. Remarks: Refer to attached Service Memorandum (referenced in block 3 above) for service details. Tested Per: ATA 45-11-14, CMM 523-0778725, Rev. 00, Dated 28/Aug/1998, Temp. Rev. 05, Dated 24/Jun/2013. Complied with Air Directive: N/A. Service Bulletins Installed: None.		Rockwell Collins certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the [product/article] is considered ready for release to service under EASA Part 145 approval no. EASA.145.4336.			
Item Numbers refer to numbers on Delivery Document					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data as specified in Block 11		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature: 		13c. Approval/Authorization No.:		14c. Approval/Certificate No.: RE3R812L	
13d. Name (Typed or Printed): Richard J Carter		14d. Name (Typed or printed): Richard J Carter		14e. Date (dd/mm/yyyy): 14/JAN/2022	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.					
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					
FAA Form 8130-3 (02-14) NSN: 0052-00-012-9905					

1. 国家 Country P. R. CHINA	2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness 批准放行证书 / 适航批准标签 AUTHORIZED RELEASE CERTIFICATE / AIRWORTHINESS APPROVAL TAG	3. 证书编号 Certificate Ref. No. 106102366
4. 单位 Organization Rockwell Collins, Inc. 32125 32ND AVENUE SOUTH FEDERAL WAY, WASHINGTON 98001-9345 USA	5. 工作单 / 合同单 / 货单 Work Order/Contract/Invoice T36336	
6. 序号 Item 000010	7. 内容 Description HDD-980 / LRM, Mass Memory HDD-980	8. 件号 Part No. 822-1197-101
	9. 通用性 Eligibility*	10. 数量 Qty 1
	11. 系列号 / 批号 Serial/ Batch No. 7YNN	12. 产品状态 Status/Work INSPECTED / TESTED
13. 备注 Remarks Refer to attached Service Memorandum (referenced in block 3 above) for service details. Tested Per: ATA 45-11-14, CMM 523-0778725, Rev. 00, Dated 28/Aug/1998, Temp. Rev. 05, Dated 24/Jun/2013. Complied with Air Directive: N/A. Service Bulletins Installed: None.		
14. 新产品 New Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例进行制造检查, 并且该产品(出口产品)符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured / inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		15. 使用过的产品 Used Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例和进口国通知的特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as otherwise specified in Block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)
16. 批准人签名 Signature 	18. 批准日期 Date 14/JAN/2022	19. 中国民航总局授权 Issued By Or On Behalf Of The CAAC FO0100484
17. 批准人姓名 (打印的) Name (Printed) Richard J Carter		

AAC-038 (12/94)

* 参阅产品目录详细查找适用性

(*) Cross-check eligibility for more details with parts catalogue

Service Memorandum
Page 1 of 2

Service Notification: 106102366		Contract Number : Customer Reject Paper Number : Government Incoming Document Number : Date Equipment Received : 01/11/2022		Repair Station Certificate # : RE3R812L
Customer: AJ WALTER AVIATION LTD				
Customer P.O. Number: T36336				
Outgoing Equipment		Incoming Equipment		Aircraft Information
Equipment Type/Model : HDD-980		HDD-980		Type : Not Available
Part Number : 822-1197-101		822-1197-101		Serial Number:
Serial Number/MCN : 7YNN		7YNN		Tail No : Position :
Description : LRM, Mass Memory H		LRM, Mass Memory H		Removed at Gateway:
Mil Nomenclature :				Date Unit Removed : 01/11/2022
Customer Part Number :				
Customer Serial Number:				
For Questions Regarding This Service Work, Please Contact Customer Service at: Phone : 253-733-3700 Fax : 253-733-3705				
Customer Complaint/Instructions PLEASE TEST AND QUOTE TO REPAIR IF FAILS TEST				
Preliminary Inspection Results: Normal wear and tear.				
Was the Complaint Verified? NO		Were There Any Defects Found? NO		
Description of What Was Wrong with the Equipment: NFF				
Airworthiness Directives No ADs issued against Rockwell to this product.				
Description of Service Work Performed: Final test passed and formatted IAW/ACMM. Note: HDD is blank and ready for service loading.				
Service Bulletins/Mods Installed This Return: None		Outgoing Service Bulletin Configuration: None		

Service Memorandum
Page 2 of 2

Service Notification: 106102366

This Article Has Been Certified Airworthy
On 01/14/2022 By Richard J Carter
FAA Repairman Certificate Number: 3857021

Preliminary Inspection : 01/14/2022 By Barry A Reeves

Service : 01/14/2022 By N / A
Final Test : 01/14/2022 By Barry A Reeves
Tested Per 1 : 523-0778725 REV. 00 TEMP REV. 5

Final Inspection : 01/14/2022 By Richard J Carter

Defective / Failed Parts Replaced

Part Number

Description

Circuit Symbol

Rockwell Collins is in compliance with the FAA Anti-Drug and Alcohol Misuse Prevention Program for personnel engaged in specified aviation activities under FAA Registration Number CONN885A