

1. Approving Competent Authority/Country
CAA / United Kingdom

2.

AUTHORISED RELEASE CERTIFICATE EASA FORM 1

3. Form Tracking Number
ARC10673

4. Organisation Name and Address

Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622
Fax:
Email: sales@oakenhurst.com
Web: www.oakenhurst.com

5. Work Order/Contract/Invoice

WP10949 / R258460



| 6. Item | 7. Description | 8. Part No. | 9. Qty. | 10. Serial No. | 11. Status/Work |
|---------|----------------|-------------|---------|----------------|-----------------|
| 1 | Headset | HME1410KA | 1 | 100 | Repaired |

12. Remarks

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. OSKY452Y.

TCCA Certificate No. 807-10

IN ACCORDANCE WITH MANUFACTURERS MANUAL No: ATA 23-41-20. dated 30th July 1997.

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in condition for safe operation
☐ Non-approved design data specified in block 12

14a. ☒ Part-145, A.50 Release to Service ☒ Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

| | | | |
|---------------------------|------------------------------------|---------------------------|------------------------------------|
| 13b. Authorised Signature | 13c. Approval/Authorisation Number | 14b. Authorised Signature | 14c. Certificate/Approval Ref. No. |
| | | | UK.145.00524 |
| 13d. Name | 13e. Date (dd mmm yyyy) | 14d. Name | 14e. Date (dd mmm yyyy) |
| | | Mr Ian Burton | 10 Apr 2015 |

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622

EASA Part 145: UK.145.00524

FAR 145: O5KY452Y

Workshop Report

No: IR10950

Issue: 01

Date: 12-Mar-15

AJW Aviation
The Headquarters
Maydwell Avenue
Slinfold
West Sussex
RH13 0AS
United Kingdom
Attn: Ms Abigail Fielder
Tel: 0044 (0) 1403 798000
Fax:
E-Mail: payableinvoices@ajw-aviation.com

Your Ref: R258460

Our Ref No: WP10949

Test Required: N/A

Part No: HME1410KA

Description: Headset

TSN: N/A

CSN: N/A

Serial No: 100

Workscope: Avionics Repair

TSO: N/A

CSO: N/A

Removed From:

Serial No:

Reg No:

Position:

Inspection Findings:

Received in average condition with stated defect unconfirmed. Inspection and fault diagnosis checks carried out. Testing found intermittent operation due to broken wire in capsule cable. Inspection showed worn mic side capsule and contaminated earpads. Unit will require replacement parts, cleaning and full final functional testing in accordance with manufacturer's CMM upon release. New ear pads, cable and capsule fitted. Unit reassembled and tested.

Signed:

Name:

Date: 10 APR 2015

For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP