

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number: WO63681	
4. Organization Name and Address: AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: U14791-1	
6. Item Description: 1 VOR-7000 VOR MB NAVIGATION RECEIVER		8. Part Number: 822-0726-120		9. Quantity: 1.00	
				10. Serial/Batch Number: 3001	
				11. Status/Work: REPAIRED	
12. REMARKS Repaired and tested serviceable per CMM 34-55-72 rev 17 dated 06 Feb 2009. For additional information refer to Tear Down Report.					
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Signature:		13c. Approved Organization Number		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12	
13d. Name (Typed or Printed):		13e. Date		14b. Signature <i>Ericson C. Digo</i>	
				14c. Approval Organization Number 33-12	
				14d. Name (Typed or Printed) Ericson Digo	
				14e. Date (dd/mm/yyyy) 13/Apr/2018	
This certificate does not constitute authority to install the part.					
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					



technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO63681

Date Printed: 13/04/2018

Customer RO: U14791-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #:

Code: AJW01

Fax #:

PN: 822-0726-120

Serial # : 3001

Email:

Qty: 1

Descr: VOR-700() VOR MB NAVIGATION RECEIVER

Mfg: ROCKWELL COLLINS

TSN: 0

TSO: 0

TSR: 0

CSN: 0

CSO: 0

CSR: 0

P/N Out: 822-0726-120

Serial # out: 3001

Symptoms:

CODE: MOD/AMENDMENT STATUS AR

DETAILS: AMENDMENT STATUS ON ARRIVAL:1,4,8,1-15,18, B,F

CODE: TEST AND RECERTIFY

DETAILS: TEST & RECERTIFY

Faults:

CODE: FUNCTIONAL TEST

DETAILS: Passed test arrival but found dust inside the unit. Recommend preventive maintenance cleaning and inspection.

CODE: CLEANING

DETAILS: Cleaning is required to remove dust inside the unit which can cause intermittent problems.

CODE: REPAIR

DETAILS: The following tasks will be performed:

- inspection
- disassembly/assembly
- cleaning
- multiple test run
- final test

Corrective Actions:

CODE: REPAIRED

DETAILS: Unit inspected inside/out, cleaned, and ran for several hours. Repaired and tested serviceable per CMM 34-55-72 rev 17 dated 06 Feb 2009.