

1. Approving Competent Authority / Country  
CIVIL AVIATION AUTHORITY  
United Kingdom

2. AUTHORISED RELEASE CERTIFICATE  
**EASA FORM 1**

3. Form Tracking Number  
BA34065992

4. Organisation Name and Address

British Airways Avionics Engineering,  
Ely Meadow, Talbot Green,  
Pontyclun, Cardiff CF72 8XL

5. Work Order/Contract/Invoice

4602582  
R343993

**BRITISH AIRWAYS**

6. Item	7. Description	8. Part number	9. Qty	10. Serial No.	11. Status/Work
1.	SMOKE DETECTOR (VITAL)	2156-204A	1	5069	Repaired

12. REMARKS : Batch No 0006163776

Unit pretested lamp found blown and spare lamp missing - all replaced.  
Unit inspected satis. Unit cleaned satis. Unit final tested to spec IAW  
ATA 26-16-04 rev9, ATP 07546 rev9B - passed  
Unit released under TCCA Approval No. 808-04\*\*

The work identified in Block 11 and described  
herein has been accomplished in accordance with 14  
CFR part 43 and in respect to that work, the items  
are approved for return to service under  
certificate no. BT7Y404J

U738444 20.08.2018 Original  
Manufacturer : AUTRONICS CORPspace(5)

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in condition for safe operation

☐ non-approved design data specified in block 12

14a. ☒ PART-145.A.50 Release to service ☒ Other Regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified  
in block 11 and described in block 12, was accomplished in accordance with  
PART 145 and in respect to that work the items are considered ready for  
release to service.

13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature	14c. Certificate/Approval Ref. no. UK.145.00142
13d. Name	13e. Date(dd/mm/yyyy)	14d. Name U738444 Tony L. Pritchard : BAAE 395 CRS	14e. Date(dd/mm/yyyy) 20.Aug.2018

**USER/INSTALLER RESPONSIBILITIES**

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1,  
it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.  
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification  
issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



British Airways Avionics Eng

Ely Meadow, Talbot Green,  
Pontyclun, Cardiff  
CF72 8XL  
GB

BRITISH AIRWAYS  
ENGINEERING

## Component Strip Report

Customer: AJW AVIATION

The Headquarters, Maydown Avenue  
Slinfold, West Sussex  
RH13 0AS

Part Number: 2156-204A:03972

Serial Number: 5069

Description: SMOKE DETECTOR (VITAL)

Repair Order Number: R343993

Order Number: 4602582

Equipment Number: 42070678

Batch Number: 0006163776

Warranty Requested:

Customer WORK REQUIRED :

Date of Receipt: 11.08.2018

Reason for Removal:

Removal Code: W474 FE

Reason for removal: FWD CARGO DET-FAN 1MSG SHOWS INOP

Date Serviceable: 20.08.2018

Unit pretested lamp found blown and spare lamp missing - all replaced.

Unit inspected satis. Unit cleaned satis. Unit final tested to spec IAW

ATA 26-16-04 rev9, ATP\_07546 rev9B - passed

\*\*Unit released under TCCA Approval No. 808-04\*\*

Warranty Decision:

Tested ☐

Repaired ☒

Overhauled ☐

Inspected ☐

Re-manufactured ☐

New ☐

Modified ☐

Certification Number: BA000034065992