


1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 149360	
4. Organization Name and Address: PHS/MWA Aviation Services 42355 Rio Nedo Rd Temecula, CA 92590 USA Ph: (951) 695-1008, FAA Approval Holder: OMXR603L				5. Work Order/Contract/Invoice Number: G105393/R354461	
6. Item: 1	7. Description: STEAM OVEN	8. Part Number: 8053-03-0000-00	9. Quantity: 1	10. Serial Number: 07-10-0706	11. Status/Work: REPAIRED
12. Remarks: All maintenance performed on WO# G105393 in accordance with CMM 25-36-81, Revision # 2, Revision Date: 9/28/2012 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145, and in respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number; "EASA.145.5102"					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval/Authorization No.:		14c. Approval/Certificate No.:	
				OMXR603L	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy):	
				30/Jul/2019	
14b. Authorized Signature: 					
14d. Name (Typed or Printed): Brian Frick					
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

WORK ORDER



PHS/MWA AVIATION SERVICES

42355 RIO NEDO
TEMECULA, CA 92590

FAA CRS No: OMXR603L
WORK ORDER: G105393

Customer: AJ WALTER AVIATION LTD. RECOVERY PR

Cust Ref #: R354461

Container: NTOC SC2010

Quality Code: 2

Date Rcvd: 2/18/2019

Mfg: SELL

Dept: GALLEY

WR: No WA: No

EASA/FAA: Yes

Part No: 8053-03-0000-00

Desc: STEAM OVEN

S/N: 07-10-0706

Qty: 1

PUBLICATIONS

25-36-81

WORK SCOPE: REPAIRED

Rev No:2

Revision Date:9/28/2012

Preliminary Insp

Unit received dirty with normal wear and tear. Tech to evaluate for damage and/or missing parts.
unit came in a cardboard box, unable to use when shipping unit back; NTOC SC2010

Reason For Removal:

no heat

Pre-Test

Unit failed visual inspection and function test. RFR confirmed

Teardown Findings / Hidden Damage

Unit failed visual inspection for a dirty inner/outer cavity and needs deep cleaning. Failed function test for a tripped
overheat switch on arrival, after reset could not duplicate fail. Door seal is worn


Corrective Action

Removed and replaced damaged, worn and/or required replacement parts.

PART NUMBER	DESCRIPTION	QTY ISSUED
0-112-002000000 SC2010	DOOR SEAL 28 X 19 X 28-5/8 BOX W/CUSTOM FOAM	72 1

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS INSPECTED AND/OR REPAIRED AND/OR OVERHAULED IN ACCORDANCE WITH THE CURRENT
REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE AND IS AIRWORTHY WITH
RESPECT TO THE WORK PERFORMED, OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by: 

Date: 07-30-19