

1. Approving Competent Aviation Authority / Country:
United Kingdom
Civil Aviation Authority

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

3. Form Tracking Number:
L 2175353

4. Organisation Name and Address:



Panasonic Avionics Corporation
Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK

5. Work Order/Contract/Invoice
W21093

Panasonic

| 6. Item | 7. Description | 8. Part No. | 9. Qty. | 10. Serial No. | 11. Status / Work |
|---|------------------|--------------|---------|----------------|-------------------|
| 1 | MAIN MULTIPLEXER | RD-AX1302-01 | 1 | 9000003 | REPAIRED |
| 12. Remarks LRU CONFORMED IAW CMM 23-34-58 REV 15 DTD JAN 2009. | | | | | |

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X.
Panasonic Avionics Corporation Internal reference SR 3499026

| | | |
|---|-------------------------------------|---|
| 13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in a condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 12. | | 14a. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service. |
| 13b. Authorised Signature: | 13c. Approval/Authorisation Number: | 14b. Authorised Signature:  |
| 13d. Name | 13e. Date (dd mmm yyyy) | 14d. Name Sham Harrar  |
| | | 14c. Certificate/Approval reference No: UK.145.00297 |
| | | 14e. Date (dd mmm yyyy) 18-FEB-2014 |

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

SOLD TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SINFOLD
WEST SUSSEX, ENGLAND RH13 0AS, GB

SHIP TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SINFOLD
WEST SUSSEX, ENGLAND RH13 0AS, GB

PAGE 1 of 1

SHIP TRANSACTION:



| | | | | | | |
|---------------------------------------|---|---|--------------------------------------|------------------------------------|-------------------------------------|-------------------------------------|
| CUSTOMER P.O. NUMBER W21093 | | CUSTOMER 1001 | TAIL NO. D-AGEL | CUST PROD REF 6084979 | SERVICE REQUEST 3499026 | |
| PART NUMBER RD-AX1302-01 | | NOMENCLATURE MAIN MULTIPLEXER | | | DATE REMOVED | DATE RECEIVED 29-JAN-2014 |
| SERIAL NUMBER 900003 | | DATE OF MFG 31-OCT-1997 | WTY START DATE 31-OCT-1997 | WTY END DATE 30-JAN-2001 | DATE REPAIRED 17-FEB-2014 | SHIP DATE |
| MOD IN 2 | | | | | | |
| REASON FOR CUSTOMER REJECTION | RFR - BITE MALFUNCTION, NOT POSSIBLE TO CONFIG ZONE 1. PREVIOUS REPAIR 178007 | | | | | |
| INTERNAL INSPECTION | No Physical Damage | | | | | |
| EXTERNAL INSPECTION | No Physical Damage - MINOR MARKS ON TOPCOVER. NO ACTION TAKEN. | | | | | |
| ACTUAL FAILURE / CORRECTIVE ACTION | UNIT TESTED AND FAILED ON BITE TEST. A1 CENTRAL PROCESSOR CARD DEFECTIVE. REPLACED A1 CENTRAL PROCESSOR CARD. UNIT CLEANED - RE- TESTED AND PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-34-58 REV 15 DTD JAN 2009. | | | | | |

MOD OUT: 2

| INSPECTED BY: Sham Harrar | | REPAIRED BY: AHMED, NASAR | | | | |
|----------------------------|--|---------------------------|------------|----------------|----------------|-----|
| PART NUMBER | DESCRIPTION | QTY | UNIT PRICE | EXTENDED PRICE | CHARGED AMOUNT | WTY |
| CUST LABOR R8U1AX1302XA | OUT OF WARRANTY CHARGE SUB ASSEMBLY PWB | | | | | |

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

| |
|------------------|
| Cost of Labor |
| Cost of Material |
| Total Cost |

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged