

1. Approving Civil Aviation
Authority/Country:

2.

FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number.

136422-1

4. Organization Name and Address.

SOUTHERN AEROPARTS
4157 SOUTHWEST BLVD
TULSA, OK. 74107
US

5. Work Order, Contract or Invoice Number.

Work Order No.: **SHY105727**

Customer RO.: **W49317**

Repair Station No.:

QAKR523K

6. Item

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1 ACTUATOR ASSY-MAIN GEAR

65-44910-27

1.00

TSC2304

REPAIRED

12. REMARKS

IN ACCORDANCE WITH
CMM: 32-30-11 REV: 65 DATE: 01-NOV-2020

NO APPLICABLE AND/OR ADDITIONAL A/D'S OR S/B'S NOTED ON THIS UNIT AT THIS TIME.

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number 145.5539

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No:

14b. Authorized Signature:

14c. Approval/Certificate No:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

SAMANTHA TALLY


09/Nov/2021

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Southern Aeroparts
4157 Southwest Blvd
Tulsa, OK. 74107
US

Tear Down/Inspection

Work Order #: SHY105727

Date Printed: 09-Nov-21

Page: 1 of 1

To:

AJ WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
WEST SUSSEX RH13 0AS
UNITED KINGDOM

Ship To:

AJ WALTER AVIATION LTD
LEUVENSESTEENWEG 573
SUITE 9A
ZAVENTEM, 1930, BELGIUM

Cust.PO Ref.: W49317

Cust.Phone: 44 1 40 371 1777

Cust.Email:

Cust.Code: 310220

Cust.Fax: 1-441403710936

Station: SAI

IN. PN: 65-44910-27

Descr: ACTUATOR ASSY-MAIN GEAR

Qty: 1

OUT PN: 65-44910-27

Serial Numbers: TSC2304

Symptoms:

See PO

ORIGINAL 8130 AND TEARDOWN REPORT IS INCLUDED IN THE REPAIR ORDER

Faults:

*****WARRANTY*****

WARRANTY REQUEST: Yes

REASON FOR WARRANTY RETURN: Damaged in transit.

PREVIOUS WORK ORDER NUMBER: SHY104687

PREVIOUS WORK SCOPE: Repair

*****SHOP REPORT*****

TECHNICIAN / NUMBER / DATE: J McGrail 109953 8-17-21

P/N & SN ON DATA PLATE MATCHES PO/RO/WO: yes

TEARDOWN FINDINGS: Received with sealant torn and swivel assy fitting broken off.

NOTES:

RECOMMENDED WORK SCOPE: "REPAIR"

Warranty denied; not due to previous workmanship

Corrective Actions:

Replaced swivel assy fitting. "REPAIRED" J McGrail 11-9-21

CMM: 32-30-11 Rev: 65 Date: 01-Nov-2020