17. Name	15. Authoris	approv	14. Certifie	EQUI	13. REMARKS IF TWO I PER ORD MENTIO					1,0	6. ITEM	B/E	4. ORGANISATION	CAA Th	1. Approvi
	Authorised Signature	approved design data and are in condition for s non-approved design data specified in block 13	s that the items identifi	STHESE PARTS ARE	HEMARKS IF TWO PARTINUMBERS PER ORDERLINE ARE MENTIONED IN BLOCK					DF1075 High speed oven LH	7. DESCRIPTION	AEROSP,	JISATION	CAA The Netherlands	1. Approving Competent Authority / Country
18. Date (D/M/Y)	16. Approval / Authorisation Number	approved design data and are in condition for safe operation non-approved design data specified in block 13	Certifies that the items identified above were manufactured in conformity to:	Royal Inventum certifies that all work specified in block 12/13 was carried out in accordance with FAR Part 145 and component in considered ready for release to service under FAA Asceptance Certificate Number: ZRYY936X	Repaired in accordance with CMM: 25-35-11 Controller with F/M: 611933 and 8/M: 2319 Shop finding report ref.:37113825 Reprinted: SB-1000-25-0001; SB-25-1107					ed oven LH		B/E AEROSPACE / INVENTUM		АИТНО	i>
	nber NL.21G.2150			vork specified in block 12/13 wa x release to service under FAA /	#: 25-35-11 Revision: 05 B/N: 2319 SB-25-1107					720737-50-43-00	8. PART NO.	Galvanibaan 5 3439 MG NIEUWEGEIN THE NETHERLANDS	KONINKLIJKE FABRIEK INVENTUM B.V.	AUTHORISED RELEASE CERTIFICATE / EASA FORM	
22. Name	20. Autho	Certifies block 1: sidered	19. 🖈	as carried Asceptan		 K. " - "	Jacobs	-# . *				INVENT ING BAN TRADE	TEL.: +3	EASA FOR	
HUYSOBUMANTORIAL	20. Authorised Signature INV	ifies that unless otherwise speci k 13 was accomplished in accor red ready for release to service.	PART-145.50 Release to Service	out in accordance wi						UNKNOWN	9. ELIGIBILITY (*)	CABLE ADDRESS: INVENTUM NIEUWEGEIN ING BANK UTRECHT NO. 68 75 43 541 TRADE REGISTER UTRECHT NO. 1132	TEL.: +31 (0)30 6029200/TELEFAX: +31 (0)30 6036949	3M 1	
		se specified in accordance service.	Service	th FAR P							10. QTY). 1132	X: +31 (0)30		
23. Date (D/M/Y) 11-03-2009	21. Certificate / Approval Ref. No.	Certifies that unless otherwise specified in block 13 the work identified in block 12 and described in block 13 was accomplished in accordance with PART145 and in respect to that work the items are considered ready for release to service.	Other regulation specified in block 13	art 145 and : 736X						1021	11. SERIAL/BATCH NO.		6036949		
	NL.14	block 12 and de	ied in block 13						Modified Repaired	Manufactured	12. STATUS/WORK	37113825 61135668	5. WORK ORL	37113825-01	3. FORM TRA
	NL.145.1150	scribed in tems are con-							 RBI		NORK	SR.	5. WORK ORDER/CONTRACT	01	3. FORM TRACKING NUMBER



Commercial Aircraft Products Group, Royal Inventum Facility Galvanibaan 5 3439 MG Nieuwegein The Netherlands Tel. +31(0)30 6029200 Fax +31(0)30 6036949

SHOPFINDING REPORT

Order details

0	61135668	Purchase order:	3582358	Work order:
Receiving date	SR TECHNICS UK LIMITED	Customer:	37113825	Repair order:

12-02-2009

Repair details				
Complaint: :Door lock broken		Failure reason:	Verify: No	No
PARTNUMBER P/N in: 720737-50-43-00	SERIALNUMBER S/N in: 1021	Man. Date: 21-12-2004 Warranty: No	RESISTANCE TEST	0
P/N out: 720737-50-43-00	• •	CMM: 25-35-11 SUPS: No	Phase B: -	() ()
		Revision: 05	Phase C: -	b
	S/N in: 2319	Software Setting: CS-820-43		;
Sub P/N out: 611933	S/N out: 2319			
		Mod. out: -		

Shop findings	
PARTNUMBER	(DESCRIPTION, DISCREPANCY, REASON - PERFORMED)
98000001	Order/environmental costs
239712	Component A
239713	Component B
239542	Door seal Broken due to wear and tear Replaced
430007039	Baffle plate Burnt due to a defective part Replaced
439001137	Modification kit DF1000/1075 Required due to a defective part Implemented
611438	
612744	Door assy DF1000 LH Is painted due to thick painting Replaced
Remarks:	

Modifications

PR-262-DOC-001	Form:
Repair station	Department
+31.(0).30.6029.280	Phone #
PR-262-DOC-001 Repair station +31.(0).30.6029.280 Repair_Nieuwegein@beaerospace.com	Email:
Name: At A H DE APPLICATION INVENTUM Signature: 41 A 1010 Q.C.DEPT.	Approved by
1 of 2	Page



Commercial Aircraft
Products Group,
Royal Inventum Facility
Galvanibaan 5
3439 MG Nieuwegein
The Netherlands
Tel. +31(0)30 6029200
Fax +31(0)30 6036949

SHOPFINDING REPORT

SB-25-1107 SB_1000-25-0001 SB_1000-25-0001

Additional instructions for the 3-Phase Safety Device - Implemented Implementation of improved power module/motor fan - Modified IMPLEMENTATION OF IMPROVED POWER MODULE / MOTOR / FAN - Modified

	PR-262-DOC-001		Form:
	Repair station		Department
	+31.(0).30.6029.280		Phone #
	PR-262-DOC-001 Repair station +31.(0).30.6029.280 Repair_Nieuwegein@beaerospace.com		Email:
REPAIR DEPART MIDGORY.	Name: 05 MRT 2009 Q.C.Dept:: Name: 05 MRT 2009 Q.C.Dept:: Name: 05 MRT 2009 Q.C.Dept:: Name: 05 MRT 2009 Q.C.Dept::	Approved by	A serviced by
	2 of 2	Fage	